

## Exhibit 3

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
290413	Alameda Point Gym & Multi-Purpose Field	Sidewalk	Amenity Not Evaluated	0	The building amenity is evaluated under its separate building components.	\$0
290417	Alameda Point Gym & Multi-Purpose Field	Gymnasium	Interior Access Route	1	The interior accessible route has non-compliant slopes.	\$2,899
290418	Alameda Point Gym & Multi-Purpose Field	Gym	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$1,456
290422	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 2	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
290426	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 3	Building Entrance - Door	1	The threshold at the accessible door is raised; however the ends are not beveled.	\$179
290427	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 3	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
290428	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 3	Building Entrance-Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
290429	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 2	Building Entrance-Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
290431	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 5	Building Entrance - Door	1	The threshold at the accessible door is raised; however the ends are not beveled.	\$179
290432	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 5	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
290433	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 5	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
290434	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 5	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$0
290435	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 5	Building Entrance-Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
290436	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 4	Building Entrance - Door	1	The threshold at the accessible door is raised; however the ends are not beveled.	\$179
290437	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 4	Building Entrance-Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
290408	Alameda Point Gym & Multi-Purpose Field	Parking Lot	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	\$3,000
290409	Alameda Point Gym & Multi-Purpose Field	Stair (ST-2)	Stairs	1	Treads have slopes greater than 1:48.	\$1,913
290447	Alameda Point Gym & Multi-Purpose Field	Ramp (R-1)	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$7,944
290448	Alameda Point Gym & Multi-Purpose Field	Ramp (R-1)	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$198
290449	Alameda Point Gym & Multi-Purpose Field	Ramp (R-1)	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	\$3,260
290450	Alameda Point Gym & Multi-Purpose Field	Ramp (R-2)	Ramp	1	Handrails are not provided where the ramp rises more than 6" or are not compliant.	\$3,260
290451	Alameda Point Gym & Multi-Purpose Field	Ramp (R-2)	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$198
290452	Alameda Point Gym & Multi-Purpose Field	Ramp (R-2)	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$6,620
290454	Alameda Point Gym & Multi-Purpose Field	Stair (ST-1)	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$1,051
290455	Alameda Point Gym & Multi-Purpose Field	Stair (ST-1)	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$1,304
290456	Alameda Point Gym & Multi-Purpose Field	Stair (ST-1)	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	\$15,300
290457	Alameda Point Gym & Multi-Purpose Field	Multi purpose field - 1st Base Dugout	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$1,792
290458	Alameda Point Gym & Multi-Purpose Field	Multi purpose field - 3rd Base Dugout	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$1,792
290414	Alameda Point Gym & Multi-Purpose Field	Main Entrance	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
290415	Alameda Point Gym & Multi-Purpose Field	Main Entrance (Lobby)	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
290416	Alameda Point Gym & Multi-Purpose Field	Main Entrance (Lobby)	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$1,805
290419	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 1	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
290420	Alameda Point Gym & Multi-Purpose Field	Gym	Alarm	2	A visual alarm is not provided where an audible alarm is present (excluding closets).	\$500
290423	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 2	Signage	2	Means of egress signage does not have tactile lettering.	\$55
290424	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 1	Building Entrance - Door	2	CALIFORNIA: The accessible entrance does not have signage with the International Symbol of Accessibility, in the existing building where not all entrances are accessible.	\$55
290425	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 3	Building Entrance - Door	2	CALIFORNIA: The accessible entrance does not have signage with the International Symbol of Accessibility, in the existing building where not all entrances are accessible.	\$55
290430	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 5	Signage	2	Means of egress signage does not have tactile lettering.	\$55
290438	Alameda Point Gym & Multi-Purpose Field	Entrance / Exit 4	Signage	2	Means of egress signage does not have tactile lettering.	\$55
295406	Alameda Point Gym & Multi-Purpose Field	Multi purpose field	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$320
294684	Alameda Point Gym & Multi-Purpose Field	Gym	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$5,439
290410	Alameda Point Gym & Multi-Purpose Field	Restroom RR-2	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
290411	Alameda Point Gym & Multi-Purpose Field	Restroom RR-2	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
290439	Alameda Point Gym & Multi-Purpose Field	Restroom (RR-5)	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
290440	Alameda Point Gym & Multi-Purpose Field	Restroom (RR-5)	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
290442	Alameda Point Gym & Multi-Purpose Field	Restroom (RR-7)	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
290443	Alameda Point Gym & Multi-Purpose Field	Restroom (RR-7)	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
290444	Alameda Point Gym & Multi-Purpose Field	Restroom (RR-3)	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
290445	Alameda Point Gym & Multi-Purpose Field	Restroom (RR-3)	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
290446	Alameda Point Gym & Multi-Purpose Field	Gym	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	\$980
290459	Alameda Point Neighborhood Park	Accessible Route (North of Playground)	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$1,250
290460	Alameda Point Neighborhood Park	Accessible Route (North of Playground)	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$1,250
290461	Alameda Point Neighborhood Park	Exercise Equipment	Exercise Equipment	1	Clear floor space is not provided at the transfer point to the exercise equipment.	\$1,250
290463	Alameda Point Neighborhood Park	Restroom RR-1	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
290464	Alameda Point Neighborhood Park	Restroom RR-2	Restroom/Bathroom-Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
290465	Alameda Point Neighborhood Park	Restroom RR-2	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294118	Bay Farm Library	Curb Ramp (CR-1)	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
294121	Bay Farm Library	Accessible Parking Aisle at P1-A	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294122	Bay Farm Library	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
294123	Bay Farm Library	Accessible Parking Aisle at P1-A	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
294124	Bay Farm Library	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294125	Bay Farm Library	Rear of building	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$11,892
294126	Bay Farm Library	Curb Ramp (CR-1)	Curb Ramp	1	The curb ramp has openings in the ground surface greater than 1/2" wide.	\$198
294127	Bay Farm Library	Walkway to Main Entrance (E-1)	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,955
294128	Bay Farm Library	Ramp (R-1)	Ramp	1	The ramp does not have a level landing at the top and/or bottom of each run.	\$5,584
294130	Bay Farm Library	Ramp (R-1)	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$13,240
294132	Bay Farm Library	Entrance (E-1)	Building Entrance-Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
294133	Bay Farm Library	Entrance (E-1)	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750
294135	Bay Farm Library	Entrance (E-1)	Door	1	CALIFORNIA: The power operated door is not compliant.	\$5,200
294152	Bay Farm Library	Entrance (E-2)	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294155	Bay Farm Library	Rear of building	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$19,820
294156	Bay Farm Library	Rear of building	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	\$8,960
294148	Bay Farm Library	Bookshelf Aisles	Interior Access Route	1	A compliant turning space is not provided at the change of direction.	\$20
294149	Bay Farm Library	Bookshelf Aisles	Interior Access Route	1	CALIFORNIA: The width of the aisle is not compliant.	\$1,000
294134	Bay Farm Library	Entrance (E-1)	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$2,600

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294136	Bay Farm Library	Entrance (E-1) Book Drop	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	\$500
294147	Bay Farm Library	Entrance (E-2)	Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$2,600
294151	Bay Farm Library	Entrance (E-2)	Signage	2	Means of egress signage does not have tactile lettering.	\$55
294153	Bay Farm Library	Entrance (E-1)	Signage	2	Means of egress signage does not have tactile lettering.	\$55
294150	Bay Farm Library	Computer receptacles	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$500
294138	Bay Farm Library	Restroom RR-1	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required clear floor space of minimum 30" by minimum 48".	\$3,000
294139	Bay Farm Library	Restroom RR-1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294140	Bay Farm Library	Restroom RR-1	Restroom/Bathroom-Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	\$1,100
294141	Bay Farm Library	Restroom RR-2	Restroom/Bathroom-Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	\$1,100
294142	Bay Farm Library	Restroom RR-2	Restroom/Bathroom - Toilet Stall	3	The side grab bar is not compliant in the wheelchair stall.	\$355
294143	Bay Farm Library	Restroom RR-2	Restroom/Bathroom - Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	\$355
294144	Bay Farm Library	Restroom RR-2	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required clear floor space of minimum 30" by minimum 48".	\$3,000
294145	Bay Farm Library	Restroom RR-2	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294158	Bay Farm Library	Drinking Fountain	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
294119	Bay Farm Library	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294157	Bay Farm Library	Drinking Fountain	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$2,841
294120	Bay Farm Library	Accessible Parking Space P1-A	Parking Space - Van	5	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
294129	Bay Farm Library	Ramp (R-1)	Ramp	5	CALIFORNIA: The exterior ramp railings are not compliant.	\$4,890
291164	Bayport Park	Entrance (E-1)	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
291171	Bayport Park	Entrance (E-2)	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$0
291174	Bayport Park	Entrance (E-2)	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
291175	Bayport Park	Entrance (E-1)	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
291173	Bayport Park	Accessible route to Entrance (E-2)	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$198
291188	Bayport Park	Softball Field 2	Exterior Accessible Route	1	CALIFORNIA: An accessible route is not provided to each functional area in the restaurant, cafeteria, banquet facility, bar or similar facility, including sunken, raised and outdoor areas.	\$3,584
291162	Bayport Park	Softball Field 1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$7,168
291163	Bayport Park	Ramp R-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$991
291176	Bayport Park	Curb Ramp (CR-1)	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	\$672
291177	Bayport Park	Van Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
291178	Bayport Park	Van Accessible Parking Aisle P1-A	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
291179	Bayport Park	Standard Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291180	Bayport Park	Rec Center Circulation Path	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
291181	Bayport Park	Van Accessible Parking Space P1-C	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
291182	Bayport Park	Van Accessible Parking Aisle P1-C	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
291183	Bayport Park	Van Accessible Parking Aisle P1-C	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
291184	Bayport Park	Standard Accessible Parking Space P1-D	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
291185	Bayport Park	Curb Ramp (CR-2)	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
291172	Bayport Park	Entrance (E-1)	Signage	2	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	\$55
291165	Bayport Park	Restroom (RR-1)	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
291166	Bayport Park	Restroom (RR-1)	Restroom/Bathroom - Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	\$355
291167	Bayport Park	Restroom (RR-2)	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
291168	Bayport Park	Restroom (RR-2)	Restroom/Bathroom - Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	\$355
291169	Bayport Park	Restroom (RR-2)	Restroom/Bathroom-Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
291170	Bayport Park	Restroom (RR-1)	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
291186	Bayport Park	Restroom (RR-3)	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
291187	Bayport Park	Restroom (RR-4)	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291189	Bayport Park	Entrance to Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
291191	Bill Osborne Model Airplane Field	Landing Areas & Amenities	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$22,400
291192	Bill Osborne Model Airplane Field	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
291193	Bill Osborne Model Airplane Field	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
291194	Bill Osborne Model Airplane Field	Accessible Parking Aisle at P1-A	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
291196	Bill Osborne Model Airplane Field	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
291198	Bill Osborne Model Airplane Field	Perimeter path	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$6,000
291200	Bill Osborne Model Airplane Field	Barbecue Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$3,136
291201	Bill Osborne Model Airplane Field	Large Landing Area - Picnic Shelter	Picnic Table	2	The picnic table surface height exceeds 34" or is lower than 28" above grade.	\$1,300
291202	Bill Osborne Model Airplane Field	Large Landing Area - Picnic Shelter	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
291205	Bill Osborne Model Airplane Field	Small Landing Area - Picnic Shelter	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
291197	Bill Osborne Model Airplane Field	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
299344	Bill Osborne Model Airplane Field	Accessible Parking Aisle at P1-A	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$672

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
430978	Bohol Circle Immigrant Park	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$44
430980	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$25
430981	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$25
430982	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$14,868
430983	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$99
430984	Bohol Circle Immigrant Park	Exercise Area 1	Exercise Equipment	1	Clear floor space is not provided at the transfer point to the exercise equipment.	\$1,239
430985	Bohol Circle Immigrant Park	Exercise Area 1	Exercise Equipment	1	Clear floor space is not provided at the transfer point to the exercise equipment.	\$297
430986	Bohol Circle Immigrant Park	Exercise Area 1	Exercise Equipment	1	Clear floor space is not provided at the transfer point to the exercise equipment.	\$117
430987	Bohol Circle Immigrant Park	Exercise Area 1	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
430988	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$620
430989	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
430990	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$620
430991	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
430993	Bohol Circle Immigrant Park	Walkway along Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$620

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
437469	Bohol Circle Immigrant Park	Ramps to Park	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	\$32,600
437185	Bohol Circle Immigrant Park	Playground	Transfer System	2	A transfer space is not provided at the platform.	\$6,250
431478	Bohol Circle Immigrant Park	Playground	Transfer System	3	CALIFORNIA - The transfer steps do not have contrasting stripes.	\$396
430967	Bohol Circle Immigrant Park	Unisex Restroom RR-1	Building Entrance-Door	3	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$458
430968	Bohol Circle Immigrant Park	Unisex Restroom RR-1	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
430970	Bohol Circle Immigrant Park	Unisex Restroom RR-2	Building Entrance-Door	3	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$458
430971	Bohol Circle Immigrant Park	Unisex Restroom RR-2	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
430974	Bohol Circle Immigrant Park	Unisex Restroom RR-3	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
430966	Bohol Circle Immigrant Park	Picnic Area serving Playground	Accessible Route	4	CALIFORNIA: The existing accessible feature is not in operable working condition.	\$0
430992	Bohol Circle Immigrant Park	Viewing Area	Controls And Dispensers	4	Controls and/or dispensers are not within an allowable reach range.	\$1,373
291006	Chochenyo Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$70,000
291007	Chochenyo Park	Walkway through Park	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$0
291008	Chochenyo Park	Walkway to Gazebo	Ramp	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$400
291013	Chochenyo Park	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
291014	Chochenyo Park	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	\$840

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291015	Chochenyo Park	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
291016	Chochenyo Park	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
291017	Chochenyo Park	Curb Ramp CR-1	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289
291018	Chochenyo Park	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
291020	Chochenyo Park	Curb Ramp CR-2	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289
291021	Chochenyo Park	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
291022	Chochenyo Park	Accessible Parking Space P-1B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
291023	Chochenyo Park	Accessible Parking Space P-1B	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
291025	Chochenyo Park	Accessible Parking Space P-1B	Parking Space - Car	1	CALIFORNIA: A car accessible stall and adjacent aisle are not provided.	\$840
297595	Chochenyo Park	North of Gazebo	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,075
291010	Chochenyo Park	Drinking Fountain DF-1 at Gazebo	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not automatically activated or the location of the manual activation is neither the front or side 6" maximum from the front.	\$8,000
291011	Chochenyo Park	North of Gazebo	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
291012	Chochenyo Park	North of Gazebo	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
291009	Chochenyo Park	Drinking Fountain DF-1 at Gazebo	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$238
296320	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$7,968
296321	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,288
296322	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,013

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296323	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,894
296324	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$5,708
296325	City Hall	ST-3	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$845
296326	City Hall	ST-3	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$3,912
296327	City Hall	ST-3	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$106
296328	City Hall	1st Floor	Door	1	CA The door lacks a level landing	\$1,178
296330	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,618
296331	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,031
296332	City Hall	ST-4	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$70
296333	City Hall	ST-5	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$1,971
296335	City Hall	ST-5	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$163
296286	City Hall	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,449
296288	City Hall	1st Floor	Floor Surface	1	The edges of the carpet are not securely attached.	\$36
296290	City Hall	1st Floor	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
296300	City Hall	1st Floor	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$18

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296302	City Hall	1st Floor	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296304	City Hall	1st Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296305	City Hall	1st Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296306	City Hall	1st Floor	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296308	City Hall	1st Floor	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	\$2,600
296310	City Hall	1st Floor	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296315	City Hall	ST-2	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$1,971
296316	City Hall	ST-2	Stairs	1	Treads have slopes greater than 1:48.	\$30,983
296318	City Hall	Elevator	Elevator	1	The clearance between the car platform sill and the edge of the hoistway landing is greater than 1-1/4".	\$506
296319	City Hall	Elevator	Elevator	1	The elevator car does not meet the minimum dimensions.	\$80,000
296162	City Hall	3rd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$732
296164	City Hall	3rd Floor	Door	1	CALIFORNIA: The power operated door is not compliant.	\$2,600
296165	City Hall	R-1 3rd Floor	Ramp	1	The ramp running slope is greater than 1:12 (8.33%) and the cross slope is greater than 1:48 (2.08%).	\$7,944
296166	City Hall	3rd Floor	Ramp	1	The clear width of the ramp is less than 36".	\$7,944
296167	City Hall	3rd Floor	Ramp	1	The ramp run rises 6" or greater but has no handrails.	\$2,880
296168	City Hall	3rd Floor	Ramp	1	Handrails do not extend 12" horizontally beyond the top and bottom of ramp runs above the landing surface.	\$350
296171	City Hall	3rd Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296172	City Hall	3rd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296173	City Hall	3rd Floor	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$1,250
296175	City Hall	3rd Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296176	City Hall	3rd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296177	City Hall	3rd Floor	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$1,250
296178	City Hall	3rd Floor ST-1	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$70
296179	City Hall	3rd Floor ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$652
296182	City Hall	3rd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296183	City Hall	3rd Floor	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296184	City Hall	3rd Floor	Door	1	CA The door lacks a level landing	\$1,178
296186	City Hall	3rd Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296187	City Hall	3rd Floor	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296188	City Hall	3rd Floor Men's Restroom	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296189	City Hall	3rd Floor	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$100
296190	City Hall	3rd Floor	Door	1	CALIFORNIA: The power operated door is not compliant.	\$2,600
296193	City Hall	3rd Floor	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
296194	City Hall	3rd Floor Women's Restroom	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296195	City Hall	3rd Floor Women's Restroom	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296196	City Hall	3rd Floor Women's Restroom	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296197	City Hall	3rd Floor Women's Restroom	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296207	City Hall	3rd Floor	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$1,250
296208	City Hall	3rd Floor	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296210	City Hall	3rd Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296211	City Hall	3rd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296212	City Hall	3rd Floor	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
296244	City Hall	2nd Floor	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296246	City Hall	2nd Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296247	City Hall	2nd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296250	City Hall	2nd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$732
296253	City Hall	2nd Floor	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296254	City Hall	2nd Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296255	City Hall	2nd Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
296257	City Hall	2nd Floor	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296258	City Hall	2nd Floor	Building Entrance - Door	1	The entry door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
296259	City Hall	2nd Floor	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
296260	City Hall	2nd Floor	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296261	City Hall	2nd Floor	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$18
296334	City Hall	ST-5	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$815
296289	City Hall	1st Floor	Building Entrance - Door	2	The bottom of the entry door vision light is higher than 43".	\$2,600
296303	City Hall	1st Floor	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
296314	City Hall	ST-2	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$1,141
296317	City Hall	Elevator	Elevator	2	CALIFORNIA: The hall call buttons are not compliant.	\$13,500
296144	City Hall	1st Floor	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$200
296163	City Hall	3rd Floor	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$5,200
296169	City Hall	3rd Floor	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
296174	City Hall	3rd Floor	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
296180	City Hall	3rd Floor ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$326
296185	City Hall	3rd Floor	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
296191	City Hall	City Clerk	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	\$2,105
296192	City Hall	City Clerk	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	\$2,105
296206	City Hall	3rd Floor	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
296209	City Hall	3rd Floor	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296220	City Hall	2nd Floor Men's Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$200
296245	City Hall	2nd Floor	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
296249	City Hall	2nd Floor	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
296252	City Hall	2nd Floor	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$93
296256	City Hall	2nd Floor	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
296262	City Hall	2nd Floor	Vending Machine	2	The vending machines have operable parts which are not within reach range.	\$3,254
296270	City Hall	1st Floor Men's Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$200
296283	City Hall	1st Floor Women's Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$200
296287	City Hall	1st Floor	Signage	3	Means of egress signage is not provided.	\$55
296291	City Hall	1st Floor	Signage	3	Means of egress signage is not provided.	\$55
296301	City Hall	1st Floor	Signage	3	Means of egress signage is not provided.	\$55
296307	City Hall	1st Floor	Signage	3	Means of egress signage is not provided.	\$55
296311	City Hall	1st Floor	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
296145	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
296146	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Water Closet	3	The toilet paper dispenser is not at a compliant location.	\$280
296147	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
296148	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296149	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
296150	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296151	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
296152	City Hall	3rd Floor Men's Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
296153	City Hall	3rd Floor	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
296154	City Hall	3rd Floor	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$5,439
296161	City Hall	3rd Floor	Signage	3	Means of egress signage is not provided.	\$55
296181	City Hall	3rd Floor	Signage	3	Means of egress signage is not provided.	\$55
296198	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
296199	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
296200	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
296201	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	The toilet paper dispenser is not at a compliant location.	\$280
296202	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
296203	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
296204	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296205	City Hall	3rd Floor Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
296213	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
296214	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
296215	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
296216	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
296217	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
296218	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
296219	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296221	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296222	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
296223	City Hall	2nd Floor Men's Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
296224	City Hall	2nd Floor	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
296232	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
296233	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
296234	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296235	City Hall	2nd Floor Women's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
296236	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
296237	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
296238	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
296239	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
296240	City Hall	2nd Floor Women's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$93
296241	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296242	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296243	City Hall	2nd Floor Women's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
296251	City Hall	2nd Floor	Signage	3	Means of egress signage is not provided.	\$55
296263	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
296264	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
296265	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
296266	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
296267	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296268	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
296269	City Hall	1st Floor Men's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
296271	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296272	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296273	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
296274	City Hall	1st Floor Men's Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
296275	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
296276	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
296277	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296278	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
296279	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
296280	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
296281	City Hall	1st Floor Women's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
296282	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
296284	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296285	City Hall	1st Floor Women's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
296329	City Hall	Sidewalk	Signage	4	Directional signage indicating the accessible route from accessible parking to the facility is not provided, where existing routes are both accessible and non-accessible.	\$280
296292	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296293	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296294	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296295	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296296	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296297	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296298	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296299	City Hall	1st Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296312	City Hall	1st Floor	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	\$400
296313	City Hall	1st Floor	Telephone	4	Clear floor space is not provided at the accessible public telephone	\$100
296155	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296156	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296157	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296158	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296159	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296160	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296170	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296225	City Hall	2nd Floor	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	\$980
296226	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296227	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296228	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296229	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296230	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296231	City Hall	3rd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296248	City Hall	2nd Floor	Signage	4	Compliant interior signage indicating a space or facility is not provided.	\$55
296309	City Hall	CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289
300247	City Hall West	Rooms on 2nd Floor	Amenity Not Evaluated	0	The amenity cannot be accessed and, therefore, cannot be evaluated.	\$0
291534	City Hall West	Stairs ST-2	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$1,267
291537	City Hall West	Stairs ST-2	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$6,520
291538	City Hall West	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	#####
291539	City Hall West	Stairs ST-3	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$8,150
291540	City Hall West	Stairs ST-3	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$634
291541	City Hall West	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,000
291543	City Hall West	Stairs ST-4	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$528
291546	City Hall West	Stairs ST-5	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$528
291547	City Hall West	Stairs ST-5	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	\$19,125
291548	City Hall West	Ramp R-1	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$50
291549	City Hall West	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,972
291550	City Hall West	Accessible Parking Spaces P-1A and P-1B	Parking Spaces-General	1	The minimum number of accessible parking spaces is not provided.	\$840
291551	City Hall West	Ramp R-1	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$19,860

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291552	City Hall West	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,310
291553	City Hall West	Accessible Entrance at R-1	Building Entrance - Door	1	Accessible entries are not identified with the International Symbol of Accessibility, where not all entrances are accessible.	\$120
291598	City Hall West	Stairs ST-6	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$352
291599	City Hall West	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$634
299566	City Hall West	Accessible Entrance at R-1	Building Entrance-Floor Surface	1	The edges of the carpet are not securely attached.	\$432
299567	City Hall West	Main Stairs Front	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$141
291555	City Hall West	Rear Stairs	Stairs	1	CALIFORNIA: Treads, including top and bottom treads, of the interior stair flight do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$141
291556	City Hall West	Rear Stairs	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$16,300
291557	City Hall West	Rear Stairs	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	\$38,250
291558	City Hall West	Main Stairs Front	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	\$38,250
291559	City Hall West	Main Stairs Front	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$16,300
291561	City Hall West	Public Works Entry	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
291562	City Hall West	Public Works Entry	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
291567	City Hall West	Elevator	Elevator	1	The re-opening device is not compliant.	\$6,440
291586	City Hall West	Waiting Room CDD	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
291590	City Hall West	CDD Entry Doors	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$1,098
291542	City Hall West	Stairs ST-4	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$978

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291596	City Hall West	Stairs ST-6	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$978
291601	City Hall West	Stairs ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$978
291554	City Hall West	Main Lobby at Accessible Entrance	Signage	2	Signs or bulletin boards are not located within the height and viewing distance requirements for the size of visual characters.	\$250
291560	City Hall West	Public Works Entry	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
291563	City Hall West	Public Works Entry	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$3,008
291585	City Hall West	Community Development Entry	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$3,008
291587	City Hall West	Conference Room CDD	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
291588	City Hall West	CDD Entry Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
291589	City Hall West	CDD Entry Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
291591	City Hall West	CDD Entry Doors	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$100
291595	City Hall West	Egress Doors	Signage	2	Means of egress signage does not have tactile lettering.	\$440
299564	City Hall West	Women's Restroom on 1st Floor	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
299565	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
291569	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom - Door	3	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$550

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291570	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
291571	City Hall West	Men's Restroom on 1st Floor	Door	3	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
291572	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
291573	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
291574	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
291575	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
291576	City Hall West	Men's Restroom on 1st Floor	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
291577	City Hall West	Men's Restroom on 1st Floor	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
291578	City Hall West	Women's Restroom on 1st Floor	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
291579	City Hall West	Women's Restroom on 1st Floor	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
291580	City Hall West	Women's Restroom on 1st Floor	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
291581	City Hall West	Women's Restroom on 1st Floor	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
291583	City Hall West	Women's Restroom on 1st Floor	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
291584	City Hall West	Women's Restroom on 1st Floor	Restroom/Bathroom - Door	3	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$550
291593	City Hall West	Women's Restroom on 1st Floor	Door	3	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300245	City Hall West	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
291536	City Hall West	Stairs ST-2	Signage	4	Directional signage indicating the accessible path of travel is not provided, where existing path of travels are both accessible and non-accessible.	\$280
299568	City Hall West	Room Signs	Exterior Accessible Route-Signage	4	Signage identifying the name of a permanent indoor or outdoor space does not have raised lettering and/or visual characters.	\$8,400
291028	City View Skate Park (Alameda Point)	Walkway at Fenced Skate Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$0
291032	City View Skate Park (Alameda Point)	Walkway to Seating Area at Fenced Skate Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,757
291035	City View Skate Park (Alameda Point)	Walkway at Fenced Skate Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$5,000
291036	City View Skate Park (Alameda Point)	Entrance E-1	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	\$2,688
291037	City View Skate Park (Alameda Point)	Entrance E-2	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	\$2,688
291038	City View Skate Park (Alameda Point)	Unfenced Skate Park	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	\$3,360
291039	City View Skate Park (Alameda Point)	Parking Lot	Parking Space - General	1	The minimum number of accessible parking spaces is not provided.	\$1,680
291040	City View Skate Park (Alameda Point)	Unfenced Skate Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$238
291041	City View Skate Park (Alameda Point)	Unfenced Skate Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$79
297599	City View Skate Park (Alameda Point)	Pavilion	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$5,734

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291034	City View Skate Park (Alameda Point)	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
291033	City View Skate Park (Alameda Point)	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$238
291502	Civic Center Parking Garage	Stairs ST-1 and ST-2	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$7,040
291504	Civic Center Parking Garage	1st Floor - Accessible Parking Space	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
291505	Civic Center Parking Garage	1st Floor - Accessible Electric Vehicle Charging Station	Parking Space-General	1	CALIFORNIA: The number of accessible electric vehicle charging station stalls is not compliant.	\$420
291506	Civic Center Parking Garage	1st Floor - Accessible Electric Vehicle Charging Station	Parking Space - General	1	CALIFORNIA: The slope of the drive-up electric vehicle charging station stall is greater than 1:48 (2.08%).	\$6,300
291508	Civic Center Parking Garage	1st Floor - Accessible Parking Space	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
291509	Civic Center Parking Garage	1st Floor - Accessible Parking Space	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
291510	Civic Center Parking Garage	1st Floor - Accessible Parking Aisle	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291511	Civic Center Parking Garage	1st Floor - Accessible Parking Space	Parking Space - Car	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$420
291512	Civic Center Parking Garage	1st Floor - Accessible Parking Aisle	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
291513	Civic Center Parking Garage	1st Floor - Accessible Parking Aisle	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420
291518	Civic Center Parking Garage	4th Floor - Accessible Parking Space	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
291519	Civic Center Parking Garage	4th Floor - Accessible Parking Aisle	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420
291520	Civic Center Parking Garage	5th Floor - Accessible Parking Aisle	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420
291521	Civic Center Parking Garage	5th Floor - Accessible Parking Space	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
291522	Civic Center Parking Garage	5th Floor - Accessible Parking Space	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
291523	Civic Center Parking Garage	6th Floor - Accessible Parking Space	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
291524	Civic Center Parking Garage	5th Floor - Accessible Parking Aisle	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291526	Civic Center Parking Garage	3rd Floor - Accessible Parking Space	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
291527	Civic Center Parking Garage	3rd Floor - Accessible Parking Aisle	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420
291528	Civic Center Parking Garage	2nd Floor - Accessible Parking Aisle	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
291529	Civic Center Parking Garage	2nd Floor - Accessible Parking Stall	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
291530	Civic Center Parking Garage	2nd Floor - Accessible Parking Stall	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
291531	Civic Center Parking Garage	Stairs ST-1	Exterior Accessible Route	1	CALIFORNIA: The accessible route does not have 80" vertical clearance.	\$1,600
291532	Civic Center Parking Garage	Stairs ST-2	Exterior Accessible Route	1	CALIFORNIA: The accessible route does not have 80" vertical clearance.	\$3,200
298151	Civic Center Parking Garage	6th Floor - Accessible Parking Space	Parking Space-Car	1	The standard car stall and/or access aisle has openings in ground surfaces greater than 1/2" wide.	\$2,854
291515	Civic Center Parking Garage	Stairs ST-2	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
291516	Civic Center Parking Garage	Stairs ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$4,075
291525	Civic Center Parking Garage	Elevator	Elevator	3	CALIFORNIA: A tactile, raised star minimum 2" high is not provided to the left of the floor designation on both jambs at the main elevator entry level OR existing stars are not compliant.	\$560

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298152	Civic Center Parking Garage	Elevator E-1	Elevator	3	The hoistway signage is not compliant.	\$2,240
291503	Civic Center Parking Garage	Parking Structure Entrances	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$840
299635	Emergency Operations Center	Stairs ST-1	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
299637	Emergency Operations Center	Main Entrance	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750
299648	Emergency Operations Center	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall is less than 108" wide.	\$420
299649	Emergency Operations Center	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
299650	Emergency Operations Center	Accessible Aisle serving P1-A	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
299651	Emergency Operations Center	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The parallel curb ramp does not have a compliant detectable warning on the landing at the bottom of the curb ramp.	\$672
299652	Emergency Operations Center	Stairs ST-1	Stairs	1	The rear of the stairs is open.	\$3,750
299655	Emergency Operations Center	Ramp R-1	Ramp	1	CALIFORNIA: The exterior ramp railings do not extend 12" horizontally above the landing beyond the top and bottom of the ramp runs and in the same direction of the ramp run.	\$652
299657	Emergency Operations Center	Walkway to Gate Entrance	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,586
299632	Emergency Operations Center	First Floor - Men's Restroom	Interior Access Route	1	Alcoves are not 36" wide minimum where the depth exceeds 24" with forward approach, or 60" wide minimum with parallel approach and depth exceeding 15".	\$1,000
299634	Emergency Operations Center	Stairs ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
299631	Emergency Operations Center	First Floor - Lobby	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$1,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299636	Emergency Operations Center	First Floor - Lobby	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$3,750
299638	Emergency Operations Center	Second Floor - Conference Room	Assembly Area	2	An assistive listening system is required, but not provided.	\$500
299640	Emergency Operations Center	Second Floor - Conference Room	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$500
299642	Emergency Operations Center	Interior Stairs	Stairs	2	CALIFORNIA: Handrails are not compliant or are not provided.	\$3,260
299643	Emergency Operations Center	Interior Stairs	Stairs	2	The rear of the stairs is open.	\$3,750
299633	Emergency Operations Center	First Floor - Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The disposal unit at the water closet is not compliant.	\$280
299644	Emergency Operations Center	First Floor - Shower Room	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The roll-in shower stall is not compliant.	\$2,250
299646	Emergency Operations Center	First Floor - Shower Room	Restroom/Bathroom - Roll - In Shower Stall	3	CALIFORNIA: The controls, faucets, and shower spray unit are not compliant.	\$650
299647	Emergency Operations Center	First Floor - Shower Room	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
316583	Emergency Operations Center	First Floor - Shower Room	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	\$789
290854	Encinal Boat Ramp	Walkway at Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$12,685
290855	Encinal Boat Ramp	Accessible Parking Space P-1A	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
290856	Encinal Boat Ramp	Accessible Aisle serving P-1A	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
290857	Encinal Boat Ramp	Accessible Aisle serving P-1A	Parking Space-Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
290858	Encinal Boat Ramp	Accessible Aisle serving P-1B	Parking Space-Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
290859	Encinal Boat Ramp	Blended Transition BT-1	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$1,344
290860	Encinal Boat Ramp	Blended Transition BT-1	Blended Transition	1	CALIFORNIA: The blended transition cross slope is greater than 1:48 (2.08%).	\$3,171
290865	Encinal Boat Ramp	Curb Ramp CR-1 and CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$1,344
290867	Encinal Boat Ramp	Picnic Table	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,792
290868	Encinal Boat Ramp	Walking Path Along the Beach	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	#####
290869	Encinal Boat Ramp	Walking Path Along the Beach	Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$48,000
290870	Encinal Boat Ramp	Walking Path Along the Beach	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$496
290871	Encinal Boat Ramp	Beach Access	Beach Access Route	1	The beach access route is not compliant or is not provided.	\$1,792
290872	Encinal Boat Ramp	Blended Transition BT-2	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$1,344
290861	Encinal Boat Ramp	Exterior Shower at Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The roll-in shower stall is not compliant.	\$2,250
290863	Encinal Boat Ramp	Unisex Restroom RR-2	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	\$100
290864	Encinal Boat Ramp	Unisex Restroom RR-2	Restroom/Bathroom-Door	3	The door has less than 32" clear width.	\$1,124
290862	Encinal Boat Ramp	Fish Cleaning Table	Controls And Dispensers	3	Controls on dispensers are not compliant.	\$200
290873	Encinal Boat Ramp	Parking Lot	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298033	Encinal Boat Ramp	Curb Ramp CR-1	Exterior Accessible Route-Signage	1	CALIFORNIA: The non-accessible entrance is not signed with a warning indication that the entrance is not accessible.	\$280
298032	Encinal Boat Ramp	Picnic Table	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$238
292564	Estuary Park	Blended Transition at Accessible Parking	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas other than bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$1,344
292565	Estuary Park	Accessible Aisle serving P-1A and P-1B	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
292566	Estuary Park	Accessible Aisle serving P-1A and P-1B	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
292567	Estuary Park	Accessible Parking Space P-1B	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
292569	Estuary Park	Blended Transition	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$2,688
292568	Estuary Park	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
294662	Fire Station #1	Front	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$15,757
294663	Fire Station #1	CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
294664	Fire Station #1	CR-1	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$79
294665	Fire Station #1	CR-2	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$159
294666	Fire Station #1	Side	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$7,195
294672	Fire Station #1	Front	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	\$1,467

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294673	Fire Station #1	Front	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	\$139
294661	Fire Station #1	Main	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$18
294667	Fire Station #1	Main	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294668	Fire Station #1	Main	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294669	Fire Station #1	Main	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$18
294670	Fire Station #1	Main	Building Entrance - Door	1	The threshold at the accessible door is greater than 1/2" in height.	\$179
294671	Fire Station #1	Main	Signage	3	Means of egress signage is not provided.	\$55
299138	Fire Station #2	Walkway from Pacific Ave to R-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,586
299139	Fire Station #2	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,972
299140	Fire Station #2	Ramp R-1	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	\$7,944
299194	Fire Station #2	Ramp R-1	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	\$4,890
299195	Fire Station #2	Front of Building	Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$2,445
316639	Fire Station #2	Ramp R-1	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	\$4,890
316640	Fire Station #2	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
299141	Fire Station #2	Entrance Door	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
299191	Fire Station #2	Kitchen	Door	1	The door has less than 32" clear width.	\$2,600
299192	Fire Station #2	Kitchen	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
316671	Fire Station #2	Kitchen	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299144	Fire Station #2	Entrance Door	Building Entrance - Door	2	The bottom of the entry door vision light is higher than 43".	\$2,600
299145	Fire Station #2	Guest Room	Guest Room	2	The clear floor space at the bed is not compliant.	\$100
299146	Fire Station #2	Guest Room 2	Guest Room	2	The clear floor space at the bed is not compliant.	\$100
299147	Fire Station #2	Conference Room	Work Surface	2	The work surface is not compliant.	\$1,000
299154	Fire Station #2	Hallway	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
299159	Fire Station #2	Door to Sleeping Rooms	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
299186	Fire Station #2	Kitchen	Reach Range	2	Operable parts or items requiring an obstructed side reach motion are higher than 48" maximum where the obstruction depth is 10" maximum, or higher than 46" maximum where the obstruction depth is between 10" and 24" and/or lower than 15" minimum height above finish floor.	\$4,000
299188	Fire Station #2	Kitchen	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
299189	Fire Station #2	Hallway	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$200
299190	Fire Station #2	Media Room	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$200
299148	Fire Station #2	Unisex Restroom	Restroom/Bathroom-Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
299149	Fire Station #2	Unisex Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
299150	Fire Station #2	Unisex Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
299151	Fire Station #2	Unisex Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
299152	Fire Station #2	Unisex Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299153	Fire Station #2	Unisex Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	\$100
299155	Fire Station #2	Men's Locker Room	Signage	3	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	\$165
299156	Fire Station #2	Men's Locker Room	Door	3	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
299157	Fire Station #2	Men's Locker Room	Locker Rooms	3	The locker room does not have accessible lockers.	\$330
299158	Fire Station #2	Men's Locker Room	Locker Rooms	3	The locker room does not have a compliant bench.	\$789
299160	Fire Station #2	Men's Restroom and Shower Room	Door	3	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
299161	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
299162	Fire Station #2	Men's Restroom and Shower Room	Interior Access Route	3	Alcoves are not 36" wide minimum where the depth exceeds 24" with forward approach, or 60" wide minimum with parallel approach and depth exceeding 15".	\$450
299163	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom- Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
299164	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
299165	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
299166	Fire Station #2	Men's Restroom and Shower Room	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
299167	Fire Station #2	Men's Restroom and Shower Room	Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
299168	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The roll-in shower stall is not compliant.	\$2,250
299170	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	\$2,750
299171	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom- Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299172	Fire Station #2	Men's Restroom and Shower Room	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
299173	Fire Station #2	Women's Locker Room	Locker Rooms	3	The locker room does not have accessible lockers.	\$330
299174	Fire Station #2	Women's Locker Room	Locker Rooms	3	The locker room does not have a compliant bench.	\$789
299175	Fire Station #2	Women's Locker Room	Door	3	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
299176	Fire Station #2	Women's Locker Room	Signage	3	The interior signage does not have compliant visual and tactile characters, with raised or indented characters or symbols.	\$55
299177	Fire Station #2	Women's Restroom and Shower Room	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	\$2,750
299178	Fire Station #2	Women's Restroom and Shower Room	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
299179	Fire Station #2	Women's Restroom and Shower Room	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
299180	Fire Station #2	Women's Restroom and Shower Room	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	\$1,368
299181	Fire Station #2	Women's Restroom and Shower Room	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The roll-in shower stall is not compliant.	\$2,250
299184	Fire Station #2	Women's Restroom and Shower Room	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
299197	Fire Station #2	Front of Building	Signage	4	Directional signage indicating the accessible route from accessible parking to the facility is not provided, where existing routes are both accessible and non-accessible.	\$280
299556	Fire Station #3	Patio	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	\$3,171
299559	Fire Station #3	Walkway at Building	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299560	Fire Station #3	Walkway at Building	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$793
299561	Fire Station #3	Walkway at Building	Exterior Accessible Route	1	CALIFORNIA: The hazardous vehicular area does not have a detectable warning or the existing detectable warning is not compliant.	\$672
299563	Fire Station #3	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
299540	Fire Station #3	Floor 1 - Hallway	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
299546	Fire Station #3	Floor 1 - Kitchen	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
299544	Fire Station #3	Floor 1 - Central Hallway to Garage	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
299548	Fire Station #3	Floor 1 - East Hallway to Garage	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
299549	Fire Station #3	Floor 1 - Nightwatch Room	Work Surface	2	The work surface is not compliant.	\$1,000
299541	Fire Station #3	Floor 1 - Unisex Restroom 1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
299547	Fire Station #3	Access to Second Floor	Elevator	3	CALIFORNIA: An elevator is required but not provided.	\$80,000
299550	Fire Station #3	Floor 2 - Unisex Restroom 1	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
299551	Fire Station #3	Floor 2 - Unisex Restroom 1	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
299552	Fire Station #3	Floor 2 - Unisex Restroom 2,3	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
299553	Fire Station #3	Floor 2 - Unisex Restroom 2,3	Restroom/Bathroom-Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	\$1,100
299554	Fire Station #3	Floor 1 - Unisex Restroom 2	Restroom/Bathroom	3	Dispenser and/or dispenser controls are not within an allowable reach range.	\$200
299555	Fire Station #3	Floor 1 - Unisex Restroom 2	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	\$65

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
316791	Fire Station #3	Floor 2 - Unisex Restroom 2,3	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	\$710
316792	Fire Station #3	Floor 2 - Unisex Restroom 2,3	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
299543	Fire Station #3	Floor 1 - Exercise room	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	\$400
299618	Fire Station #4	Accessible Parking P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
299619	Fire Station #4	Access Aisle serving P1-A	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
299620	Fire Station #4	Accessible Parking P1-A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
299621	Fire Station #4	Accessible Parking P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
299622	Fire Station #4	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
299623	Fire Station #4	Curb Ramp CR-1	Curb Ramp	1	The slope of the curb ramp flare is greater than 1:10 (10%).	\$1,750
299626	Fire Station #4	Entrance Gate	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750
299627	Fire Station #4	Walkway around Building	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$14,865
299628	Fire Station #4	Front Entry Door	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$496
299569	Fire Station #4	Office	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
299607	Fire Station #4	Kitchen	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
299608	Fire Station #4	Kitchen	Door	1	The door has less than 32" clear width.	\$2,600
299609	Fire Station #4	Exercise Room	Door	1	The door has less than 32" clear width.	\$2,600
299610	Fire Station #4	Exercise Room	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
299611	Fire Station #4	Exit Door	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
299613	Fire Station #4	Exit Door	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
299617	Fire Station #4	Rear Entrance	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299629	Fire Station #4	Front Entry Door	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$1,000
299570	Fire Station #4	Office	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	\$1,000
299571	Fire Station #4	Office	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$500
299582	Fire Station #4	Women's Restroom	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400
299588	Fire Station #4	Main Hallway	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$200
299589	Fire Station #4	Exercise Room	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$400
299605	Fire Station #4	Kitchen	Reach Range	2	Operable parts or items requiring an obstructed side reach motion are higher than 48" maximum where the obstruction depth is 10" maximum, or higher than 46" maximum where the obstruction depth is between 10" and 24" and/or lower than 15" minimum height above finish floor.	\$5,000
299606	Fire Station #4	Kitchen	Sink	2	Sinks do not have knee and/or toe clearance.	\$1,986
299612	Fire Station #4	Throughout Building	Signage	2	Means of egress signage does not have tactile lettering.	\$330
299615	Fire Station #4	Laundry Room	Laundry- Washer	2	The washing machine controls are not within reach range.	\$200
299616	Fire Station #4	Laundry Room	Operable Part	2	Clear floor space is not provided at the operable part.	\$200
299572	Fire Station #4	Unisex Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
299573	Fire Station #4	Unisex Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
299574	Fire Station #4	Unisex Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
299575	Fire Station #4	Unisex Restroom	Restroom/Bathroom- Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
299576	Fire Station #4	Unisex Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299577	Fire Station #4	Unisex Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
299579	Fire Station #4	Women's Locker Room	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	\$789
299580	Fire Station #4	Women's Locker Room	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
299581	Fire Station #4	Women's Locker Room	Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
299583	Fire Station #4	Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
299584	Fire Station #4	Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
299585	Fire Station #4	Women's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
299586	Fire Station #4	Women's Restroom	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
299587	Fire Station #4	Women's Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The roll-in shower stall is not compliant.	\$2,250
299592	Fire Station #4	Men's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
299593	Fire Station #4	Men's Restroom	Restroom/Bathroom - Door	3	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400
299594	Fire Station #4	Men's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
299595	Fire Station #4	Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
299596	Fire Station #4	Men's Restroom	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The roll-in shower stall is not compliant.	\$2,250
299597	Fire Station #4	Men's Restroom	Restroom/Bathroom	3	Clear widths are not 36" minimum (including protruding objects). Smaller widths of 32" min. to 36" a max. length of 24" and not separated by segments a min. of 48" long and 36" wide min.	\$9,300

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
299598	Fire Station #4	Men's Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	\$27,500
299600	Fire Station #4	Men's Restroom	Restroom/Bathroom-Water Closet	3	The water closet in a wheelchair stall in a multi-stall restroom does not have the required clearance.	\$1,368
299601	Fire Station #4	Men's Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
299603	Fire Station #4	Men's Locker Room	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	\$789
317119	Fire Station #4	Women's Restroom	Controls And Dispensers	3	Controls throughout the common area are not compliant.	\$225
317154	Fire Station #4	Drinking Fountain	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
317156	Fire Station #4	Men's and Women's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$110
317157	Fire Station #4	Men's and Women's Restroom	Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$2,500
299630	Fire Station #4	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
299591	Fire Station #4	Throughout Building	Controls And Dispensers	4	CALIFORNIA: The location of electrical outlets are not compliant.	\$5,000
299604	Fire Station #4	Men's Locker Room	Turning Space	4	A compliant turning space is not provided.	\$3,600
300512	Franklin Park & Recreation Center	Picnic Area	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$896
300533	Franklin Park & Recreation Center	Shuffleboard	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$358
300534	Franklin Park & Recreation Center	Walkway from San Jose Ave	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,050
300535	Franklin Park & Recreation Center	Asphalt Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,870

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300536	Franklin Park & Recreation Center	Asphalt Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,570
300537	Franklin Park & Recreation Center	Walkway from Morton St	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,220
300538	Franklin Park & Recreation Center	Curb Ramp CR -1	Curb Ramp	1	CALIFORNIA: The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289
300539	Franklin Park & Recreation Center	Walkway from CR-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$14,480
300540	Franklin Park & Recreation Center	Asphalt Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$10,480
300541	Franklin Park & Recreation Center	Walkway to Play Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,250
300542	Franklin Park & Recreation Center	Walkway to Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,300
300543	Franklin Park & Recreation Center	Walkway at Recreation Center	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$11,734
300544	Franklin Park & Recreation Center	Walkway at Playground	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$12,280
300545	Franklin Park & Recreation Center	Walkway from San Antonio Ave to Playground	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,478
300546	Franklin Park & Recreation Center	Gate to Playground	Gate	1	The gate hardware is not compliant.	\$200
300548	Franklin Park & Recreation Center	Walkway from San Antonio Ave to Basketball Courts	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,189
300549	Franklin Park & Recreation Center	Walkway from Paru St to Tennis Courts	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,903
300551	Franklin Park & Recreation Center	Tennis Courts	Gate	1	The gate hardware is not compliant.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300552	Franklin Park & Recreation Center	Tennis Courts	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750
300553	Franklin Park & Recreation Center	Walkway from San Jose Ave to Baseball Field	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$932
300555	Franklin Park & Recreation Center	Baseball Field Gate at San Jose Ave	Gate	1	The gate hardware is not compliant.	\$200
300568	Franklin Park & Recreation Center	Drinking Fountain DF-1	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$555
300579	Franklin Park & Recreation Center	Franklin Center	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
300580	Franklin Park & Recreation Center	Franklin Center	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$10
300581	Franklin Park & Recreation Center	Franklin Center	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$50
300582	Franklin Park & Recreation Center	Franklin Center	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$560
300583	Franklin Park & Recreation Center	Franklin Center	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$258
305859	Franklin Park & Recreation Center	Walkway from San Jose Ave	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$160
305860	Franklin Park & Recreation Center	Tennis Courts	Building Entrance-Door	1	The threshold at the accessible door is raised; however the ends are not beveled.	\$179
306029	Franklin Park & Recreation Center	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
306423	Franklin Park & Recreation Center	Playground	Stairs	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$282
300571	Franklin Park & Recreation Center	Franklin Center	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300572	Franklin Park & Recreation Center	Franklin Center	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$0
300573	Franklin Park & Recreation Center	Franklin Center	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
300574	Franklin Park & Recreation Center	Franklin Center	Door	1	The door has less than 32" clear width.	\$2,600
300575	Franklin Park & Recreation Center	Franklin Center	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	\$200
300547	Franklin Park & Recreation Center	Gate to Playground	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
300550	Franklin Park & Recreation Center	Tennis Courts	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
300554	Franklin Park & Recreation Center	Baseball Field Gate at San Jose Ave	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
300558	Franklin Park & Recreation Center	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
300566	Franklin Park & Recreation Center	Baseball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
300567	Franklin Park & Recreation Center	Baseball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
306028	Franklin Park & Recreation Center	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$1,000
300570	Franklin Park & Recreation Center	Franklin Center	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$93
300577	Franklin Park & Recreation Center	Franklin Center - Kitchen	Kitchen	2	Less than minimum one of each type of operable part is within reach range.	\$400
306422	Franklin Park & Recreation Center	Franklin Center - Kitchen	Sink	2	CALIFORNIA: The sink does not have the required clear floor space of minimum 30" by minimum 48" for a forward approach with knee and toe clearance.	\$3,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300559	Franklin Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
300513	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
300514	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
300515	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
300516	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
300517	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
300518	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
300519	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
300520	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
300521	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
300522	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
300523	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
300524	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
300525	Franklin Park & Recreation Center	Men's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300526	Franklin Park & Recreation Center	Women's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
300527	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
300528	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
300529	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
300530	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	\$100
300531	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
300532	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$586
305861	Franklin Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	\$720
305862	Franklin Park & Recreation Center	Men's and Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	\$2,200
305863	Franklin Park & Recreation Center	Men's and Women's Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$626
305864	Franklin Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The disposal unit at the water closet is not compliant.	\$280
300576	Franklin Park & Recreation Center	Franklin Center - Kitchen	Kitchen - Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	\$759
300578	Franklin Park & Recreation Center	Franklin Center - Kitchen	Kitchen - Refrigerator/Freezer	4	The combination refrigerator/freezer does not have at least 50% of the freezer space 54" maximum above the finish floor or ground.	\$1,000
317569	Garage Central Repair	Parking Lot	Amenity Not Evaluated	0	The building amenity is evaluated under its separate building components.	\$0
300587	Garage Central Repair	Entry Door	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300595	Garage Central Repair	Entry Door	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300597	Garage Central Repair	Entry Door	Building Entrance-Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
300598	Garage Central Repair	Entry Door, on the Interior Side	Building Entrance-Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
300599	Garage Central Repair	Entry Door	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
300600	Garage Central Repair	Entry Door	Building Entrance - Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
300586	Garage Central Repair	Service Counter	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$1,805
300590	Garage Central Repair	Entry Hall	Protruding Object	2	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
300596	Garage Central Repair	Entry Door	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$100
300601	Garage Central Repair	Entry Hall	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$100
300602	Garage Central Repair	Entry Door	Building Entrance - Door	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
300603	Garage Central Repair	Entry Hall	Protruding Object	2	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$100
300614	Garage Central Repair	Fleet Parts Department	Door	2	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
300615	Garage Central Repair	Office	Door	2	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
300630	Garage Central Repair	Conference Room	Door	2	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
300632	Garage Central Repair	Fleet Parts Department	Protruding Object	2	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300633	Garage Central Repair	Fleet Parts Department	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$100
300634	Garage Central Repair	Lunchroom	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
300635	Garage Central Repair	Lunchroom	Door	2	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
300636	Garage Central Repair	Lunchroom	Door	2	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300638	Garage Central Repair	Lunchroom	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
300639	Garage Central Repair	Lunchroom	Building Entrance - Door	2	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
300640	Garage Central Repair	Lunchroom	Building Entrance - Door	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
300641	Garage Central Repair	Lunchroom	Door	2	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
300643	Garage Central Repair	Lunchroom	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$100
300593	Garage Central Repair	Locker and Dressing Room	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	\$789
300606	Garage Central Repair	Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
300607	Garage Central Repair	Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
300608	Garage Central Repair	Restroom	Restroom/Bathroom - Water Closet	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	\$1,100
300609	Garage Central Repair	Restroom	Restroom/Bathroom - Water Closet	3	The urinal dimensions are not compliant.	\$935
300610	Garage Central Repair	Locker and Dressing Room	Restroom/Bathroom-Locker	3	The locker area does not have accessible lockers.	\$330

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300611	Garage Central Repair	Locker and Dressing Room	Door	3	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
300612	Garage Central Repair	Locker and Dressing Room	Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300617	Garage Central Repair	Restroom	Door	3	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
300618	Garage Central Repair	Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
300619	Garage Central Repair	Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
300620	Garage Central Repair	Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
300621	Garage Central Repair	Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
300622	Garage Central Repair	Restroom	Protruding Object	3	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$600
300624	Garage Central Repair	Restroom	Restroom/Bathroom - Signage	3	The door has less than 32" clear width.	\$2,600
300625	Garage Central Repair	Restroom	Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300626	Garage Central Repair	Locker and Dressing Room	Building Entrance-Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
317481	Garage Central Repair	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
317482	Garage Central Repair	Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
300591	Garage Central Repair	Locker and Dressing Room	Locker and Dressing Rooms	4	Signage identifying the name of a permanent indoor or outdoor space does not have raised lettering and/or visual characters.	\$560
300623	Garage Central Repair	Restroom	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls are not compliant.	\$500

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300627	Garage Central Repair	Locker and Dressing Room	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls are not compliant.	\$500
300628	Garage Central Repair	Entry Hall	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls are not compliant.	\$500
300629	Garage Central Repair	Entry Hall	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls are not compliant.	\$500
296940	Godfrey Park & Recreation Center	Stairs ST-1	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	\$1,913
296945	Godfrey Park & Recreation Center	Picnic Area	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$29,730
296946	Godfrey Park & Recreation Center	Picnic Area	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$0
296947	Godfrey Park & Recreation Center	Walkway between Play Areas	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$896
296950	Godfrey Park & Recreation Center	Stairs ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$1,630
296951	Godfrey Park & Recreation Center	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$106
296953	Godfrey Park & Recreation Center	Walkway from Beach Road to Baseball Field	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$16,800
296954	Godfrey Park & Recreation Center	Walkway from Beach Road to Baseball Field	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$0
296955	Godfrey Park & Recreation Center	Walkway from Beach Road to Baseball Field	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$0

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296956	Godfrey Park & Recreation Center	Walkway from Beach Road to Baseball Field	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$250
304274	Godfrey Park & Recreation Center	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
296961	Godfrey Park & Recreation Center	Recreation Center - Rear Egress Door	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296965	Godfrey Park & Recreation Center	Recreation Center - Kitchen	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
296948	Godfrey Park & Recreation Center	Swings	Play Component - Swing	2	A compliant turning space is not provided at a school-age swing.	\$2,000
296957	Godfrey Park & Recreation Center	Recreation Center - Front Door	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
296958	Godfrey Park & Recreation Center	Recreation Center - Front Door	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
296959	Godfrey Park & Recreation Center	Recreation Center - Front Door	Signage	2	Means of egress signage does not have tactile lettering.	\$55
296960	Godfrey Park & Recreation Center	Recreation Center - Rear Egress Door	Signage	2	Means of egress signage does not have tactile lettering.	\$55
296962	Godfrey Park & Recreation Center	Recreation Center - Rear Egress Door	Door	2	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
296963	Godfrey Park & Recreation Center	Recreation Center - Kitchen	Kitchen-Range/Cooktop/Oven	2	The location of the controls requires reaching across burners.	\$759
296966	Godfrey Park & Recreation Center	Recreation Center - Kitchen	Door	2	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296967	Godfrey Park & Recreation Center	Recreation Center - Rear Door	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
296942	Godfrey Park & Recreation Center	Recreation Center - Unisex Toilet Room RR-2	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296943	Godfrey Park & Recreation Center	Recreation Center - Unisex Toilet Rooms RR-1/RR-2	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
296944	Godfrey Park & Recreation Center	Recreation Center - Unisex Toilet Rooms RR-1/RR-2	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
304273	Godfrey Park & Recreation Center	Recreation Center - Unisex Toilet Room RR-1	Restroom/Bathroom-Water Closet	3	The grab bars at the water closet are not compliant.	\$1,420
296941	Godfrey Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$238
296964	Godfrey Park & Recreation Center	Recreation Center - Kitchen	Exterior Accessible Route-Signage	4	Signage identifying the name of a permanent indoor or outdoor space does not have raised lettering and/or visual characters.	\$280
303448	Grand St Boat Launch Bathroom & Ramp	Walkway from P-1A	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$800
303449	Grand St Boat Launch Bathroom & Ramp	Walkway from Restrooms to Boat Launch	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$11,892
294894	Grand St Boat Launch Bathroom & Ramp	Walkway from Restrooms to Boat Launch	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas other than bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$2,688
294895	Grand St Boat Launch Bathroom & Ramp	Walkway from Restrooms to Boat Launch	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$0
294896	Grand St Boat Launch Bathroom & Ramp	Walkway from Restrooms to Boat Launch	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$0
294898	Grand St Boat Launch Bathroom & Ramp	Gangway	Boarding Pier	1	The edge protection is higher than 4" maximum and/or wider than 2" maximum.	\$4,890

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294899	Grand St Boat Launch Bathroom & Ramp	Park Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$34,110
294869	Grand St Boat Launch Bathroom & Ramp	Walkway at Restroom	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$10,703
294871	Grand St Boat Launch Bathroom & Ramp	Accessible Parking Space P-1A	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
294872	Grand St Boat Launch Bathroom & Ramp	Access Aisle serving P-1A	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
294873	Grand St Boat Launch Bathroom & Ramp	Accessible Parking Space P-1A	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
294874	Grand St Boat Launch Bathroom & Ramp	Access Aisle serving P-1A	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294875	Grand St Boat Launch Bathroom & Ramp	Accessible Parking Space P-1A	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294879	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Interior Access Route	1	Alcoves are not 36" wide minimum where the depth exceeds 24" with forward approach, or 60" wide minimum with parallel approach and depth exceeding 15".	\$1,000
303447	Grand St Boat Launch Bathroom & Ramp	Men's and Women's Restroom	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$3,500
294900	Grand St Boat Launch Bathroom & Ramp	Fish Cleaning Table/Sink	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
294897	Grand St Boat Launch Bathroom & Ramp	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
294877	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
294878	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
294880	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	\$720

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294881	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
294882	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294883	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	\$1,368
294884	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294885	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
294886	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
294887	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294888	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Restroom/Bathroom - Toilet Stall	3	The wheelchair stall with a wall mounted water closet, in a multi-stall restroom, is less than 60" wide and 56" deep.	\$1,368
294889	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
294890	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294891	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294892	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
294893	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
303443	Grand St Boat Launch Bathroom & Ramp	Women's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
303444	Grand St Boat Launch Bathroom & Ramp	Men's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
303445	Grand St Boat Launch Bathroom & Ramp	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
303446	Grand St Boat Launch Bathroom & Ramp	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is located on a wall or post-mounted cantilevered, but is not minimum 18" and maximum 19" in depth.	\$5,439
294870	Grand St Boat Launch Bathroom & Ramp	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
306142	Harbor Bay Ferry Terminal	Public Transit Stop	Exterior Accessible Route	1	CALIFORNIA: The bus stop boarding and alighting area is not compliant.	\$793
298382	Harbor Bay Ferry Terminal	Accessible Parking Space P-1B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
298383	Harbor Bay Ferry Terminal	Accessible Parking Space P-1B	Parking Space - Car	1	CALIFORNIA: The car parking stall is less than 108" wide.	\$420
298384	Harbor Bay Ferry Terminal	Accessible Parking Space P-1A	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$420
298385	Harbor Bay Ferry Terminal	Accessible Parking Space P1-D	Parking Space - Car	1	CALIFORNIA: The car parking stall is less than 108" wide.	\$420
298386	Harbor Bay Ferry Terminal	Accessible Parking Space P-1C	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$420
298387	Harbor Bay Ferry Terminal	Access Aisle serving P-1E & P-1F	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
298388	Harbor Bay Ferry Terminal	Accessible Parking Space P1-E	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$420
298395	Harbor Bay Ferry Terminal	Walkway at Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,537
298396	Harbor Bay Ferry Terminal	Walkway at CR-3	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,200
298397	Harbor Bay Ferry Terminal	Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298398	Harbor Bay Ferry Terminal	Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,600
298399	Harbor Bay Ferry Terminal	Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$9,360
298400	Harbor Bay Ferry Terminal	Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$13,760
298401	Harbor Bay Ferry Terminal	Walkway To Public Transit Stop	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,973
298402	Harbor Bay Ferry Terminal	Walking Path	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$6,720
298380	Harbor Bay Ferry Terminal	Parking Lot	Parking Space-Van	2	CALIFORNIA: A van space and adjacent van aisle are not provided.	\$1,680
298379	Harbor Bay Ferry Terminal	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
298389	Harbor Bay Ferry Terminal	Men's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
298390	Harbor Bay Ferry Terminal	Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
298391	Harbor Bay Ferry Terminal	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
298392	Harbor Bay Ferry Terminal	Women's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
298393	Harbor Bay Ferry Terminal	Women's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
298394	Harbor Bay Ferry Terminal	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
306299	Harbor Bay Ferry Terminal	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$238

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298381	Harbor Bay Ferry Terminal	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
294163	Harrington Park & Restrooms	Picnic Tables	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$1,075
294159	Harrington Park & Restrooms	Walkway to Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$10,000
299539	Harrington Park & Restrooms	Unisex Restroom (RR-1)	Restroom/Bathroom-Unisex	2	Alcoves are not 36" wide min. if depth exceeds 24" with forward approach or 60" wide min. with parallel approach and depth exceeds 15"	\$1,250
294160	Harrington Park & Restrooms	Unisex Restroom (RR-1)	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The lavatory located adjacent the side wall /side partition does not have the required side clearance.	\$0
294161	Harrington Park & Restrooms	Unisex Restroom (RR-1)	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294162	Harrington Park & Restrooms	Drinking Fountain	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
299538	Harrington Park & Restrooms	Drinking Fountain	Drinking Fountain/Water Cooler	4	The minimum number and types of drinking fountains are not provided.	\$0
295390	Jean Sweeney Park & Restrooms	Playground	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$0
295376	Jean Sweeney Park & Restrooms	Walkway through Parking Lot from Atlantic Avenue	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$672
295377	Jean Sweeney Park & Restrooms	Accessible Parking Space P-1B	Parking Space-Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
295380	Jean Sweeney Park & Restrooms	Walkway through Parking Lot from Atlantic Avenue	Exterior Accessible Route	1	The sidewalk does not have 80" vertical clearance.	\$1,599
295381	Jean Sweeney Park & Restrooms	Accessible Parking Space P-1C	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295394	Jean Sweeney Park & Restrooms	Stone Art Display	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	\$728
305033	Jean Sweeney Park & Restrooms	Playground	Stairs	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$106
295388	Jean Sweeney Park & Restrooms	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$1,750
295389	Jean Sweeney Park & Restrooms	Swings	Play Component - Swing	2	A turning space is not provided at a preschool swing.	\$1,000
295383	Jean Sweeney Park & Restrooms	Park Map Sign	Signage	2	Protruding signs posted on two posts more than 12" apart: the lowest part of the sign is over 27" or under 80" above finish floor.	\$280
295385	Jean Sweeney Park & Restrooms	Jean Sweeney Sign	Signage	2	Protruding signs posted on two posts more than 12" apart: the lowest part of the sign is over 27" or under 80" above finish floor.	\$280
305032	Jean Sweeney Park & Restrooms	Playground	Transfer System	2	The transfer platform for connecting to elevated play elements has non-compliant dimensions.	\$23,909
295391	Jean Sweeney Park & Restrooms	Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
295387	Jean Sweeney Park & Restrooms	Men's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
295392	Jean Sweeney Park & Restrooms	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
298343	Krusi Park & Recreation Center	Tennis Courts	Building Entrance-Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
298345	Krusi Park & Recreation Center	Tennis Courts	Gate	1	The gate hardware is not compliant.	\$400
298347	Krusi Park & Recreation Center	Walking Paths throughout Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$40,000
298348	Krusi Park & Recreation Center	Performance Seating Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$7,168

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298350	Krusi Park & Recreation Center	Tennis Courts	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$200
298351	Krusi Park & Recreation Center	Corn Hole Game Area	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$717
298352	Krusi Park & Recreation Center	Tennis Courts	Exterior Accessible Route	1	The gate maneuvering clearance area is not compliant.	\$568
298355	Krusi Park & Recreation Center	Walking Paths throughout Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$5,000
298359	Krusi Park & Recreation Center	Picnic Area	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,792
298360	Krusi Park & Recreation Center	Performance Stage	Assembly Area	1	A direct accessible route is not provided from the assembly seating area to a performance area.	\$3,964
309046	Krusi Park & Recreation Center	Drinking Fountain DF-3 and DF-4	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$120
309047	Krusi Park & Recreation Center	Drinking Fountain DF-2	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$120
309048	Krusi Park & Recreation Center	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$13,440
309360	Krusi Park & Recreation Center	Fenced Playground	Stairs	1	CALIFORNIA: The top of the transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$282
298330	Krusi Park & Recreation Center	Recreation Center - Main Room	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
298333	Krusi Park & Recreation Center	Recreation Center - Kitchen Exit Door	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
298334	Krusi Park & Recreation Center	Recreation Center - Kitchen Exit Door	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
309051	Krusi Park & Recreation Center	Recreation Center - Main Room	Building Entrance-Floor Surface	1	The edges of the carpet are not securely attached.	\$450

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298346	Krusi Park & Recreation Center	Tennis Courts	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$320
298353	Krusi Park & Recreation Center	Baseball Field #3	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	\$2,185
298357	Krusi Park & Recreation Center	Baseball Field #1	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	\$2,185
298361	Krusi Park & Recreation Center	Fenced Playground	Ground Surface - Fibar	2	The ground surface has not been inspected and maintained regularly.	\$1,463
298362	Krusi Park & Recreation Center	Fenced Playground	Transfer System	2	The transfer platform for connecting to elevated play elements has non-compliant dimensions.	\$23,909
298363	Krusi Park & Recreation Center	Fenced Playground	Play Component-Swing	2	A turning space is not provided at a preschool swing.	\$750
298364	Krusi Park & Recreation Center	Unfenced Playground	Play Component-Swing	2	A compliant turning space is not provided at a school-age swing.	\$750
298365	Krusi Park & Recreation Center	Unfenced Playground	Ground Surface - Fibar	2	The ground surface has not been inspected and maintained regularly.	\$800
298329	Krusi Park & Recreation Center	Recreation Center - Main Room	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298331	Krusi Park & Recreation Center	Recreation Center - Main Room	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298332	Krusi Park & Recreation Center	Recreation Center - Kitchen Exit Door	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298354	Krusi Park & Recreation Center	Drinking Fountain DF-3 and DF-4	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$3,500
298356	Krusi Park & Recreation Center	Drinking Fountain DF-2	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$3,500

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298358	Krusi Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
298328	Krusi Park & Recreation Center	Recreation Center - Unisex Restroom	Restroom/Bathroom - Door	3	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$200
298336	Krusi Park & Recreation Center	Recreation Center - Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
298337	Krusi Park & Recreation Center	Recreation Center - Men's Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
298338	Krusi Park & Recreation Center	Recreation Center - Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The disposal unit at the water closet is not compliant.	\$280
298339	Krusi Park & Recreation Center	Recreation Center - Women's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
298340	Krusi Park & Recreation Center	Recreation Center - Women's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
298341	Krusi Park & Recreation Center	Recreation Center - Women's Restroom	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$794
298342	Krusi Park & Recreation Center	Recreation Center - Men's Restroom	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$794
309049	Krusi Park & Recreation Center	Recreation Center - Men's Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
309050	Krusi Park & Recreation Center	Recreation Center - Women's Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
309361	Krusi Park & Recreation Center	Drinking Fountain DF-2, DF-3, and DF-4	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	\$24,000
298034	Leydecker Park & Recreation Center	Walking Path Perimeter	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	\$49,550
298035	Leydecker Park & Recreation Center	Walking Path Perimeter	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$15,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298036	Leydecker Park & Recreation Center	Walking Path Perimeter	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$0
298037	Leydecker Park & Recreation Center	Parking Lot P1	Parking Spaces-General	1	Accessible parking spaces are not dispersed where parking serves more than one accessible entrance.	\$420
298051	Leydecker Park & Recreation Center	Playground	Curb Ramp	1	CALIFORNIA: The curb ramp is non-compliant.	\$2,422
298054	Leydecker Park & Recreation Center	Playground	Building Entrance-Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$1,250
298056	Leydecker Park & Recreation Center	Walking Path Perimeter	Exterior Accessible Route	1	An accessible route does not connect accessible building or facility entrances with all accessible spaces and elements within the building or facility. At least one accessible route shall connect accessible elements that are on the same site.	\$717
298062	Leydecker Park & Recreation Center	Tennis Courts	Interior Door	1	CALIFORNIA: Maneuvering clearance at the door is not level and clear.	\$1,250
298063	Leydecker Park & Recreation Center	Parking Lot P2	Parking Space - General	1	The minimum number of accessible parking spaces is not provided.	\$11,600
298064	Leydecker Park & Recreation Center	Tennis Courts	Exterior Accessible Route	1	An accessible route does not connect accessible building or facility entrances with all accessible spaces and elements within the building or facility. At least one accessible route shall connect accessible elements that are on the same site.	\$1,982
309501	Leydecker Park & Recreation Center	Playground	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$717
298046	Leydecker Park & Recreation Center	Men's Restroom	Interior Access Route	1	Alcoves are not 36" wide minimum where the depth exceeds 24" with forward approach, or 60" wide minimum with parallel approach and depth exceeding 15".	\$500
298066	Leydecker Park & Recreation Center	Large Activities Room Door 1	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
298067	Leydecker Park & Recreation Center	Large Activities Room Door 1	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298069	Leydecker Park & Recreation Center	Large Activities Room Door 2	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
298070	Leydecker Park & Recreation Center	Large Activities Room Door 2	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298080	Leydecker Park & Recreation Center	Large Activities Room Door 4	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
298081	Leydecker Park & Recreation Center	Large Activities Room Door 3	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
298082	Leydecker Park & Recreation Center	Large Activities Room Door 2	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
298083	Leydecker Park & Recreation Center	Large Activities Room Door 1	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
298086	Leydecker Park & Recreation Center	Small Classroom Exit Door 1	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
298087	Leydecker Park & Recreation Center	Small Classroom Exit Door 1	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
298089	Leydecker Park & Recreation Center	Small Classroom Exit Door 2	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
298090	Leydecker Park & Recreation Center	Small Classroom Exit Door 2	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
298095	Leydecker Park & Recreation Center	Small Classroom Door 1	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
298096	Leydecker Park & Recreation Center	Small Classroom Door 1	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298097	Leydecker Park & Recreation Center	Small Classroom Door 2	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298098	Leydecker Park & Recreation Center	Small Classroom Door 2	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
298101	Leydecker Park & Recreation Center	Kitchen Exit Door	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298109	Leydecker Park & Recreation Center	Vestibule Doors	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298050	Leydecker Park & Recreation Center	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$1,313

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298052	Leydecker Park & Recreation Center	Playground	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
298053	Leydecker Park & Recreation Center	Playground	Play Component-Swing	2	A compliant turning space is not provided at a school-age swing.	\$1,500
298055	Leydecker Park & Recreation Center	Playground	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
298057	Leydecker Park & Recreation Center	Baseball Field	Exterior Accessible Route	2	A compliant accessible route is not provided from the public access to the amenity.	\$717
298058	Leydecker Park & Recreation Center	Baseball Field	Bleacher Seating	2	The wheelchair space is not the minimum required dimensions at the bleacher seating for the baseball field.	\$250
298061	Leydecker Park & Recreation Center	Tennis Courts	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
298065	Leydecker Park & Recreation Center	Baseball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$105
298047	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400
298068	Leydecker Park & Recreation Center	Large Activities Room Door 1	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298071	Leydecker Park & Recreation Center	Large Activities Room Door 2	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298072	Leydecker Park & Recreation Center	Large Activities Room Door 3	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298073	Leydecker Park & Recreation Center	Large Activities Room Door 3	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,000
298074	Leydecker Park & Recreation Center	Large Activities Room Door 3	Signage	2	Means of egress signage does not have tactile lettering.	\$55
298075	Leydecker Park & Recreation Center	Large Activities Room Door 1	Signage	2	Means of egress signage does not have tactile lettering.	\$55
298076	Leydecker Park & Recreation Center	Large Activities Room Door 2	Signage	2	Means of egress signage does not have tactile lettering.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298077	Leydecker Park & Recreation Center	Large Activities Room Door 4	Signage	2	Means of egress signage does not have tactile lettering.	\$55
298078	Leydecker Park & Recreation Center	Large Activities Room Door 4	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298079	Leydecker Park & Recreation Center	Large Activities Room Door 4	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298084	Leydecker Park & Recreation Center	Small Classroom Exit Door 1	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,000
298085	Leydecker Park & Recreation Center	Small Classroom Exit Door 1	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298088	Leydecker Park & Recreation Center	Small Classroom Exit Door 2	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,000
298092	Leydecker Park & Recreation Center	Small Classroom 2	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
298093	Leydecker Park & Recreation Center	Small Classroom 1	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
298094	Leydecker Park & Recreation Center	Small Classroom Door 1	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298099	Leydecker Park & Recreation Center	Kitchen Exit Door	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298102	Leydecker Park & Recreation Center	Kitchen	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
298105	Leydecker Park & Recreation Center	Kitchen Door to Large Classroom	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298106	Leydecker Park & Recreation Center	Kitchen Door to Large Classroom	Door	2	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
298107	Leydecker Park & Recreation Center	Vestibule Doors	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298108	Leydecker Park & Recreation Center	Vestibule Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298111	Leydecker Park & Recreation Center	Vestibule Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,000
298113	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400
298060	Leydecker Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
309524	Leydecker Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
298038	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298039	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
298040	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
298041	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
298042	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	\$355
298043	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$293
298044	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	\$720
298045	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
298048	Leydecker Park & Recreation Center	Men's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
298049	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298112	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298114	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
298115	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298116	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
298117	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
298118	Leydecker Park & Recreation Center	Women's Restroom	Controls And Dispensers	3	The height of controls are not compliant.	\$400
298119	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
298120	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	\$355
298121	Leydecker Park & Recreation Center	Women's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
298122	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
298123	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298124	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
298125	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298126	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Door	3	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400
298127	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298128	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
309500	Leydecker Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
309521	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
309522	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
309523	Leydecker Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$100
298059	Leydecker Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$238
298103	Leydecker Park & Recreation Center	Kitchen	Kitchen-Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	\$759
298104	Leydecker Park & Recreation Center	Kitchen	U-Shaped or L-Shaped Layout	4	The clearance between opposing base cabinets, counter tops, appliances or walls within kitchen work areas in a U-shaped kitchen enclosed on three sides are less than 60".	\$9,850
297177	Lincoln Park & Facilities	Playground	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	\$0
297037	Lincoln Park & Facilities	CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
297038	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$753
297039	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$8,087
297040	Lincoln Park & Facilities	CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
297041	Lincoln Park & Facilities	CR-2	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297042	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$11,555
297043	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,162
297044	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$10,742
297045	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$17,184
297046	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$119
297047	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$99
297048	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$6,520
297049	Lincoln Park & Facilities	Sidewalk	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$198
297148	Lincoln Park & Facilities	Harrison Center	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$5,847
297151	Lincoln Park & Facilities	Harrison Center	Building Entrance - Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
297171	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$8,400
297172	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$5,320
297173	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,160
297174	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$11,040
297175	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$6,840

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297176	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$396
297178	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$6,000
297179	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$16,500
297180	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$25,150
297181	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$139
297182	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$39,937
297183	Lincoln Park & Facilities	Park	Exterior Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$192
297184	Lincoln Park & Facilities	Fitness Park	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,452
297185	Lincoln Park & Facilities	P1-A	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
297186	Lincoln Park & Facilities	P1-A	Parking Space - Car	1	An access aisle is not provided.	\$420
297187	Lincoln Park & Facilities	P1-A	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
297188	Lincoln Park & Facilities	P1	Parking Space - Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	\$840
297189	Lincoln Park & Facilities	P1-A	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
297190	Lincoln Park & Facilities	Accessible Parking Space	Exterior Accessible Route	1	A compliant accessible route is not provided from accessible parking to the public facility entrance.	\$480
297194	Lincoln Park & Facilities	Baseball	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	\$1,750

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297195	Lincoln Park & Facilities	Baseball	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$5,451
297196	Lincoln Park & Facilities	Baseball	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$10,445
297198	Lincoln Park & Facilities	Picnic Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$892
297201	Lincoln Park & Facilities	Picnic Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,330
297202	Lincoln Park & Facilities	Picnic Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,427
297203	Lincoln Park & Facilities	To Pool	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$200
297204	Lincoln Park & Facilities	To Tennis	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	\$1,487
297205	Lincoln Park & Facilities	To Tennis	Exterior Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$120
297207	Lincoln Park & Facilities	Basketball Court	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,102
297066	Lincoln Park & Facilities	Harrison Center	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$18
297067	Lincoln Park & Facilities	Harrison Center	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297068	Lincoln Park & Facilities	Harrison Center	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
297069	Lincoln Park & Facilities	Harrison Center	Building Entrance - Door	1	The entry door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
297070	Lincoln Park & Facilities	Harrison Center	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
297072	Lincoln Park & Facilities	Harrison Center	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	\$3,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297083	Lincoln Park & Facilities	Harrison Center- Women's Restroom	Restroom/Bathroom - Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
297097	Lincoln Park & Facilities	Harrison Center- Men's Restroom	Restroom/Bathroom - Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
297104	Lincoln Park & Facilities	Harrison Center	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
297105	Lincoln Park & Facilities	Harrison Center	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
297106	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297107	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297108	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297109	Lincoln Park & Facilities	Harrison Center	Door	1	The door has less than 32" clear width.	\$2,600
297110	Lincoln Park & Facilities	Harrison Center	Building Entrance - Door	1	The accessible door has less than 32" clear width.	\$2,480
297111	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297112	Lincoln Park & Facilities	Harrison Center	Door	1	The door has less than 32" clear width.	\$2,600
297113	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297114	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297116	Lincoln Park & Facilities	Harrison Center	Door	1	The door has less than 32" clear width.	\$2,600
297117	Lincoln Park & Facilities	Harrison Center	Interior Access Route	1	The accessible route is less than 36" wide.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297120	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297121	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297122	Lincoln Park & Facilities	Harrison Center	Door	1	The door has less than 32" clear width.	\$2,600
297123	Lincoln Park & Facilities	Harrison Center	Door	1	The door has less than 32" clear width.	\$2,600
297124	Lincoln Park & Facilities	Harrison Center	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
297125	Lincoln Park & Facilities	Harrison Center	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
297126	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297127	Lincoln Park & Facilities	Harrison Center	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
297128	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297129	Lincoln Park & Facilities	Harrison Center	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	\$1,000
297131	Lincoln Park & Facilities	Harrison Center	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	\$500
297132	Lincoln Park & Facilities	Harrison Center	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	\$500
297133	Lincoln Park & Facilities	Harrison Center	Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297134	Lincoln Park & Facilities	Harrison Center	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
297135	Lincoln Park & Facilities	Harrison Center	Door	1	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$93

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297139	Lincoln Park & Facilities	Harrison Center	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297140	Lincoln Park & Facilities	Harrison Center	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
297141	Lincoln Park & Facilities	Harrison Center	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
297142	Lincoln Park & Facilities	Harrison Center	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297143	Lincoln Park & Facilities	Harrison Center	Door	1	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$186
297144	Lincoln Park & Facilities	Harrison Center	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
297145	Lincoln Park & Facilities	Harrison Center	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
297146	Lincoln Park & Facilities	Harrison Center	Door	1	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$186
297147	Lincoln Park & Facilities	Harrison Center	Floor Surface	1	The edges of the carpet are not securely attached.	\$36
297153	Lincoln Park & Facilities	Harrison Center	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297154	Lincoln Park & Facilities	Harrison Center	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
297155	Lincoln Park & Facilities	Harrison Center	Door	1	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$186
297156	Lincoln Park & Facilities	Harrison Center	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
297159	Lincoln Park & Facilities	Lodge	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$18
297160	Lincoln Park & Facilities	Lodge	Building Entrance - Door	1	CA The door lacks a level landing	\$1,178

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297161	Lincoln Park & Facilities	Lodge	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
297162	Lincoln Park & Facilities	Lodge	Building Entrance - Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
297167	Lincoln Park & Facilities	Lodge	Controls And Dispensers	1	The height of controls throughout the common area are not compliant.	\$500
297168	Lincoln Park & Facilities	Lodge	Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
297169	Lincoln Park & Facilities	Lodge	Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
297150	Lincoln Park & Facilities	Harrison Center	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	\$720
297152	Lincoln Park & Facilities	Harrison Center	Trash Receptacle	2	A trash receptacle is not located on an accessible route, within reach range, and with adjacent clear ground space.	\$115
297191	Lincoln Park & Facilities	Baseball Field	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	\$262
297192	Lincoln Park & Facilities	Baseball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
297193	Lincoln Park & Facilities	Baseball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
297197	Lincoln Park & Facilities	Baseball	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
297206	Lincoln Park & Facilities	To Tennis	Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$200
297208	Lincoln Park & Facilities	Bocce	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
297210	Lincoln Park & Facilities	Park	Bench	2	An adjacent clear space is not provided at the bench.	\$52
297211	Lincoln Park & Facilities	Park	Bench	2	An adjacent clear space is not provided at the bench.	\$52

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297212	Lincoln Park & Facilities	Park	Bench	2	An adjacent clear space is not provided at the bench.	\$52
297213	Lincoln Park & Facilities	Park	Bench	2	An adjacent clear space is not provided at the bench.	\$52
297214	Lincoln Park & Facilities	Park	Bench	2	An adjacent clear space is not provided at the bench.	\$52
297050	Lincoln Park & Facilities	Restroom Building- Men's	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	\$794
297051	Lincoln Park & Facilities	Restroom Building- Men's	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$0
297058	Lincoln Park & Facilities	Restroom Building- Women's	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	\$794
297059	Lincoln Park & Facilities	Restroom Building- Women's	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$0
297086	Lincoln Park & Facilities	Harrison Center- Women's Restroom	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	\$794
297115	Lincoln Park & Facilities	Harrison Center	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	\$5,414
297119	Lincoln Park & Facilities	Harrison Center	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	\$720
297130	Lincoln Park & Facilities	Harrison Center	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
297137	Lincoln Park & Facilities	Harrison Center	Dispenser	2	Items requiring a reach motion, but do not have an operable part, are not within compliant reach ranges.	\$400
297138	Lincoln Park & Facilities	Harrison Center	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$93
297199	Lincoln Park & Facilities	DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
297052	Lincoln Park & Facilities	Restroom Building- Men's	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297053	Lincoln Park & Facilities	Restroom Building-Men's	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
297054	Lincoln Park & Facilities	Restroom Building-Men's	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
297055	Lincoln Park & Facilities	Restroom Building-Men's	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
297056	Lincoln Park & Facilities	Restroom Building-Men's	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
297057	Lincoln Park & Facilities	Restroom Building-Men's	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
297060	Lincoln Park & Facilities	Restroom Building-Women's	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
297061	Lincoln Park & Facilities	Restroom Building-Women's	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
297062	Lincoln Park & Facilities	Restroom Building-Women's	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
297063	Lincoln Park & Facilities	Restroom Building-Women's	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
297064	Lincoln Park & Facilities	Restroom Building-Women's	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
297065	Lincoln Park & Facilities	Restroom Building-Men's	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
297071	Lincoln Park & Facilities	Harrison Center	Signage	3	Means of egress signage is not provided.	\$55
297074	Lincoln Park & Facilities	Harrison Center	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
297075	Lincoln Park & Facilities	Harrison Center	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$5,439

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297076	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
297077	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
297078	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297079	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	\$1,250
297080	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297081	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
297082	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width	\$1,124
297084	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
297085	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Shelving	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
297087	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
297088	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
297089	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Controls And Dispensers	3	The height of controls are not compliant.	\$200
297090	Lincoln Park & Facilities	Harrison Center-Women's Restroom	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	\$2,750
297091	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	\$2,750
297092	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Controls And Dispensers	3	The height of controls are not compliant.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297093	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
297094	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
297095	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	\$200
297096	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
297098	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
297099	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297100	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
297101	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
297102	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width	\$1,124
297103	Lincoln Park & Facilities	Harrison Center-Men's Restroom	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	\$1,250
297157	Lincoln Park & Facilities	Harrison Center	Signage	3	Means of egress signage is not provided.	\$55
297158	Lincoln Park & Facilities	Harrison Center	Signage	3	Means of egress signage is not provided.	\$55
297166	Lincoln Park & Facilities	Lodge	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
297170	Lincoln Park & Facilities	Lodge	Signage	3	Means of egress signage is not provided.	\$55
297149	Lincoln Park & Facilities	Harrison Center	Kitchen - Counter - Public	4	A minimum 30" wide section of the counter is not a minimum height of 28" and maximum height of 34" with knee and toe clearance.	\$2,382

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297200	Lincoln Park & Facilities	DF-1	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	\$2,505
297209	Lincoln Park & Facilities	Bocce	Grill	4	An accessible 48" x 48" clear floor or ground space is not located on all usable sides of the grill.	\$140
297073	Lincoln Park & Facilities	Harrison Center	Telephone	4	The highest operable part of the accessible public telephone is not compliant.	\$400
297118	Lincoln Park & Facilities	Harrison Center	Kitchen - Range/Cooktop/Oven	4	The location of the controls requires reaching across burners.	\$759
297136	Lincoln Park & Facilities	Harrison Center	Kitchen - Counter - Public	4	A minimum 30" wide section of the counter is not a minimum height of 28" and maximum height of 34" with knee and toe clearance.	\$2,382
297163	Lincoln Park & Facilities	Lodge	Kitchen - Counter - Residential And Employee-Only	5	The height of the counter is greater than 34".	\$1,986
297164	Lincoln Park & Facilities	Lodge	U-Shaped or L-Shaped Layout	5	The clearance between opposing base cabinets, counter tops, appliances or walls within kitchen work areas in a U-shaped kitchen enclosed on three sides are less than 60".	\$9,850
297165	Lincoln Park & Facilities	Lodge	Sink	5	The accessible sink does not have push/lever hardware.	\$555
296996	Littlejohn Park & Recreation Center	Recreation Center and Restrooms	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	\$0
296981	Littlejohn Park & Recreation Center	Walkway at Recreation Center	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$224
296987	Littlejohn Park & Recreation Center	Walkway at Recreation Center	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$250
296988	Littlejohn Park & Recreation Center	Playground	Elevated Route- Accessed By Ramp	1	The elevated route connecting elevated play components accessed by a ramp has running slopes greater than 1:12.	\$25,000
296991	Littlejohn Park & Recreation Center	Playground	Stairs	1	CALIFORNIA: The top of the transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$176

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296995	Littlejohn Park & Recreation Center	Temporary Portable Toilet	Restroom/Bathroom - Door	1	The threshold at the accessible door is greater than 1/2 inch in height.	\$179
296997	Littlejohn Park & Recreation Center	Walkway from Pacific Avenue to Recreation Center	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$40
296998	Littlejohn Park & Recreation Center	Walkway at Recreation Center	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,200
297003	Littlejohn Park & Recreation Center	Temporary Portable Toilet	Restroom/Bathroom - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
297005	Littlejohn Park & Recreation Center	Walkway at Basketball Courts	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,800
297006	Littlejohn Park & Recreation Center	Walkway at Basketball Courts	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$600
297007	Littlejohn Park & Recreation Center	Walkway at Basketball Courts	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$400
297008	Littlejohn Park & Recreation Center	Walkway at Basketball Courts	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$60
297010	Littlejohn Park & Recreation Center	Walkway from Pacific Avenue and Benton Street	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$800
297013	Littlejohn Park & Recreation Center	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
309363	Littlejohn Park & Recreation Center	Baseball Field	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,075
296977	Littlejohn Park & Recreation Center	Alameda Library Amenity	Reach Range	2	Operable parts or items requiring an obstructed side reach motion are higher than 48" maximum where the obstruction depth is 10" maximum, or higher than 46" maximum where the obstruction depth is between 10" and 24" and/or lower than 15" minimum height above finish floor.	\$500

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296984	Littlejohn Park & Recreation Center	Playground	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
296985	Littlejohn Park & Recreation Center	Playground	Transfer System	2	A means of support is not provided at the transfer platform and/or transfer steps.	\$1,000
296986	Littlejohn Park & Recreation Center	Playground	Play Component - Play Table	2	The play table does not provide knee clearance 24" high minimum, 17" deep minimum, and 30" wide minimum, and/or the tops of rims, curbs, or other obstructions at the play table are higher than 31".	\$1,103
297009	Littlejohn Park & Recreation Center	Basketball Courts	Player Seating	2	A wheelchair space is not provided at the player seating for the basketball courts.	\$52
309364	Littlejohn Park & Recreation Center	Baseball Field	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$105
297000	Littlejohn Park & Recreation Center	Picnic Area 1	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
297001	Littlejohn Park & Recreation Center	Picnic Area 2	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
297004	Littlejohn Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
309362	Littlejohn Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
303762	Longfellow Park & Restrooms	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
294075	Longfellow Park & Restrooms	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
294076	Longfellow Park & Restrooms	Sidewalk	Exterior Accessible Route	1	ADVISORY: A marked crosswalk is not provided where the accessible route crosses a vehicular way between the accessible parking aisle and the building entrance.	\$0
294077	Longfellow Park & Restrooms	Sidewalk	Protruding Object	1	Protruding objects obstruct the required clear width of the accessible route.	\$2,000
294104	Longfellow Park & Restrooms	Playstructure	Stairs	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$458

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294111	Longfellow Park & Restrooms	Gate to Tennis Courts	Gate	1	The gate maneuvering clearance area is not compliant.	\$568
294112	Longfellow Park & Restrooms	Walkway North of Tennis Courts	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	\$119
294113	Longfellow Park & Restrooms	Walkway North of Tennis Courts	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$119
294114	Longfellow Park & Restrooms	Walkway North of Tennis Courts	Exterior Accessible Route	1	CALIFORNIA: The slopes of the exterior accessible route are not compliant.	\$595
294115	Longfellow Park & Restrooms	Walkway North of Tennis Courts	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
294094	Longfellow Park & Restrooms	Recreation Center Entry	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294095	Longfellow Park & Restrooms	Recreation Center Entry	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$0
294068	Longfellow Park & Restrooms	Curb Ramp CR-1	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
294097	Longfellow Park & Restrooms	Recreation Center Entry	Floor Surface	1	Floor surfaces are not firm, stable or slip resistant	\$72
294098	Longfellow Park & Restrooms	Recreation Center Entry North	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294099	Longfellow Park & Restrooms	Recreation Center Entry South	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$0
294100	Longfellow Park & Restrooms	Recreation Center Entry South	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294101	Longfellow Park & Restrooms	Recreation Center Entry South	Building Entrance-Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$100
294107	Longfellow Park & Restrooms	Playstructure	Play Component - Play Table	2	The play table does not provide knee clearance 24" high minimum, 17" deep minimum, and 30" wide minimum, and/or the tops of rims, curbs, or other obstructions at the play table are higher than 31".	\$1,103

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294110	Longfellow Park & Restrooms	Picnic Area	Picnic Table	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	\$2,000
294116	Longfellow Park & Restrooms	Gate at Park Entry	Sport Court	2	The gate does not have a smooth surface within 10" of the ground.	\$160
294117	Longfellow Park & Restrooms	Gate to Tennis Courts	Sport Court	2	The gate does not have a smooth surface within 10" of the ground.	\$160
294080	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$400
294089	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$400
294096	Longfellow Park & Restrooms	Recreation Center Entry	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$220
294069	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294070	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294071	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
294072	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
294073	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
294078	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294079	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
294081	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory located adjacent the side wall /side partition does not have the required side clearance.	\$720
294082	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294083	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	\$630
294084	Longfellow Park & Restrooms	All-Gender Restroom RR-2	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$100
294085	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294086	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294087	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
294088	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294090	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
294091	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Restroom/Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	\$630
294092	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$100
294093	Longfellow Park & Restrooms	All-Gender Restroom RR-1	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294102	Longfellow Park & Restrooms	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	\$5,440
294640	Main Library	P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
294641	Main Library	P1-A	Parking Space - Van	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$420
294642	Main Library	P1-A	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
294643	Main Library	P1-A	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294644	Main Library	P1-B	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294645	Main Library	P1-B	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
294646	Main Library	P1-B	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
294647	Main Library	P1-B	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294650	Main Library	P1-C	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
294651	Main Library	P1-C	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294652	Main Library	P1-D	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294653	Main Library	P1-C	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
294654	Main Library	P1-C	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294655	Main Library	P1-D	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
294579	Main Library	Rear Parking	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$654
294649	Main Library	CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
294656	Main Library	Front	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$119
294657	Main Library	Front	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,249
294658	Main Library	Side	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$218
294659	Main Library	Side	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$634
294612	Main Library	Computer Lab	Interior Access Route	1	CALIFORNIA: The width of the aisle is not compliant.	\$100
294613	Main Library	Computer Lab	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294614	Main Library	Computer Lab	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294616	Main Library	Homework Center	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294617	Main Library	Homework Center	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294618	Main Library	Exit Door Second Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294619	Main Library	Exit Door Second Floor	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294623	Main Library	Exit Door First Floor	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294624	Main Library	Children's Programs	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294625	Main Library	Meeting Room A	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294626	Main Library	Meeting Room A Exit	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294628	Main Library	Meeting Room A Exit	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294629	Main Library	Meeting Room A	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294630	Main Library	Family Study Room	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294631	Main Library	Family Study Room	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294632	Main Library	Family Study Room	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294634	Main Library	Meeting Room B	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294635	Main Library	Meeting Room B	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294636	Main Library	Meeting Room B	Interior Access Route	1	The accessible route is less than 36" wide.	\$1,982
294637	Main Library	ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$2,282
294638	Main Library	Main	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294639	Main Library	Main	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294593	Main Library	Outdoor Seating	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294594	Main Library	Outdoor Seating	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294595	Main Library	Outdoor Seating	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294603	Main Library	Kid's Restroom	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294660	Main Library	ST-2	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$326
294615	Main Library	Homework Center	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
294633	Main Library	Meeting Room B	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
294605	Main Library	Men's Second Floor	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	\$794
294583	Main Library	Men's Restroom-Cafe	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	\$794
294590	Main Library	Women's Restroom-Cafe	Restroom/Bathroom	2	CALIFORNIA: The baby changing table is not compliant.	\$794
294620	Main Library	Exit Door Second Floor	Signage	3	Means of egress signage is not provided.	\$55
294621	Main Library	Exit Door First Floor	Signage	3	Means of egress signage is not provided.	\$55
294622	Main Library	Outdoor Seating	Signage	3	Means of egress signage is not provided.	\$55
294627	Main Library	Meeting Room A Exit	Signage	3	Means of egress signage is not provided.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294592	Main Library	Outdoor Seating	Dining And Work Surface	3	CALIFORNIA: A compliant dining table is not provided.	\$1,300
294596	Main Library	Cafe	Dining And Work Surface	3	CALIFORNIA: A compliant dining table is not provided.	\$1,300
294597	Main Library	Cafe	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
294598	Main Library	Kid's Restroom	Restroom/Bathroom - Water Closet	3	ADVISORY: The centerline of the water closet, in the restroom used primarily by children, does not meet children's specifications.	\$0
294599	Main Library	Kid's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294600	Main Library	Kid's Restroom	Restroom/Bathroom - Water Closet	3	ADVISORY: The height of the water closet used primarily by children does not meet children's specifications.	\$0
294601	Main Library	Kid's Restroom	Restroom/Bathroom - Water Closet	3	ADVISORY: The toilet paper dispenser in the restroom primarily for children's use does not meet children's specifications.	\$0
294602	Main Library	Kid's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
294604	Main Library	Men's Second Floor	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294606	Main Library	Men's Second Floor	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294607	Main Library	Women's Second Floor	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
294608	Main Library	Women's Second Floor	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294609	Main Library	Women's Second Floor	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
294610	Main Library	Women's Second Floor	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294611	Main Library	Women's Second Floor	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294580	Main Library	Men's Restroom-Cafe	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
294581	Main Library	Men's Restroom-Cafe	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294582	Main Library	Men's Restroom-Cafe	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
294584	Main Library	Men's Restroom-Cafe	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
294585	Main Library	Men's Restroom-Cafe	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294586	Main Library	Men's Restroom-Cafe	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
294587	Main Library	Women's Restroom-Cafe	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
294588	Main Library	Women's Restroom-Cafe	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294589	Main Library	Women's Restroom-Cafe	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
294591	Main Library	Women's Restroom-Cafe	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294648	Main Library	Rear Parking	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$654
292584	Main St Ferry Terminal & Bathroom	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: An accessible route is not provided from the bus stop and its alighting area to adjacent sidewalks, paths, and streets.	\$0
292570	Main St Ferry Terminal & Bathroom	Accessible Route from Parking Lot	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas other than bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$10,080
292572	Main St Ferry Terminal & Bathroom	Curb Ramp (CR-3)	Curb Ramp	1	CALIFORNIA: The parallel curb ramp does not have a compliant detectable warning on the landing at the bottom of the curb ramp.	\$672
292574	Main St Ferry Terminal & Bathroom	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
292575	Main St Ferry Terminal & Bathroom	Accessible Parking Aisle P1-E	Parking Space-Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
292576	Main St Ferry Terminal & Bathroom	Accessible Parking Space P1-G	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$840
292577	Main St Ferry Terminal & Bathroom	Accessible Parking Space P1-I	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$420
292578	Main St Ferry Terminal & Bathroom	Accessible Parking Space P1-H	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
292579	Main St Ferry Terminal & Bathroom	Accessible Parking Space P1-H	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
292581	Main St Ferry Terminal & Bathroom	Parking Lot	Parking Space - General	1	Accessible parking spaces are not at the nearest accessible entrance.	\$1,680
292582	Main St Ferry Terminal & Bathroom	Parking Lot	Parking Space - General	1	The minimum number of accessible parking spaces is not provided.	\$420
292583	Main St Ferry Terminal & Bathroom	Men's Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
292585	Main St Ferry Terminal & Bathroom	Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
292586	Main St Ferry Terminal & Bathroom	Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
292587	Main St Ferry Terminal & Bathroom	Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
292588	Main St Ferry Terminal & Bathroom	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
292589	Main St Ferry Terminal & Bathroom	Women's Restroom	Restroom/Bathroom- Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
292590	Main St Ferry Terminal & Bathroom	Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
292591	Main St Ferry Terminal & Bathroom	Women's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
292592	Main St Ferry Terminal & Bathroom	Women's Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
292593	Main St Ferry Terminal & Bathroom	Women's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
292594	Main St Ferry Terminal & Bathroom	Women's Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$200
292595	Main St Ferry Terminal & Bathroom	Drinking Fountain (DF-1)	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$3,611
292597	Main St Ferry Terminal & Bathroom	Telephone	Telephone	4	Clear floor space is not provided at the accessible public telephone	\$100
292580	Main St Ferry Terminal & Bathroom	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
292571	Main St Ferry Terminal & Bathroom	Accessible Parking Aisle P1-A	Parking Space - Van	5	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
302317	Main Street Dog Park	Dog Park Vestibule Entrance	Building Entrance-Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$3,500
292665	Main Street Dog Park	Dog Park Access from the Parking Lot	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	\$44,800
292666	Main Street Dog Park	Parking Lot	Parking Spaces-General	1	Accessible parking spaces are not dispersed where parking serves more than one accessible entrance.	\$420
292668	Main Street Dog Park	Dog Park Vestibule	Gate	1	The gate does not have a smooth surface within 10" of the ground.	\$320
292670	Main Street Dog Park	Walkway from Parking Lot to Entrance	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$41,622
292671	Main Street Dog Park	Curb Ramp CR-1 and CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
292672	Main Street Dog Park	Walkway from Parking Lot to Entrance	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$0

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
292667	Main Street Dog Park	Dog Park	Exterior Accessible Route	2	CALIFORNIA: An accessible route is not provided to each functional area in the restaurant, cafeteria, banquet facility, bar or similar facility, including sunken, raised and outdoor areas.	\$1,210
302319	Main Street Dog Park	Dog Park	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
302322	Main Street Linear Park	Street Crossing at Willie Stargell Ave	Amenity Not Evaluated	0	The amenity is not regulated by the ADA.	\$0
292915	Main Street Linear Park	Walking Path throughout Park from Atlantic Ave to Singleton Ave	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$0
292916	Main Street Linear Park	Entrance from Bertero Ct	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$672
292917	Main Street Linear Park	North Entrance from Kingfisher Ave	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$672
292918	Main Street Linear Park	North Entrance from Kingfisher Ave	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,250
292919	Main Street Linear Park	South Entrance from Kingfisher Ave	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$672
292920	Main Street Linear Park	South Entrance from Kingfisher Ave	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,500
292921	Main Street Linear Park	Entrance from Kinkaid Ct	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,500
292922	Main Street Linear Park	Entrance from Kinkaid Ct	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$672
292923	Main Street Linear Park	Walking Path throughout Park from Atlantic Ave to Singleton Ave	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	#####

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
292924	Main Street Linear Park	Walking Path throughout Park from Atlantic Ave to Singleton Ave	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$0
292925	Main Street Soccer Field	Bus stop to Gate 1	Exterior Accessible Route	1	CALIFORNIA: An accessible route is not provided from the bus stop and its alighting area to adjacent sidewalks, paths, and streets.	\$4,480
292926	Main Street Soccer Field	Parking Lot	Parking Space-Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	\$840
292927	Main Street Soccer Field	Gate 1 to Bleachers	Exterior Accessible Route	1	A compliant accessible route is not provided from the property line to the site facilities.	\$4,480
292928	Main Street Soccer Field	Walkway (West)	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$11,892
292929	Main Street Soccer Field	Walkway (West)	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$9,910
292931	Main Street Soccer Field	Bleacher Seating	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$1,792
313419	Main Street Soccer Field	Parking Lot	Parking Space-Car	1	CALIFORNIA: A car accessible stall and adjacent aisle are not provided.	\$2,520
313420	Main Street Soccer Field	Parking Lot	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
313421	Main Street Soccer Field	Parking Lot	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$840
313423	Main Street Soccer Field	Gate 1 (G-1)	Gate	1	The gate maneuvering clearance area is not compliant.	\$568
313424	Main Street Soccer Field	Gate 1 (G-1)	Gate	1	The gate maneuvering clearance area is not compliant.	\$568
292930	Main Street Soccer Field	Bleacher Seating	Bleacher Seating	2	A wheelchair space is not provided at the bleacher seating for the soccer field.	\$358
313422	Main Street Soccer Field	Gate 1 (G-1)	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298153	Maintenance Service Center & Garage	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
298154	Maintenance Service Center & Garage	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
298191	Maintenance Service Center & Garage	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,189
298192	Maintenance Service Center & Garage	Sidewalk	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$79
298193	Maintenance Service Center & Garage	Sidewalk	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$991
298194	Maintenance Service Center & Garage	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
298195	Maintenance Service Center & Garage	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
298196	Maintenance Service Center & Garage	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
298197	Maintenance Service Center & Garage	Sidewalk	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$99
309527	Maintenance Service Center & Garage	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
298157	Maintenance Service Center & Garage	Restroom for All Gender	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
298163	Maintenance Service Center & Garage	Primary Entry	Floor Surface	1	Floor surfaces are not firm, stable or slip resistant	\$500
298164	Maintenance Service Center & Garage	Lobby	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
298166	Maintenance Service Center & Garage	Office	Door	1	The accessible door does not have the required PULL SIDE maneuvering clearances.	\$100
298167	Maintenance Service Center & Garage	Break Station in Corridor	Floor Surface	1	Floor surfaces are not firm, stable or slip resistant	\$450

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298173	Maintenance Service Center & Garage	Restroom for Women	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$0
298174	Maintenance Service Center & Garage	Restroom for Men	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$100
298185	Maintenance Service Center & Garage	Lunch Room	Floor Surface	1	Floor surfaces are not firm, stable or slip resistant	\$900
298188	Maintenance Service Center & Garage	Lunch Room	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
298189	Maintenance Service Center & Garage	Primary Entry	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$79
298190	Maintenance Service Center & Garage	Primary Entry	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,189
298427	Maintenance Service Center & Garage	Restroom for All Gender	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$0
298432	Maintenance Service Center & Garage	Primary Entry	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$500
298433	Maintenance Service Center & Garage	Primary Entry	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
298437	Maintenance Service Center & Garage	Restroom for Women	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
298438	Maintenance Service Center & Garage	Restroom for Men	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$250
298441	Maintenance Service Center & Garage	Lunch Room	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
298444	Maintenance Service Center & Garage	Lunch Room	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
298445	Maintenance Service Center & Garage	Lunch Room	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$500
298158	Maintenance Service Center & Garage	Restroom for All Gender	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298161	Maintenance Service Center & Garage	Restroom for All Gender	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$100
298162	Maintenance Service Center & Garage	Primary Entry	Door	2	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$100
298165	Maintenance Service Center & Garage	Lobby	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$100
298168	Maintenance Service Center & Garage	Lobby	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$100
298169	Maintenance Service Center & Garage	Corridor	Door	2	The bottom of the door vision light is higher than 43" maximum.	\$2,600
298181	Maintenance Service Center & Garage	Restroom for Men	Restroom/Bathroom	2	The slope of the floor surface is greater than 2%.	\$450
298184	Maintenance Service Center & Garage	Lunch Room	Door	2	The bottom of the door vision light is higher than 43" maximum.	\$2,600
298186	Maintenance Service Center & Garage	Conference Room	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$1,000
298187	Maintenance Service Center & Garage	Conference Room	Door	2	The bottom of the doors' vision lights are higher than 43" maximum.	\$5,200
298428	Maintenance Service Center & Garage	Restroom for All Gender	Door	2	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
298431	Maintenance Service Center & Garage	Primary Entry	Door	2	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$100
298434	Maintenance Service Center & Garage	Lobby	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$1,805
298443	Maintenance Service Center & Garage	Lunch Room	Building Entrance-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$160
309530	Maintenance Service Center & Garage	Lobby	Signage	2	Means of egress signage does not have tactile lettering.	\$550

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298159	Maintenance Service Center & Garage	Restroom for All Gender	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
298160	Maintenance Service Center & Garage	Restroom for All Gender	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The controls, faucets, and shower spray unit are not compliant.	\$650
298170	Maintenance Service Center & Garage	Restroom for Women	Restroom/Bathroom-Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
298171	Maintenance Service Center & Garage	Restroom for Women	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
298172	Maintenance Service Center & Garage	Restroom for Women	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	\$65
298175	Maintenance Service Center & Garage	Restroom for Men	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$100
298176	Maintenance Service Center & Garage	Restroom for Men	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	\$100
298178	Maintenance Service Center & Garage	Restroom for Men	Restroom/Bathroom-Locker	3	The locker area does not have a compliant bench.	\$200
298179	Maintenance Service Center & Garage	Restroom for Men	Restroom/Bathroom-Locker	3	The locker area does not have accessible lockers.	\$330
298180	Maintenance Service Center & Garage	Restroom for Men	Restroom/Bathroom-Roll-In Shower Stall	3	CALIFORNIA: The controls, faucets, and shower spray unit are not compliant.	\$650
298182	Maintenance Service Center & Garage	Corridor	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
298425	Maintenance Service Center & Garage	Restroom for All Gender	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	\$65
298426	Maintenance Service Center & Garage	Restroom for All Gender	Restroom/Bathroom-Lavatory	3	The lavatory does not have the required clear floor space of minimum 30" by minimum 48".	\$3,000
298429	Maintenance Service Center & Garage	Restroom for All Gender	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
298430	Maintenance Service Center & Garage	Restroom for All Gender	Restroom/Bathroom-Shelving	3	The shelf is not located between 40" minimum and 48" maximum above finish floor.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298439	Maintenance Service Center & Garage	Restroom for Men	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
298440	Maintenance Service Center & Garage	Restroom for Men	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$200
309528	Maintenance Service Center & Garage	Restroom for All Gender	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
298156	Maintenance Service Center & Garage	Parking Lot P1	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
298183	Maintenance Service Center & Garage	Lunch Room	Exterior Accessible Route-Signage	4	Signage with tactile lettering is located lower than 48" measured to the baseline of the lowest tactile character, or higher than 60" measured to the baseline of the highest tactile character.	\$280
294901	Marina Cove Waterfront Park	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
294903	Marina Cove Waterfront Park	Accessible Parking Space P-1A	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294904	Marina Cove Waterfront Park	Accessible Parking Space P-1A	Parking Space - Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
294905	Marina Cove Waterfront Park	Access Aisle serving P-1A	Parking Space - Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
294906	Marina Cove Waterfront Park	Accessible Parking Space P-1A	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
294907	Marina Cove Waterfront Park	Access Aisle serving P-1A	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294908	Marina Cove Waterfront Park	Walkway throughout Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$0
294909	Marina Cove Waterfront Park	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
294911	Marina Cove Waterfront Park	Walkway at Parking Lot	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294912	Marina Cove Waterfront Park	Ramp R-1	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$3,310
294914	Marina Cove Waterfront Park	Walkway throughout Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$39,640
303452	Marina Cove Waterfront Park	Play Area	Stairs	1	CALIFORNIA: Each transfer step do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$352
303453	Marina Cove Waterfront Park	Ramp R-1	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	\$1,630
294913	Marina Cove Waterfront Park	Chess Table	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
303451	Marina Cove Waterfront Park	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
294902	Marina Cove Waterfront Park	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
294910	Marina Cove Waterfront Park	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	4	A clear space is not positioned at the lower level drinking fountain for a forward approach and centered on the unit.	\$238
348167	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$549
348107	Marina Village Park	Walkway from P1-A to CR-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$496
348108	Marina Village Park	Walkway from P1-A to CR-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$800
348109	Marina Village Park	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
348110	Marina Village Park	Walkway around Building	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$11,939
348111	Marina Village Park	Walkway around Building	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$0
348112	Marina Village Park	Walkway around Building	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$25

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
348113	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,563
348114	Marina Village Park	Walkway from CR-1 to CR-2	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$13,218
348115	Marina Village Park	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
348116	Marina Village Park	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
348117	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$250
348118	Marina Village Park	Walkway to Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$400
348119	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,513
348120	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,000
348121	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,063
348122	Marina Village Park	Walkway to Bridge Across Lagoon	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$300
348123	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,625
348124	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,750
348125	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,688
348126	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
348127	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,250
348128	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	The sidewalk does not have 80" vertical clearance.	\$1,599

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
348129	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,650
348130	Marina Village Park	East Entrance	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	\$100
305117	Marina Village Park	Access Aisle serving P1-A	Parking Space-Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420
296000	Marina Village Park	Walkway from P1-A to CR-1	Exterior Accessible Route	1	ADVISORY: A marked crosswalk is not provided where the accessible route crosses a vehicular way between the accessible parking aisle and the building entrance.	\$0
296009	Marina Village Park	Accessible Parking Space P1-A	Parking Space-Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
296010	Marina Village Park	Curb Ramp CR-1	Curb Ramp - Perpendicular	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
296012	Marina Village Park	Curb Ramp CR-1	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$0
296013	Marina Village Park	Curb Ramp CR-1	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$0
296019	Marina Village Park	Walkway from CR-2	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
296020	Marina Village Park	Walkway from CR-2	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
296023	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$375
296024	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$125
296026	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$500
296027	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,000
296028	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$500

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296029	Marina Village Park	Walkway through Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$500
298142	Marina Village Park	Access Aisle serving P1-A	Parking Space-Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
298129	Marina Village Park	Accessible Parking Space P1-A	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
348165	Marina Village Park	West Fitness Area	Exterior Accessible Route	2	A compliant accessible route is not provided from the public access to the amenity.	\$8,064
348166	Marina Village Park	East Fitness Area	Exterior Accessible Route	2	A compliant accessible route is not provided from the public access to the amenity.	\$22,579
296022	Marina Village Park	Dog Waste Bags	Reach Range	2	Items requiring an obstructed forward reach motion are higher than 48" maximum height where the depth of the obstruction is 20" maximum, or greater than 44" maximum height where the depth of the obstruction is 20" to 25" maximum, or lower than minimum 15" height above finish floor.	\$500
296025	Marina Village Park	Picnic Area	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
348131	Marina Village Park	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
348132	Marina Village Park	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
348133	Marina Village Park	Men's Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
348134	Marina Village Park	Men's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
348135	Marina Village Park	Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
348136	Marina Village Park	Men's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required clear floor space of minimum 30" by minimum 48".	\$3,000
348137	Marina Village Park	Men's Restroom	Restroom/Bathroom-Floor Space	3	The required turning space within the restroom is not provided.	\$11,563

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
348138	Marina Village Park	Men's Restroom	Restroom/Bathroom - Lavatory	3	The slope of the floor surface is greater than 2% cross or 5% running	\$446
348139	Marina Village Park	Men's Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,563
348140	Marina Village Park	Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
348141	Marina Village Park	Men's Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$366
348142	Marina Village Park	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	\$1,100
348143	Marina Village Park	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
348144	Marina Village Park	Men's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
348145	Marina Village Park	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
348146	Marina Village Park	Men's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$250
348147	Marina Village Park	Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
348148	Marina Village Park	Women's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
348149	Marina Village Park	Women's Restroom	Restroom/Bathroom - Door	3	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
348150	Marina Village Park	Men's and Women's Restroom	Restroom/Bathroom - Door	3	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar, which can be 78" minimum.	\$5,200
348151	Marina Village Park	Women's Restroom	Restroom/Bathroom	3	Controls on dispensers are not compliant.	\$281
348152	Marina Village Park	Women's Restroom	Restroom/Bathroom - Floor Space	3	The required turning space within the restroom is not provided.	\$9,250
348153	Marina Village Park	Women's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
348154	Marina Village Park	Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
348155	Marina Village Park	Women's Restroom	Restroom/Bathroom - Lavatory	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
348156	Marina Village Park	Women's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required clear floor space of minimum 30" by minimum 48".	\$3,000
348157	Marina Village Park	Women's Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
348158	Marina Village Park	Women's Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$366
348159	Marina Village Park	Women's Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
348160	Marina Village Park	Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	\$1,375
348161	Marina Village Park	Women's Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
348162	Marina Village Park	Women's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
348163	Marina Village Park	Women's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$250
348164	Marina Village Park	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
349079	Marina Village Park	Women's Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,563
349080	Marina Village Park	Men's Restroom	Building Entrance-Door	3	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$2,188
349081	Marina Village Park	Women's Restroom	Building Entrance-Door	3	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$2,188
296004	Marina Village Park	Parking Lot P1	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
347919	Mastick Senior Center & Grounds	Residential Dwelling Units	Amenity Not Evaluated	0	The amenity cannot be accessed and, therefore, cannot be evaluated.	\$0

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347918	Mastick Senior Center & Grounds	Residential Dwelling Units	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$8,960
347990	Mastick Senior Center & Grounds	Entrance Doors	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$4,026
347991	Mastick Senior Center & Grounds	Entrance Doors	Door	1	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$28,600
296343	Mastick Senior Center & Grounds	Ramp R-1	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$19,860
296352	Mastick Senior Center & Grounds	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
296377	Mastick Senior Center & Grounds	Access Aisle serving P1-A	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
296378	Mastick Senior Center & Grounds	Accessible Parking Space P1-B	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
296379	Mastick Senior Center & Grounds	Access Aisle serving P1-C and P1-D	Curb Ramp	1	The curb ramp projects into vehicular traffic lanes, parking space, or associated access aisle.	\$1,750
296380	Mastick Senior Center & Grounds	Accessible Parking Space P1-D	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
296381	Mastick Senior Center & Grounds	Accessible Parking Space P1-E	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
296382	Mastick Senior Center & Grounds	Accessible Parking Space P1-F	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
296383	Mastick Senior Center & Grounds	Accessible Parking Space P1-G	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
296384	Mastick Senior Center & Grounds	Accessible Parking Space P1-H	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
297768	Mastick Senior Center & Grounds	Ramp R-1	Ramp	1	CALIFORNIA: The exterior ramp railings do not extend 12" horizontally above the landing beyond the top and bottom of the ramp runs and in the same direction of the ramp run.	\$326

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297796	Mastick Senior Center & Grounds	Access Aisle serving P1-B	Curb Ramp	1	The curb ramp projects into vehicular traffic lanes, parking space, or associated access aisle.	\$1,750
297797	Mastick Senior Center & Grounds	Accessible Parking Space P1-C	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
297798	Mastick Senior Center & Grounds	Accessible Parking Space P1-E	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
297799	Mastick Senior Center & Grounds	Accessible Parking Space P1-F	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
297800	Mastick Senior Center & Grounds	Accessible Parking Space P1-G	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
297801	Mastick Senior Center & Grounds	Accessible Parking Space P1-H	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
348013	Mastick Senior Center & Grounds	Ramp R-3	Ramp	1	CALIFORNIA: The exterior ramp railings do not extend 12" horizontally above the landing beyond the top and bottom of the ramp runs and in the same direction of the ramp run.	\$652
347860	Mastick Senior Center & Grounds	Ramp R-4	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$19,860
347861	Mastick Senior Center & Grounds	Ramp R-4	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	\$9,780
347863	Mastick Senior Center & Grounds	Ramp R-4	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
347920	Mastick Senior Center & Grounds	Courtyard	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	\$1,456
348003	Mastick Senior Center & Grounds	Walkway to Skills Center	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,478
347848	Mastick Senior Center & Grounds	Patio at Social Hall	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$620
347842	Mastick Senior Center & Grounds	Walkway to Thrift Shop	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347844	Mastick Senior Center & Grounds	Patio at Social Hall	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,982
347846	Mastick Senior Center & Grounds	Patio at Social Hall	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
347870	Mastick Senior Center & Grounds	Walkway from CR-1 to CR-2	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$6,937
347871	Mastick Senior Center & Grounds	Walkway from CR-1 to CR-2	Exterior Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$500
347872	Mastick Senior Center & Grounds	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
347873	Mastick Senior Center & Grounds	Walkway to R-3	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,478
347874	Mastick Senior Center & Grounds	Walkway to R-3	Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$600
347875	Mastick Senior Center & Grounds	Ramp R-3	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,972
347876	Mastick Senior Center & Grounds	Ramp R-3	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	\$9,780
347877	Mastick Senior Center & Grounds	Walkway from R-3 to R-4	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$5,576
347878	Mastick Senior Center & Grounds	Walkway from R-3 to R-4	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
347880	Mastick Senior Center & Grounds	Courtyard	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,974
347850	Mastick Senior Center & Grounds	Patio at Social Hall	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,956
347922	Mastick Senior Center & Grounds	Curb Ramp CR-2	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas other than bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$2,016
347923	Mastick Senior Center & Grounds	Overhead Signs	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	\$2,912

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347924	Mastick Senior Center & Grounds	Passenger Loading Zone	Loading/Unloading Zone	1	An accessible passenger loading/unloading zone is not provided where a loading/unloading area is present.	\$2,400
347925	Mastick Senior Center & Grounds	Passenger Loading Zone	Loading/Unloading Zone	1	CALIFORNIA: The loading/unloading access aisle is not marked or the existing aisle marking is not compliant.	\$420
347926	Mastick Senior Center & Grounds	Passenger Loading Zone	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas other than bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$1,344
347928	Mastick Senior Center & Grounds	Courtyard	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$7,930
347930	Mastick Senior Center & Grounds	Courtyard	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	#####
347931	Mastick Senior Center & Grounds	Courtyard	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$372
347933	Mastick Senior Center & Grounds	Courtyard	Exterior Accessible Route	1	CALIFORNIA: The accessible route does not have 80" vertical clearance.	\$500
347938	Mastick Senior Center & Grounds	Courtyard	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the accessible route.	\$1,456
347940	Mastick Senior Center & Grounds	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,972
347941	Mastick Senior Center & Grounds	Ramp R-1	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	\$9,780
347944	Mastick Senior Center & Grounds	Walkway East of East Building	Guards	1	CALIFORNIA: Guards are not compliant or are not provided where required.	\$1,630
347945	Mastick Senior Center & Grounds	Entrance Gate to R-2	Building Entrance - Door	1	The accessible door has less than 32" clear width.	\$2,480
347947	Mastick Senior Center & Grounds	Ramp R-2	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$7,282
347948	Mastick Senior Center & Grounds	Ramp R-2	Ramp	1	CALIFORNIA: The ramp run does not have edge protection or the edge protection is not compliant.	\$9,780

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347949	Mastick Senior Center & Grounds	Ramp R-2	Ramp	1	CALIFORNIA: The exterior ramp railings do not extend 12" horizontally above the landing beyond the top and bottom of the ramp runs and in the same direction of the ramp run.	\$652
347782	Mastick Senior Center & Grounds	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$7,875
347783	Mastick Senior Center & Grounds	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall is less than 108" wide.	\$420
347784	Mastick Senior Center & Grounds	Access Aisle serving P1-B	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
347785	Mastick Senior Center & Grounds	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
347786	Mastick Senior Center & Grounds	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
347787	Mastick Senior Center & Grounds	Access Aisle serving P1-C and P1-D	Parking Space-Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$6,250
347788	Mastick Senior Center & Grounds	Accessible Parking Space P1-D	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
347789	Mastick Senior Center & Grounds	Accessible Parking Space P1-G	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
347790	Mastick Senior Center & Grounds	Access Aisle serving P1-G and P1-H	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
347791	Mastick Senior Center & Grounds	Accessible Parking Space P1-H	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
347792	Mastick Senior Center & Grounds	Accessible Parking Space P1-E	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
347793	Mastick Senior Center & Grounds	Access Aisle serving P1-E and P1-F	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
347794	Mastick Senior Center & Grounds	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347795	Mastick Senior Center & Grounds	Curb Ramp CR-1	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas other than bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$3,360
347796	Mastick Senior Center & Grounds	Walkway to Social Hall	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$620
348018	Mastick Senior Center & Grounds	Ramp R-4	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$4,965
347961	Mastick Senior Center & Grounds	Main and Rear Entrance Door	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	\$5,200
347968	Mastick Senior Center & Grounds	Doors	Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$10,400
347857	Mastick Senior Center & Grounds	Entrance Door	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
348004	Mastick Senior Center & Grounds	Entrance Doors	Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$732
348007	Mastick Senior Center & Grounds	Entrance Doors	Door	1	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$5,200
347855	Mastick Senior Center & Grounds	Northwest Entrance Door	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
347856	Mastick Senior Center & Grounds	Entrance Door from Patio	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
347858	Mastick Senior Center & Grounds	Northeast Entrance Door	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
347859	Mastick Senior Center & Grounds	Northeast Entrance Door	Building Entrance - Door	1	Gaps in the door threshold or entry are over .5" wide OR elongated gaps are not perpendicular to path of travel	\$250
347797	Mastick Senior Center & Grounds	Main Entrance Door	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	\$2,600
347831	Mastick Senior Center & Grounds	Men's Restroom	Exterior Accessible Route	1	CALIFORNIA: The accessible route does not have 80" vertical clearance.	\$200
347847	Mastick Senior Center & Grounds	West Entrance Door	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347849	Mastick Senior Center & Grounds	North Entrance Door	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
347896	Mastick Senior Center & Grounds	Main Entrance Door	Building Entrance - Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$125
347899	Mastick Senior Center & Grounds	Main Entrance Door	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$1,830
347921	Mastick Senior Center & Grounds	Room C	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
347978	Mastick Senior Center & Grounds	Entrance Doors	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$4,026
347986	Mastick Senior Center & Grounds	Entrance Doors	Door	1	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$28,600
347903	Mastick Senior Center & Grounds	Laundry Room	Door	2	The door has less than 32" clear width.	\$2,600
347904	Mastick Senior Center & Grounds	Laundry Room	Door	2	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	\$293
347905	Mastick Senior Center & Grounds	Laundry Room	Door	2	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
347906	Mastick Senior Center & Grounds	Laundry Room	Operable Part	2	Clear floor space is not provided at the operable part.	\$3,000
347907	Mastick Senior Center & Grounds	Laundry Room	Exterior Accessible Route	2	Clear ground space is not provided at the operable part.	\$625
347864	Mastick Senior Center & Grounds	Door to Laundry/RR-4	Building Entrance - Door	2	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
347865	Mastick Senior Center & Grounds	Door to Laundry/RR-4	Building Entrance - Door	2	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
347992	Mastick Senior Center & Grounds	Entrance Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$4,400

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347993	Mastick Senior Center & Grounds	Egress Doors	Signage	2	Means of egress signage does not have tactile lettering.	\$605
347994	Mastick Senior Center & Grounds	Room B	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$500
347995	Mastick Senior Center & Grounds	Closets	Door	2	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	\$586
347997	Mastick Senior Center & Grounds	Room B	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
347998	Mastick Senior Center & Grounds	Room B	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	\$65
348000	Mastick Senior Center & Grounds	Offices	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$500
296374	Mastick Senior Center & Grounds	Courtyard	Vertical Level Change	2	Vertical level changes between 1/4" and 1/2" high are not beveled or vertical level changes greater than 1/2" high are not ramped.	\$119
296375	Mastick Senior Center & Grounds	Courtyard	Exterior Accessible Route	2	A compliant accessible route is not provided from the public access to the amenity.	\$2,688
347843	Mastick Senior Center & Grounds	Gates to Courtyard	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$800
347851	Mastick Senior Center & Grounds	Garden	Exterior Accessible Route	2	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,974
347852	Mastick Senior Center & Grounds	Garden	Exterior Accessible Route	2	Clear ground space is not provided at the operable part.	\$150
347853	Mastick Senior Center & Grounds	Garden	Controls And Dispensers	2	Controls throughout the common area are not compliant.	\$225
347854	Mastick Senior Center & Grounds	Garden	Exterior Accessible Route	2	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$499
347929	Mastick Senior Center & Grounds	Courtyard	Exterior Accessible Route	2	Clear ground space is not provided at the operable part.	\$250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347946	Mastick Senior Center & Grounds	Entrance Gate to R-2	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
347962	Mastick Senior Center & Grounds	Egress Doors	Signage	2	Means of egress signage does not have tactile lettering.	\$165
347963	Mastick Senior Center & Grounds	Main Lobby	Protruding Object	2	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
347964	Mastick Senior Center & Grounds	Main Lobby	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$125
347966	Mastick Senior Center & Grounds	Interior Doors	Door	2	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$732
347967	Mastick Senior Center & Grounds	Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$2,400
347974	Mastick Senior Center & Grounds	Coffee Area	Restroom/Bathroom - Door	2	CALIFORNIA: The dining or work surface is not compliant.	\$500
347976	Mastick Senior Center & Grounds	Game Room	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$500
347881	Mastick Senior Center & Grounds	Conference Space	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
347882	Mastick Senior Center & Grounds	Conference Space	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$500
347883	Mastick Senior Center & Grounds	Entrance Door	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
347884	Mastick Senior Center & Grounds	Entrance Door	Signage	2	Means of egress signage does not have tactile lettering.	\$55
347886	Mastick Senior Center & Grounds	Conference Space	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$125
348014	Mastick Senior Center & Grounds	Kiln Room	Door	2	The pull side of the accessible door does not have the required maneuvering clearances.	\$125

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
348005	Mastick Senior Center & Grounds	Entrance Doors	Signage	2	Means of egress signage does not have tactile lettering.	\$110
348006	Mastick Senior Center & Grounds	Classroom Area	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$125
348008	Mastick Senior Center & Grounds	Classroom Area	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$500
348009	Mastick Senior Center & Grounds	Sink	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$125
348010	Mastick Senior Center & Grounds	Kiln Room	Door	2	The push side of the accessible door does not have the required maneuvering clearances.	\$125
348011	Mastick Senior Center & Grounds	Sink	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	\$65
348012	Mastick Senior Center & Grounds	Sink	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$125
347901	Mastick Senior Center & Grounds	Kitchen	Sink	2	Exposed pipes lack insulation and/or sharp or abrasive surfaces are present under the sink.	\$65
347800	Mastick Senior Center & Grounds	Egress Doors	Building Entrance - Door	2	Means of egress signage does not have tactile lettering.	\$330
347801	Mastick Senior Center & Grounds	Activities Area	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
347805	Mastick Senior Center & Grounds	Activities Area	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$625
347807	Mastick Senior Center & Grounds	Activities Area	Protruding Object	2	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
347808	Mastick Senior Center & Grounds	Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$2,000
347809	Mastick Senior Center & Grounds	Activities Area	Service Counter	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$1,805

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347810	Mastick Senior Center & Grounds	Activities Area	Exterior Accessible Route	2	A compliant accessible route is not provided from the public access to the amenity.	\$1,792
347887	Mastick Senior Center & Grounds	Aisles	Interior Access Route	2	CALIFORNIA: The width of the aisle is not compliant.	\$1,250
347888	Mastick Senior Center & Grounds	Dressing Room	Door	2	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
347889	Mastick Senior Center & Grounds	Dressing Room	Door	2	The door has less than 32" clear width.	\$2,600
347890	Mastick Senior Center & Grounds	Dressing Room	Door	2	The required turning space within the dressing room is not provided.	\$9,250
347891	Mastick Senior Center & Grounds	Dressing Room	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$125
347892	Mastick Senior Center & Grounds	Dressing Room	Restroom/Bathroom-Locker	2	The dressing area does not have a compliant bench.	\$1,000
347894	Mastick Senior Center & Grounds	Egress Doors	Signage	2	Means of egress signage does not have tactile lettering.	\$330
347897	Mastick Senior Center & Grounds	Main Entrance Door	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$800
347898	Mastick Senior Center & Grounds	Main Entrance Door	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$125
347979	Mastick Senior Center & Grounds	Entrance Doors	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$2,200
347980	Mastick Senior Center & Grounds	Kitchen	Interior Access Route	2	CALIFORNIA: The service counter does not have 36" long section that is 34" maximum above finished floor that is oriented for a parallel approach, or the service counter does not have a 36" long section that is 34" maximum above the finished floor, with knee and toe clearance oriented for a forward approach.	\$1,805
347981	Mastick Senior Center & Grounds	Kitchen	Interior Access Route	2	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
347982	Mastick Senior Center & Grounds	Egress Doors	Interior Access Route	2	Means of egress signage does not have tactile lettering.	\$605

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347983	Mastick Senior Center & Grounds	Kitchen	Door	2	The push side of the accessible door does not have the required maneuvering clearances.	\$125
347984	Mastick Senior Center & Grounds	Kitchen	Interior Access Route	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$125
347988	Mastick Senior Center & Grounds	Room D	Interior Access Route	2	CALIFORNIA: The dining or work surface is not compliant.	\$1,000
347908	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
347909	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
347910	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
347911	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
347912	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	\$1,124
347913	Mastick Senior Center & Grounds	Lower Level Restroom	Door	3	The accessible door has less than 80" head clearance (excluding closer and door stop).	\$2,600
347915	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required knee clearance.	\$720
347916	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 35" above finish floor to the bottom of the reflective surface, where it is not installed above a lavatory or counter.	\$200
347917	Mastick Senior Center & Grounds	Lower Level Restroom	Restroom/Bathroom - Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	\$2,750
347989	Mastick Senior Center & Grounds	Exterior Signs	Exterior Accessible Route-Signage	3	The signage with raised characters is not compliant.	\$1,650
347845	Mastick Senior Center & Grounds	Patio at Social Hall	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
347927	Mastick Senior Center & Grounds	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347934	Mastick Senior Center & Grounds	Courtyard	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
347936	Mastick Senior Center & Grounds	Picnic Area at Skills Center	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
297769	Mastick Senior Center & Grounds	Women's Restroom	Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297770	Mastick Senior Center & Grounds	Men's and Women's Restroom	Restroom/Bathroom-Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$732
297786	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
297787	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	\$280
297794	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Water Closet	3	The space between the grab bar and projecting objects below and at the ends of the bar is less than 1-1/2".	\$100
296371	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$293
296372	Mastick Senior Center & Grounds	Women's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$500
296373	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$293
296369	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
296350	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Door	3	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$116
296351	Mastick Senior Center & Grounds	Women's Restroom	Building Entrance-Door	3	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
305406	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	\$1,100
347951	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required knee clearance.	\$720

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347952	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
347953	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
347954	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	\$1,100
347955	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required knee clearance.	\$720
347956	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
347958	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
347959	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
347960	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
347969	Mastick Senior Center & Grounds	Staff Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
347970	Mastick Senior Center & Grounds	Staff Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
347971	Mastick Senior Center & Grounds	Staff Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width	\$1,124
347972	Mastick Senior Center & Grounds	Staff Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
347973	Mastick Senior Center & Grounds	Staff Restroom	Restroom/Bathroom - Door	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
347975	Mastick Senior Center & Grounds	Main Lobby Building	Exterior Accessible Route-Signage	3	The signage with raised characters is not compliant.	\$300
297774	Mastick Senior Center & Grounds	Women's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297776	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
297778	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
297780	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$293
297789	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$794
297790	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
297791	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$293
297792	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
296364	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	\$280
296365	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
347799	Mastick Senior Center & Grounds	Main Entrance Door	Exterior Accessible Route-Signage	3	The signage with raised characters is not compliant.	\$150
347804	Mastick Senior Center & Grounds	Activities Area	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
347811	Mastick Senior Center & Grounds	Restroom Hall	Door	3	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
347812	Mastick Senior Center & Grounds	Restroom Hall	Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
347813	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
347814	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required knee clearance.	\$720

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347815	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
347816	Mastick Senior Center & Grounds	Women's Restroom	Controls And Dispensers	3	Controls on dispensers are not compliant.	\$200
347817	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
347818	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
347819	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$794
347820	Mastick Senior Center & Grounds	Women's Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
347821	Mastick Senior Center & Grounds	Restroom Hall	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$5,439
347823	Mastick Senior Center & Grounds	Restroom Hall	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
347824	Mastick Senior Center & Grounds	Men's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$250
347825	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required knee clearance.	\$720
347826	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
347827	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
347828	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
347829	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347830	Mastick Senior Center & Grounds	Men's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
347832	Mastick Senior Center & Grounds	Restroom Hall	Door	3	The door or gate in an recess greater than 8" deep does not have the required maneuvering clearances.	\$2,083
347833	Mastick Senior Center & Grounds	Restroom Hall	Door	3	CALIFORNIA: Maneuvering clearance at the door is not level and clear.	\$1,250
347834	Mastick Senior Center & Grounds	Unisex Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
347835	Mastick Senior Center & Grounds	Unisex Restroom	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
347836	Mastick Senior Center & Grounds	Unisex Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
347837	Mastick Senior Center & Grounds	Unisex Restroom	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
347838	Mastick Senior Center & Grounds	Unisex Restroom	Restroom/Bathroom - Door	3	The door has less than 32" clear width.	\$1,124
347839	Mastick Senior Center & Grounds	Unisex Restroom	Restroom/Bathroom - Door	3	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400
347840	Mastick Senior Center & Grounds	Unisex Restroom	Restroom/Bathroom - Floor Space	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
347900	Mastick Senior Center & Grounds	Main Entrance Door	Exterior Accessible Route-Signage	3	The signage with raised characters is not compliant.	\$150
347977	Mastick Senior Center & Grounds	Exterior Signs	Exterior Accessible Route-Signage	3	The signage with raised characters is not compliant.	\$1,650
347914	Mastick Senior Center & Grounds	Lower Level Restroom	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls and outlets are not compliant.	\$625
347866	Mastick Senior Center & Grounds	Storages/Closets/Laundry Room	Exterior Accessible Route-Signage	4	Signage identifying the name of a permanent indoor or outdoor space does not have raised lettering and/or visual characters.	\$1,120
347996	Mastick Senior Center & Grounds	Electrical Controls	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls and outlets are not compliant.	\$6,250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296370	Mastick Senior Center & Grounds	Drinking Fountain DF-2	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	\$125
297771	Mastick Senior Center & Grounds	Parking Lot	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
347867	Mastick Senior Center & Grounds	Stair ST-1	Stairs	4	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
347868	Mastick Senior Center & Grounds	Stair ST-2	Stairs	4	CALIFORNIA: Handrails are not compliant or are not provided.	\$6,520
347879	Mastick Senior Center & Grounds	Stair ST-3	Stairs	4	CALIFORNIA: Handrails are not compliant or are not provided.	\$3,260
347939	Mastick Senior Center & Grounds	Stair ST-4	Stairs	4	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
347942	Mastick Senior Center & Grounds	Stair ST-5	Stairs	4	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
347943	Mastick Senior Center & Grounds	Stair ST-6	Stairs	4	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
347965	Mastick Senior Center & Grounds	Electrical Controls	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls and outlets are not compliant.	\$3,750
347885	Mastick Senior Center & Grounds	Conference Space	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls and outlets are not compliant.	\$625
348002	Mastick Senior Center & Grounds	Entrance Door	Exterior Accessible Route-Signage	4	The signage with raised characters is not compliant.	\$150
347902	Mastick Senior Center & Grounds	Kitchen	Controls And Dispensers	4	Controls and/or dispensers are not within an allowable reach range.	\$1,098
347802	Mastick Senior Center & Grounds	Activities Area	Drinking Fountain/Water Cooler	4	The location of the spout of the wheelchair height drinking fountain is not compliant.	\$2,505
347803	Mastick Senior Center & Grounds	Activities Area	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	\$980

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
347806	Mastick Senior Center & Grounds	Electrical Controls	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls and outlets are not compliant.	\$3,125
347822	Mastick Senior Center & Grounds	Restroom Hall	Drinking Fountain/Water Cooler	4	Knee and toe clearance is not provided at the lower level fountain.	\$980
347895	Mastick Senior Center & Grounds	Electrical Controls	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls and outlets are not compliant.	\$2,500
347985	Mastick Senior Center & Grounds	Electrical Controls	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls and outlets are not compliant.	\$5,000
348001	Mastick Senior Center & Grounds	Offices	Door	5	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
296890	McKinley Park & Recreation Center	Asphalt Walkway throughout Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$8,000
296891	McKinley Park & Recreation Center	Asphalt Walkway throughout Park	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$0
296892	McKinley Park & Recreation Center	Asphalt Walkway throughout Park	Exterior Accessible Route	1	The accessible route has running slopes greater than 1:20 (5%).	\$0
296893	McKinley Park & Recreation Center	Asphalt Walkway throughout Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$0
305075	McKinley Park & Recreation Center	Play Area	Stairs	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$422
305078	McKinley Park & Recreation Center	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
296852	McKinley Park & Recreation Center	Recreation Center - Main Entrance	Building Entrance - Door	1	The maneuvering clearance at the accessible door is not level and clear.	\$1,250
296853	McKinley Park & Recreation Center	Recreation Center - Main Entrance	Building Entrance - Door	1	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
296854	McKinley Park & Recreation Center	Recreation Center - Main Entrance	Building Entrance - Door	1	The non-fire, automatic accessible door requires more than 5 pounds of pressure to operate.	\$366
296855	McKinley Park & Recreation Center	Recreation Center - Main Entrance	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296866	McKinley Park & Recreation Center	Recreation Center - Lower Classroom	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750
296887	McKinley Park & Recreation Center	Play Area	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$1,000
296888	McKinley Park & Recreation Center	Play Area	Play Component - Swing	2	A turning space is not provided at a preschool swing.	\$1,500
296889	McKinley Park & Recreation Center	Picnic Area	Operable Part	2	Clear floor space is not provided at the operable part.	\$238
305076	McKinley Park & Recreation Center	Play Area	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	\$5,000
296856	McKinley Park & Recreation Center	Recreation Center - Elevated Classroom	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$326
296857	McKinley Park & Recreation Center	Recreation Center - Elevated Classroom Kitchen	Sink	2	The sink rim is higher than 34", and does not have knee and toe clearance (does not apply to mop basins, utility sinks, or bar sinks).	\$720
296858	McKinley Park & Recreation Center	Recreation Center - Elevated Classroom Kitchen	Work Surface	2	The work surface height is not compliant. Knee and toe clearances are not provided.	\$1,000
296859	McKinley Park & Recreation Center	Recreation Center - Elevated Classroom Kitchen	Controls And Dispensers	2	Controls and/or dispensers are not within an allowable reach range.	\$2,196
296860	McKinley Park & Recreation Center	Recreation Center - Main Entrance	Signage	2	Means of egress signage does not have tactile lettering.	\$55
296864	McKinley Park & Recreation Center	Recreation Center - Lower Classroom	Signage	2	Means of egress signage does not have tactile lettering.	\$55
296865	McKinley Park & Recreation Center	Recreation Center - Lower Classroom	Building Entrance - Door	2	The non-fire, automatic accessible door requires more than 5 pounds of pressure to operate.	\$366
305073	McKinley Park & Recreation Center	Recreation Center - Lower Classroom	Operable Part	2	Clear floor space is not provided at the operable part.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
305074	McKinley Park & Recreation Center	Recreation Center - Elevated Classroom	Stairs	2	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$70
296894	McKinley Park & Recreation Center	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
296868	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom-Signage	3	The restroom does not compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$120
296869	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom-Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
296870	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
296871	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
296872	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
296873	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	\$720
296874	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom-Unisex	3	The slope of the floor surface is greater than 2% cross or 5% running	\$450
296875	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
296876	McKinley Park & Recreation Center	All Gender Restroom RR-1	Building Entrance-Door	3	The non-fire, automatic accessible door requires more than 5 pounds of pressure to operate.	\$366
296877	McKinley Park & Recreation Center	All Gender Restroom RR-1	Building Entrance-Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$732
296878	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom-Signage	3	The restroom does not compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$120
296879	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
296880	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	\$720
296881	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
296882	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
296883	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom-Unisex	3	The slope of the floor surface is greater than 2% cross or 5% running	\$450
296884	McKinley Park & Recreation Center	All Gender Restroom RR-2	Controls And Dispensers	3	The height of controls are not compliant.	\$200
296885	McKinley Park & Recreation Center	All Gender Restroom RR-2	Restroom/Bathroom-Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$586
296886	McKinley Park & Recreation Center	All Gender Restroom RR-1	Restroom/Bathroom-Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
305077	McKinley Park & Recreation Center	All Gender Restrooms RR-1/RR-2	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$626
300338	O'Club	Throughout	Amenity Not Evaluated	0	The amenity is an employee space and, therefore, will not be evaluated.	\$0
300803	O'Club	Stairs ST-2	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$106
300804	O'Club	Stairs ST-2	Stairs	1	Treads have slopes greater than 1:48.	\$77
300805	O'Club	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$106
300806	O'Club	Stairs ST-1	Stairs	1	Treads have slopes greater than 1:48.	\$1,530
301013	O'Club	Stairs ST-4 at Main Dining Room	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$282

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300971	O'Club	Stairs ST-3 at Rose Garden Room	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$282
300382	O'Club	Stairs ST-4 at Main Dining Room	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$4,890
300359	O'Club	Stairs ST-3 at Rose Garden Room	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$1,956
300334	O'Club	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,972
300335	O'Club	Stairs ST-2	Stairs	1	Handrails are not compliant.	\$1,956
300336	O'Club	Accessible Parking Space P1-B	Parking Space - General	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
300337	O'Club	Accessible Parking Space P1-B	Parking Space - General	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
300339	O'Club	Rose Garden	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$7,928
300340	O'Club	Sidewalk near CR-2	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$79
300341	O'Club	Sidewalk near Curb Ramp CR-2	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
300342	O'Club	Sidewalk near CR-2	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$20
300343	O'Club	Walkway from CR-2 to R-1	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$20
300344	O'Club	Ramp R-1	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	\$18,536
300345	O'Club	Ramp R-1	Ramp	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$840
300346	O'Club	Ramp R-1	Ramp	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$119
300347	O'Club	Stairs ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$1,304
300325	O'Club	Curb Ramp CR-2	Curb Ramp - Perpendicular	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300326	O'Club	Parking Lot	Parking Space - General	1	The minimum number of accessible parking spaces is not provided.	\$23,200
300327	O'Club	Accessible Parking Space P1-B	Exterior Accessible Route	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
300350	O'Club	Walkway from Accessible Parking	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$159
317570	O'Club	Curb Ramp CR-1 and CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$1,344
317573	O'Club	Accessible Parking Space P1-A	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
317574	O'Club	Accessible Parking Space P1-A	Parking Space-Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$420
317575	O'Club	Accessible Parking Space P1-A	Parking Space-Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$11,300
317576	O'Club	Accessible Parking Space P1-B	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$420
321035	O'Club	Accessible Parking Space P1-A	Parking Space - General	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
301012	O'Club	Room adjacent to Main Dining Room	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
300383	O'Club	Dressing Room	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
300384	O'Club	Entry Door	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300385	O'Club	Entry Door	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300386	O'Club	Entry Door	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
300390	O'Club	Women's Restroom	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300367	O'Club	Men's Restroom	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
300370	O'Club	Main Dining Room	Assembly Area	1	A direct accessible route is not provided from the assembly seating area to a performance area.	\$12,000
300372	O'Club	Room adjacent to Main Dining Room	Interior Accessible Route	1	The interior accessible route has non-compliant slopes.	\$4,912
300376	O'Club	Trident Room 325 seats	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
300378	O'Club	Trident Room 325 seats	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
300379	O'Club	Trident Room 325 seats	Floor Surface	1	Gaps in the walking surface are over 1/2" wide, or elongated gaps are not perpendicular to the path of travel.	\$500
300381	O'Club	Entry Door	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
300351	O'Club	Throughout Building	Door	1	The hardware at the accessible door (including sliding doors - both sides) requires tight grasping, pinching or twisting of the wrist to operate OR is mounted below 34" or above 48".	\$2,051
300349	O'Club	Lobby	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$100
317587	O'Club	Main Dining Room	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$3,260
317588	O'Club	Main Dining Room	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$352
321037	O'Club	Exterior Patio	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$7,928
300807	O'Club	Entry Door	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	\$500
301009	O'Club	Women's Restroom	Protruding Object	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$93

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
301010	O'Club	Men's Restroom	Restroom/Bathroom-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400
300371	O'Club	Main Dining Room	Signage	2	Means of egress exit signs do not have tactile lettering.	\$110
300373	O'Club	Main Dining Room	Assembly Area	2	The assistive listening device is not compliant or is not provided.	\$3,750
300374	O'Club	Room adjacent to Main Dining Room	Signage	2	Means of egress exit signs do not have tactile lettering.	\$110
300375	O'Club	Trident Room 325 seats	Signage	2	Means of egress exit signs do not have tactile lettering.	\$220
300377	O'Club	Trident Room 325 seats	Reach Range	2	Items requiring an unobstructed side reach motion are higher than 48" maximum and/or lower than 15" minimum height above finish floor.	\$400
300380	O'Club	Main Dining Room	Door	2	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$800
300329	O'Club	Entry Door	Building Entrance-Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
300331	O'Club	Squadron Room	Dining And Work Surface	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	\$1,805
300333	O'Club	Lobby	Service Counter	2	The service counter height is greater than 36" and/or the counter length is less than 36", where a parallel approach is present.	\$1,805
300355	O'Club	Lobby	Door	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
300356	O'Club	Lobby	Door	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
300358	O'Club	Terrace Room / Rose Garden Room Exit to Stair-3	Door	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$110
300348	O'Club	Entry Door	Building Entrance	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
300801	O'Club	Entry Door	Building Entrance-Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$400

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
317589	O'Club	Dressing Room	Assembly Area	2	An accessible route does not connect the assembly area wheelchair spaces with performing areas.	\$12,000
301006	O'Club	Women's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$400
301008	O'Club	Women's Restroom	Restroom/Bathroom-Lavatory	3	The lavatory faucet hardware is not compliant.	\$555
300972	O'Club	Unisex Restroom	Restroom/Bathroom-Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
300973	O'Club	Unisex Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
300974	O'Club	Unisex Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
300975	O'Club	Women's Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
300979	O'Club	Women's Restroom	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
300980	O'Club	Women's Restroom	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
300981	O'Club	Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA- The water closet does not have the required clear floor space.	\$1,100
300387	O'Club	Unisex Restroom	Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
300388	O'Club	Unisex Restroom	Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300389	O'Club	Women's Restroom	Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
300391	O'Club	Men's Restroom	Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
300393	O'Club	Men's Restroom	Door	3	The threshold at the accessible door is greater than ½" in height.	\$179
300360	O'Club	Unisex Restroom	Restroom/Bathroom - Floor Space	3	The water closet in a single user / unisex restroom does not have the required clearance.	\$1,368
300361	O'Club	Women's Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300362	O'Club	Unisex Restroom	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
300363	O'Club	Women's Restroom	Restroom/Bathroom-Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
300364	O'Club	Women's Restroom	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
300365	O'Club	Men's Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	\$935
300366	O'Club	Men's Restroom	Restroom/Bathroom-Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
300368	O'Club	Main Dining Room	Exterior Accessible Route	3	The amenity is not located on an accessible route.	\$12,000
317578	O'Club	Men's Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
317579	O'Club	Men's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$93
317580	O'Club	Men's Restroom	Restroom/Bathroom-Toilet Stall	3	A wheelchair stall is not provided in a multi-user restroom.	\$2,750
317581	O'Club	Women's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
317582	O'Club	Women's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
317583	O'Club	Men's Restroom	Restroom/Bathroom-Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	\$720
317584	O'Club	Men's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
317585	O'Club	Men's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
317586	O'Club	Unisex Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
321036	O'Club	Dressing Room	Locker and Dressing Rooms	3	The locker room does not have a compliant bench.	\$789
321038	O'Club	Women's Restroom	Restroom/Bathroom-Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
317572	O'Club	Parking Lot	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
300352	O'Club	Squadron Room	Controls And Dispensers	4	CALIFORNIA: The location of electrical outlets are not compliant.	\$1,000
300353	O'Club	Squadron Room	Controls And Dispensers	4	CALIFORNIA: The location of electrical controls are not compliant.	\$500
300354	O'Club	Lobby	Controls And Dispensers	4	CALIFORNIA: The location of electrical outlets are not compliant.	\$2,500
429765	Parking Lot "A" - Park Avenue	Access Aisle serving P1-A	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$6,250
429766	Parking Lot "A" - Park Avenue	Access Aisle serving P1-A	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$525
429767	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-A	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$350
429768	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$350
429770	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$350
429772	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$7,875
429773	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$525
429774	Parking Lot "A" - Park Avenue	Access Aisle serving P1-B	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$525

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
429775	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$7,875
429776	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$525
429777	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$525
429778	Parking Lot "A" - Park Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$525
429779	Parking Lot "A" - Park Avenue	Access Aisle serving P1-C	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$525
429780	Parking Lot "A" - Park Avenue	Parking Lot	Parking Space - General	1	The minimum number of accessible parking spaces is not provided.	\$525
429764	Parking Lot "A" - Park Avenue	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$350
429746	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$350
429747	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-B	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$350
429748	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$7,875
429749	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$7,875
429750	Parking Lot "C" - Alameda Avenue	Access Aisle serving P1-A and P1-B	Parking Space-Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$6,250
429751	Parking Lot "C" - Alameda Avenue	Access Aisle serving P1-A and P1-B	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$525
429754	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-A	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$525

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
429755	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$525
429756	Parking Lot "C" - Alameda Avenue	Access Aisle serving P1-C	Parking Space - Car	1	CALIFORNIA: The car aisle markings are not compliant.	\$525
429757	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$525
429759	Parking Lot "C" - Alameda Avenue	Access Aisle serving P1-C	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$6,250
437182	Parking Lot "C" - Alameda Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$7,875
437183	Parking Lot "C" - Alameda Avenue	Parking Space adjacent to P1-C	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$525
429744	Parking Lot "C" - Alameda Avenue	Entrance at Alameda St.	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$350
429745	Parking Lot "C" - Alameda Avenue	Entrance at Central Ave.	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$350
429725	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$525
429726	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$7,875
429727	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$350
429728	Parking Lot "W" - 700 Block Haight Avenue	Access Aisle serving P1-A and P1-B	Parking Space-Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$6,250
429729	Parking Lot "W" - 700 Block Haight Avenue	Access Aisle serving P1-A and P1-B	Parking Space-Van	1	CALIFORNIA: The van aisle markings are not compliant.	\$525
429731	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$525

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
429732	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$7,875
429733	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$350
429736	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$525
429737	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$7,875
429738	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	An access aisle is not provided.	\$525
429739	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$350
437184	Parking Lot "W" - 700 Block Haight Avenue	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$525
429722	Parking Lot "W" - 700 Block Haight Avenue	Haight Avenue Entrance	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$350
429723	Parking Lot "W" - 700 Block Haight Avenue	Santa Clara Avenue Entrance	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$350
294523	Police Station	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
294524	Police Station	Access Aisle Serving P1-A	Parking Space - Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294525	Police Station	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294526	Police Station	Accessible Parking Space P1-A	Parking Space - Van	1	CALIFORNIA: The van parking stall is less than 108" wide.	\$420
294527	Police Station	Access Aisle Serving P1-A	Parking Space - Van	1	CALIFORNIA: The van parking aisle is less than 96" wide, where the van stall is less than 144" wide.	\$420

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294530	Police Station	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
294531	Police Station	Access Aisle Serving P1-B and P1-C	Parking Space - Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294532	Police Station	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
294533	Police Station	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: The car parking stall is less than 108" wide.	\$420
294534	Police Station	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: The car parking stall is less than 108" wide.	\$420
294538	Police Station	Accessible Parking Space P1-B	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
294539	Police Station	Accessible Parking Space P1-C	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
294447	Police Station	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$9,018
294448	Police Station	Sidewalk	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$20
294449	Police Station	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,964
294450	Police Station	Curb Ramp CR-1	Curb Ramp	1	The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289
294451	Police Station	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,955
294513	Police Station	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$352
294515	Police Station	Stairs ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$815
294516	Police Station	Stairs ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$815

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294517	Police Station	Lobby	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$432
294518	Police Station	Ramp R-1	Ramp	1	Handrails are not provided where the ramp rises more than 6" or are not compliant.	\$9,454
294519	Police Station	Ramp R-1	Ramp	1	The handrail height is not compliant.	\$1,630
294520	Police Station	Ramp R-1	Ramp	1	The ramp has a running slope in excess of 1:12 (8.33%) and/or cross slope in excess of 1:48 (2.08%).	\$17,874
294521	Police Station	Memorial	Exterior Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$744
294522	Police Station	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,016
294535	Police Station	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
294536	Police Station	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
294537	Police Station	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289
294540	Police Station	Curb Ramp CR-2	Curb Ramp	1	Curb ramp is not wholly within the marked crossing.	\$350
294492	Police Station	Lobby	Floor Surface	1	The edges of the carpet are not securely attached.	\$54
294497	Police Station	Room 102	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294498	Police Station	Room 102	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294499	Police Station	Room 102	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$100
294500	Police Station	Room 102	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
294502	Police Station	Room 103	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294503	Police Station	Room 103	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294504	Police Station	Room 103	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294507	Police Station	Room 104	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294508	Police Station	Room 104	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
294509	Police Station	Room 104	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
294510	Police Station	Lobby 1	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294511	Police Station	Lobby 2	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294512	Police Station	Lobby 1	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294462	Police Station	Unisex Restroom 1	Restroom/Bathroom - Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar, which can be 78" minimum.	\$2,600
294514	Police Station	Stairs ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$326
294493	Police Station	Lobby	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	\$93
294494	Police Station	Lobby	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	\$7,218
294495	Police Station	Records	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	\$3,008
294496	Police Station	Lobby	Reach Range	2	Items that require a forward reach motion require more than 48" height reach.	\$500
294501	Police Station	Room 102	Reach Range	2	Items requiring an unobstructed forward reach motion are higher than 48" maximum or lower than 15" minimum height above finish floor.	\$500
294505	Police Station	Room 104	Counter	2	The sales or service counter does not have an accessible portion with maximum 36" height surface above finish floor or ground.	\$3,008
294506	Police Station	Room 104	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
294488	Police Station	Lobby	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294489	Police Station	Lobby	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$5,439
294452	Police Station	Unisex Restroom 1	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
294453	Police Station	Unisex Restroom 1	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294454	Police Station	Unisex Restroom 1	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
294455	Police Station	Unisex Restroom 1	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
294456	Police Station	Unisex Restroom 1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$600
294457	Police Station	Unisex Restroom 1	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
294458	Police Station	Unisex Restroom 1	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
294459	Police Station	Unisex Restroom 1	Restroom/Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	\$720
294460	Police Station	Unisex Restroom 1	Restroom/Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	\$555
294461	Police Station	Unisex Restroom 1	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
294463	Police Station	Unisex Restroom 1	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
294464	Police Station	Unisex Restroom 1	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	\$1,250
294465	Police Station	Unisex Restroom 1	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294466	Police Station	Unisex Restroom 1	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294467	Police Station	Unisex Restroom 1	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
294468	Police Station	Unisex Restroom 1	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
294469	Police Station	Unisex Restroom 1	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
294470	Police Station	Unisex Restroom 2	Restroom/Bathroom - Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
294471	Police Station	Unisex Restroom 2	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
294472	Police Station	Unisex Restroom 2	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
294473	Police Station	Unisex Restroom 2	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
294474	Police Station	Unisex Restroom 2	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
294475	Police Station	Unisex Restroom 2	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	\$1,250
294476	Police Station	Unisex Restroom 2	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
294477	Police Station	Unisex Restroom 2	Restroom/Bathroom-Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
294478	Police Station	Unisex Restroom 2	Restroom/Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	\$555
294479	Police Station	Unisex Restroom 2	Restroom/Bathroom - Lavatory	3	The lavatory is mounted higher than 34" to the higher of the rim or counter.	\$720
294480	Police Station	Unisex Restroom 2	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294481	Police Station	Unisex Restroom 2	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
294482	Police Station	Unisex Restroom 2	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
294483	Police Station	Unisex Restroom 2	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
294484	Police Station	Unisex Restroom 2	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294485	Police Station	Unisex Restroom 2	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
294486	Police Station	Unisex Restroom 2	Restroom/Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	\$630
294487	Police Station	Unisex Restroom 1	Restroom/Bathroom - Water Closet	3	The height of the water closet is not 17" minimum to 19" maximum above finished floor.	\$630
294528	Police Station	Parking Lot	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
294490	Police Station	Lobby	Drinking Fountain/Water Cooler	4	The spout and/or water flow of the lower level drinking fountain is not compliant.	\$2,505
294491	Police Station	Lobby	Drinking Fountain/Water Cooler	4	The location of the spout of the wheelchair height drinking fountain is not compliant.	\$2,505
298870	Recreation & Park Admin Building	Employee Unisex Restrom	Amenity Not Evaluated	0	The amenity is not used by members of the public.	\$0
291603	Recreation & Park Admin Building	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$1,056
291604	Recreation & Park Admin Building	Stairs ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$6,520

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291605	Recreation & Park Admin Building	Walkway to R-1 from Santa Clara Ave	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,189
291606	Recreation & Park Admin Building	Walkway to R-1 from Santa Clara Ave	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$33,694
291607	Recreation & Park Admin Building	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: The parking stall is less than the required minimum length of 216" (18').	\$420
291608	Recreation & Park Admin Building	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	\$840
291609	Recreation & Park Admin Building	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
291610	Recreation & Park Admin Building	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,972
291612	Recreation & Park Admin Building	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,972
298373	Recreation & Park Admin Building	Ramp R-1	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	\$13,040
291613	Recreation & Park Admin Building	Rear Entrance Door	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
291614	Recreation & Park Admin Building	Rear Entrance Door	Building Entrance - Door	1	The accessible door has less than 32" clear width.	\$2,480
291615	Recreation & Park Admin Building	Rear Entrance Door	Building Entrance - Door	1	The threshold at the accessible door is raised; however the ends are not beveled.	\$179
291619	Recreation & Park Admin Building	Front Lobby Room	Door	1	The door has less than 32" clear width.	\$2,600
291620	Recreation & Park Admin Building	Front Entrance Door	Building Entrance - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
291621	Recreation & Park Admin Building	Front Entrance Door	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291622	Recreation & Park Admin Building	Rear Entrance Door	Building Entrance - Door	2	CALIFORNIA: The accessible entrance does not have signage with the International Symbol of Accessibility, in the existing building where not all entrances are accessible.	\$55
291642	Recreation & Park Admin Building	Rear Entrance Door	Signage	2	Means of egress signage does not have tactile lettering.	\$55
291623	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
291624	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
291625	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
291626	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
291627	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
291628	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
291629	Recreation & Park Admin Building	Women's Restroom	Controls And Dispensers	3	Controls on dispensers are not compliant.	\$200
291630	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	\$1,250
291631	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
291632	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
291633	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
291634	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
291635	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
291636	Recreation & Park Admin Building	Men's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
291637	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
291638	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
291639	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Door	3	The push side of the door does not have the required maneuvering clearances.	\$1,250
291640	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
291641	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
298370	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	\$1,100
298371	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
298372	Recreation & Park Admin Building	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
298374	Recreation & Park Admin Building	Women's Restroom	Reach Range	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
298375	Recreation & Park Admin Building	Women's Restroom	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
298376	Recreation & Park Admin Building	Men's and Women's Restroom	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$586
298377	Recreation & Park Admin Building	Men's and Women's Restroom	Restroom/Bathroom-Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$400

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
298378	Recreation & Park Admin Building	Parking Lot	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
291618	Recreation & Park Admin Building	Rear Entrance Door	Building Entrance-Door	5	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
291617	Recreation & Park Admin Building	Rear Entrance Door	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
306420	Rittler Park	Baseball Field 1 and 2	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$143
298419	Rittler Park	Walkway from Grand Street to Baseball Fields	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,973
298420	Rittler Park	Walkway from Grand Street to Baseball Fields	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$6,937
298421	Rittler Park	Baseball Field 2	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
298422	Rittler Park	Baseball Field 2	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
298423	Rittler Park	Baseball Field 1	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
298424	Rittler Park	Baseball Field 1	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$52
436968	Seaplane Ferry Terminal	Stairs ST-1	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas at bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$3,360
436969	Seaplane Ferry Terminal	Passenger Loading Zone	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas at bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$29,400
430277	Seaplane Ferry Terminal	Blended Transition BT-1, BT-2, BT-3, BT-4, and BT-5	Blended Transition	1	CALIFORNIA: The blended transition does not have a compliant detectable warning.	\$4,200
430280	Seaplane Ferry Terminal	Electric Vehicle Charging Station EVCS-A	Parking Space-Van	1	CALIFORNIA: Existing signage at the electric vehicle charging station is not compliant.	\$350

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
436976	Seaplane Ferry Terminal	Electric Vehicle Charging Station EVCS-A	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
436977	Seaplane Ferry Terminal	Electric Vehicle Charging Station EVCS-B	Parking Space-Van	1	CALIFORNIA: Existing signage at the electric vehicle charging station is not compliant.	\$350
436979	Seaplane Ferry Terminal	Detectable Warnings at Parking Lot	Exterior Accessible Route	1	CALIFORNIA: The detectable warning for areas at bus stop, reflecting pool, hazardous vehicular area, or track crossing is not compliant.	\$5,040
436980	Seaplane Ferry Terminal	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$176
436866	Seaplane Ferry Terminal	South Walkway to Terminal	Operable Part	2	Clear floor space is not provided at the operable part.	\$297
430279	Seaplane Ferry Terminal	South Walkway to Terminal	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$10,000
430278	Seaplane Ferry Terminal	Path to Terminal	Signage	4	Directional signage indicating the accessible route from accessible parking to the facility is not provided, where existing routes are both accessible and non-accessible.	\$1,050
290404	Seaplane Lagoon Promenade	Bike Rack (east)	Exterior Accessible Route	1	CALIFORNIA: The slopes of the exterior accessible route are not compliant.	\$496
430255	Seaplane Lagoon Promenade	Path Connecting Public Right of Way to Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$396
430268	Seaplane Lagoon Promenade	Path Connecting Public Right of Way to Park	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$4,956
430272	Seaplane Lagoon Promenade	Western Picnic Area	Operable Part	2	Clear floor space is not provided at the operable part.	\$297

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
430276	Seaplane Lagoon Promenade	East Picnic Area	Operable Part	2	Clear floor space is not provided at the operable part.	\$297
430256	Seaplane Lagoon Promenade	Unisex Restroom RR-1	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$458
430257	Seaplane Lagoon Promenade	Unisex Restroom RR-1	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,750
430258	Seaplane Lagoon Promenade	Unisex Restroom RR-1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
430259	Seaplane Lagoon Promenade	Unisex Restroom RR-1	Restroom/Bathroom-Unisex	3	The slope of the floor surface is greater than 2% cross or 5% running	\$1,066
430260	Seaplane Lagoon Promenade	Unisex Restroom RR-2	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$458
430261	Seaplane Lagoon Promenade	Unisex Restroom RR-2	Restroom/Bathroom-Unisex	3	The slope of the floor surface is greater than 2% cross or 5% running	\$1,066
430262	Seaplane Lagoon Promenade	Unisex Restroom RR-2	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,750
430263	Seaplane Lagoon Promenade	Unisex Restroom RR-2	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
430264	Seaplane Lagoon Promenade	Unisex Restroom RR-2	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$350
430265	Seaplane Lagoon Promenade	Unisex Restroom RR-3	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$458
430266	Seaplane Lagoon Promenade	Unisex Restroom RR-3	Restroom/Bathroom-Unisex	3	The slope of the floor surface is greater than 2% cross or 5% running	\$1,066
430267	Seaplane Lagoon Promenade	Unisex Restroom RR-3	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$116
290400	Seaplane Lagoon Promenade	Stair ST-1	Stairs	4	CALIFORNIA: Handrails are not compliant or are not provided.	\$1,630
290401	Seaplane Lagoon Promenade	Stair ST-1	Stairs	4	Treads have slopes greater than 1:48.	\$15,300

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
290402	Seaplane Lagoon Promenade	Stairs ST-2, ST-3, ST-4	Stairs	4	Handrails are not compliant or are not provided.	\$4,890
430269	Seaplane Lagoon Promenade	Stairs ST-4	Stairs	4	CALIFORNIA: Handrails are not compliant or are not provided.	\$5,094
430274	Seaplane Lagoon Promenade	Decomposed Granite Walkways	Accessible Route	4	CALIFORNIA: The existing accessible feature is not in operable working condition.	\$0
300204	Shoreline Park & Bathrooms 1-4	Trail	Amenity Not Evaluated	0	The building amenity is evaluated under its separate building components.	\$0
306418	Shoreline Park & Bathrooms 1-4	On-Street Parking	Parking Space-General	1	An accessible parking space is not provided where an off-street parking facility is not provided.	\$1,120
306419	Shoreline Park & Bathrooms 1-4	Picnic Area 1, 2, and 3	Controls And Dispensers	1	Clear space is not provided at the control or operating mechanism.	\$1,290
300198	Shoreline Park & Bathrooms 1-4	Curb Ramp CR-1	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	\$1,750
300199	Shoreline Park & Bathrooms 1-4	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
300200	Shoreline Park & Bathrooms 1-4	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp landing is not level. The slope of the curb ramp landing exceeds the maximum allowable 1:48 (2.08%).	\$1,289
300201	Shoreline Park & Bathrooms 1-4	Sidewalk near CR-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$793
300202	Shoreline Park & Bathrooms 1-4	Sidewalk near CR-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$500
300203	Shoreline Park & Bathrooms 1-4	Sidewalk near CR-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$991
300206	Shoreline Park & Bathrooms 1-4	Picnic Area 1	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$717
300209	Shoreline Park & Bathrooms 1-4	Sidewalk near CR-1	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$79
300211	Shoreline Park & Bathrooms 1-4	Walkway to West Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,150

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300212	Shoreline Park & Bathrooms 1-4	Walkway to West Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$951
300238	Shoreline Park & Bathrooms 1-4	Walkway from Asphalt Path to West Restrooms	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$1,400
300239	Shoreline Park & Bathrooms 1-4	Picnic Area 2	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$717
300243	Shoreline Park & Bathrooms 1-4	Picnic Area 3	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,075
300205	Shoreline Park & Bathrooms 1-4	Picnic Area 1	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
300242	Shoreline Park & Bathrooms 1-4	Picnic Area 2	Picnic Table	2	The picnic table does not allow a clear space for forward wheelchair approach with knee and toe clearance.	\$1,300
306322	Shoreline Park & Bathrooms 1-4	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
300197	Shoreline Park & Bathrooms 1-4	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	Knee and toe clearance is not provided at the lower level fountain.	\$2,505
300179	Shoreline Park & Bathrooms 1-4	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
300235	Shoreline Park & Bathrooms 1-4	Drinking Fountain DF-2	Drinking Fountain/Water Cooler	3	CALIFORNIA: The drinking fountain is not located completely within alcoves, positioned completely between wing walls, or otherwise positioned so as not to encroach into pedestrian ways.	\$8,000
300236	Shoreline Park & Bathrooms 1-4	Drinking Fountain DF-2	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
300237	Shoreline Park & Bathrooms 1-4	Drinking Fountain DF-2	Drinking Fountain/Water Cooler	3	Knee and toe clearance is not provided at the lower level fountain.	\$2,505
300180	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300181	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
300182	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
300183	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
300184	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
300185	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
300186	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Water Closet	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$100
300187	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
300188	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	\$1,100
300189	Shoreline Park & Bathrooms 1-4	East Men's Restroom RR-1	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
300190	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
300191	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
300192	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
300193	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
300194	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
300195	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300196	Shoreline Park & Bathrooms 1-4	East Women's Restroom RR-2	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet stall door is not compliant.	\$1,100
300213	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
300214	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
300215	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
300216	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
300217	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Urinal	3	The urinal dimensions are not compliant.	\$935
300218	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
300219	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
300220	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Lavatory	3	The automatic faucet, when activated, does not remain on for minimum 10 seconds.	\$555
300221	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Lavatory	3	The lavatory does not have the required knee clearance.	\$720
300222	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
300223	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
300224	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
300225	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
300226	Shoreline Park & Bathrooms 1-4	West Men's Restroom RR-3	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300227	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
300228	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
300229	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
300230	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
300231	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
300232	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
300233	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Water Closet	3	The side grab bar at the water closet is not compliant.	\$355
300234	Shoreline Park & Bathrooms 1-4	West Women's Restroom RR-4	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The wheelchair stall with in-swinging door does not have the required dimensions.	\$1,100
294169	Tillman Park & Recreation Center	Rear Entrance	Building Entrance-Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
294172	Tillman Park & Recreation Center	Front Entrance	Building Entrance - Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
294178	Tillman Park & Recreation Center	Kitchen Entrance	Building Entrance - Door	1	CALIFORNIA: Maneuvering clearance at the exterior side of the pull door with frontal approach is not level and clear.	\$1,250
294167	Tillman Park & Recreation Center	Walkways throughout	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$9,910
294194	Tillman Park & Recreation Center	Walkway adjacent to Gazebo	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$793
294195	Tillman Park & Recreation Center	Gazebo	Ramp	1	CALIFORNIA: A ramp is required but not provided.	\$7,944
294202	Tillman Park & Recreation Center	Playground 2	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$5,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294204	Tillman Park & Recreation Center	Accessible picnic area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$396
302614	Tillman Park & Recreation Center	Gazebo	Ramp	1	CALIFORNIA: The exterior ramp railings are not compliant.	\$4,564
294168	Tillman Park & Recreation Center	Rear Entrance	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$200
294170	Tillman Park & Recreation Center	Rear Entrance	Signage	2	Means of egress signage does not have tactile lettering.	\$55
294171	Tillman Park & Recreation Center	Front Entrance	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
294173	Tillman Park & Recreation Center	Rear Entrance	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
294174	Tillman Park & Recreation Center	Front Entrance	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
294175	Tillman Park & Recreation Center	Kitchen	Kitchen-Residential And Employee-Only Counter	2	The height of the counter is greater than 34".	\$1,986
294193	Tillman Park & Recreation Center	Kitchen	Sink	2	The accessible sink is not installed with the front of the higher of the rim or counter surface 34" maximum above finished floor.	\$720
294196	Tillman Park & Recreation Center	Playground 1	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$650
294197	Tillman Park & Recreation Center	Playground 1	Transfer System	2	The elevated play structure does not have a transfer platform.	\$50,000
294198	Tillman Park & Recreation Center	Playground 1	Play Component-Swing	2	A turning space is not provided at a preschool swing.	\$0
294199	Tillman Park & Recreation Center	Playground 2	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$1,000
294203	Tillman Park & Recreation Center	Team Seating	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$87

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294176	Tillman Park & Recreation Center	Kitchen	Sink	3	CALIFORNIA: The sink does not have the required clear floor space of minimum 30" by minimum 48" for a forward approach with knee and toe clearance.	\$3,000
294177	Tillman Park & Recreation Center	Kitchen	Kitchen Cabinets	3	CA Kitchen Cabinets	\$8,365
294180	Tillman Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
294181	Tillman Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
294182	Tillman Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
294183	Tillman Park & Recreation Center	Women's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
294184	Tillman Park & Recreation Center	Women's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294185	Tillman Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
294187	Tillman Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
294188	Tillman Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
294189	Tillman Park & Recreation Center	Men's Restroom	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
294190	Tillman Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294191	Tillman Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Water Closet	3	Projecting object above the grab bar is less than 12" minimum above the bar.	\$200
294192	Tillman Park & Recreation Center	Men's Restroom	Restroom/Bathroom-Urinal	3	The clear floor space at the urinal is less than minimum 30" by minimum 48".	\$1,100
294217	Towata Park	Accessible Parking Space P-1A	Parking Space - Van	0	Maintenance of Accessible Features	\$0

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294206	Towata Park	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The parallel curb ramp is not compliant, or is required but not provided.	\$1,750
294207	Towata Park	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The parallel curb ramp is not compliant, or is required but not provided.	\$1,750
294208	Towata Park	Walkway from Public Way	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$250
294209	Towata Park	Walking Path	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$250
294213	Towata Park	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: The van parking stall markings are not compliant.	\$420
294215	Towata Park	Accessible Parking Space P-1A	Parking Space-Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$420
294216	Towata Park	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294219	Towata Park	Accessible Parking Space P-1B	Parking Space-Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
294221	Towata Park	Accessible Parking Space P-1B	Parking Space-Car	1	CALIFORNIA: The accessible route is located so that the disabled user is compelled to walk or wheel behind parked vehicles other than his or her own vehicle.	\$420
294222	Towata Park	Accessible Parking Space P-1B	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
294223	Towata Park	Accessible Parking Space P-1B	Parking Space-Car	1	CALIFORNIA: A car accessible stall and adjacent aisle are not provided.	\$840
294225	Towata Park	Walkway from P-1B to Scenic Walk	Curb Ramp	1	A curb ramp is not provided where the accessible route crosses a curb.	\$1,750
294226	Towata Park	Route from Parking to Waterfront	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$20
294228	Towata Park	Picnic Area	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$896
294229	Towata Park	Path between Picnic Area and Bridge	Accessible Route	1	CALIFORNIA: A warning curb is not provided on a walkway where the walkway edge is more than 4" above the adjacent surface.	\$7,200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294231	Towata Park	Path between Picnic Area and Bridge	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$1,254
294232	Towata Park	Shared Use Path between Picnic Area and Bridge	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$250
294234	Towata Park	Curb Ramp CR-3	Curb Ramp	1	CALIFORNIA: The curb ramp is non-compliant.	\$2,422
305079	Towata Park	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300
305080	Towata Park	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	\$840
305081	Towata Park	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
305082	Towata Park	Curb Ramp CR-2	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
305083	Towata Park	Curb Ramp CR-3	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$2,016
294227	Towata Park	Picnic Area	Picnic Table	2	CALIFORNIA: A compliant picnic table is not provided.	\$1,300
294210	Towata Park	Drinking Fountain DF-1	Drinking Fountain/Water Cooler	4	The minimum number and types of drinking fountains are not provided.	\$8,000
294224	Towata Park	Parking Lot	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
295868	Veterans Building & Grounds	210	Amenity Not Evaluated	0	The amenity is under construction and cannot be evaluated.	\$0
295931	Veterans Building & Grounds	184	Amenity Not Evaluated	0	The amenity cannot be accessed and, therefore, cannot be evaluated.	\$0
295792	Veterans Building & Grounds	315	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295793	Veterans Building & Grounds	315	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295794	Veterans Building & Grounds	315 Exit	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295795	Veterans Building & Grounds	315 Exit	Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
295823	Veterans Building & Grounds	380	Floor Surface	1	The edges of the carpet are not securely attached.	\$36
295826	Veterans Building & Grounds	ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$2,282
295827	Veterans Building & Grounds	ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$2,934
295828	Veterans Building & Grounds	ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$4,564
295829	Veterans Building & Grounds	ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$2,934
295848	Veterans Building & Grounds	250	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295849	Veterans Building & Grounds	250	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295853	Veterans Building & Grounds	250	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295854	Veterans Building & Grounds	250	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295855	Veterans Building & Grounds	250	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295856	Veterans Building & Grounds	250	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295857	Veterans Building & Grounds	250	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
295858	Veterans Building & Grounds	250	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
295859	Veterans Building & Grounds	250	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295864	Veterans Building & Grounds	220	Door	1	The threshold at the accessible door is greater than ½" in height.	\$179
295874	Veterans Building & Grounds	200	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
295889	Veterans Building & Grounds	120	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295892	Veterans Building & Grounds	121	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$100
295893	Veterans Building & Grounds	Main	Building Entrance - Floor Surface	1	The edges of the carpet are not securely attached.	\$36
295894	Veterans Building & Grounds	121	Door	1	CA The door lacks a level landing	\$1,178
295895	Veterans Building & Grounds	121	Floor Surface	1	The edges of the carpet are not securely attached.	\$1,800
295898	Veterans Building & Grounds	130	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295901	Veterans Building & Grounds	134	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
295904	Veterans Building & Grounds	134	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
295905	Veterans Building & Grounds	134	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295906	Veterans Building & Grounds	134	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295907	Veterans Building & Grounds	134	Door	1	CA The door lacks a level landing	\$1,178
295909	Veterans Building & Grounds	120	Door	1	CA The door lacks a level landing	\$1,178
295910	Veterans Building & Grounds	120	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295918	Veterans Building & Grounds	Exit Door at 155	Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
295919	Veterans Building & Grounds	Exit Door at 155	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$1,250
295920	Veterans Building & Grounds	Exit Door at 155	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295921	Veterans Building & Grounds	Exit Door at 155	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295926	Veterans Building & Grounds	180	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295927	Veterans Building & Grounds	180	Door	1	The door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
295929	Veterans Building & Grounds	180	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295932	Veterans Building & Grounds	180	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$100
295933	Veterans Building & Grounds	ST-2	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$815
295935	Veterans Building & Grounds	ST-2	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
295936	Veterans Building & Grounds	ST-2	Door	1	The push side of the accessible door does not have the required maneuvering clearances.	\$1,250
295937	Veterans Building & Grounds	ST-2	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295938	Veterans Building & Grounds	ST-2	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295939	Veterans Building & Grounds	ST-2	Door	1	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
295940	Veterans Building & Grounds	ST-2	Door	1	CA The door lacks a level landing	\$1,178

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295941	Veterans Building & Grounds	R-1	Ramp	1	The ramp running slope exceeds 1:12 (8.33%).	\$19,860
295942	Veterans Building & Grounds	R-1	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
295943	Veterans Building & Grounds	R-1	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
295944	Veterans Building & Grounds	Elevator	Protruding Object	1	Protruding objects in the 27" to 80" range above finished floor protrude more than 4" into the circulation path along the interior accessible route.	\$728
295946	Veterans Building & Grounds	Elevator	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295948	Veterans Building & Grounds	Elevator	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295950	Veterans Building & Grounds	Elevator	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295951	Veterans Building & Grounds	Elevator	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295956	Veterans Building & Grounds	Elevator	Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295957	Veterans Building & Grounds	Elevator	Door	1	The opening force required to open the accessible, hinged, non-fire door is more than 5 pounds.	\$366
295960	Veterans Building & Grounds	Main	Building Entrance - Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
295961	Veterans Building & Grounds	Main	Building Entrance - Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295963	Veterans Building & Grounds	Main	Building Entrance - Door	1	The entry door does not have 80" minimum head clearance from finish floor, excluding door closer hinged bar and door stops which can be 78" minimum.	\$0
295964	Veterans Building & Grounds	Main	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750
295965	Veterans Building & Grounds	Main	Building Entrance - Door	1	CALIFORNIA: The maneuvering clearance at the entry door is not compliant.	\$1,750

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295966	Veterans Building & Grounds	R-2	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$20,522
295967	Veterans Building & Grounds	R-2	Building Entrance - Door	1	CALIFORNIA: The power operated door is not compliant.	\$2,600
295968	Veterans Building & Grounds	R-2	Ramp	1	CALIFORNIA: The exterior ramp railings extend more than 3-1/2" into the ramp clear width.	\$86,060
295969	Veterans Building & Grounds	ST-3	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$422
295970	Veterans Building & Grounds	ST-3	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$489
295971	Veterans Building & Grounds	ST-4	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$2,934
295972	Veterans Building & Grounds	ST-4	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$282
295973	Veterans Building & Grounds	ST-4	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route is less than 48" wide.	\$1,130
295974	Veterans Building & Grounds	ST-4	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$535
295975	Veterans Building & Grounds	ST-4	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$79
295976	Veterans Building & Grounds	ST-5	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$421
295977	Veterans Building & Grounds	ST-5	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$1,232
295979	Veterans Building & Grounds	ST-6	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$3,586

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295980	Veterans Building & Grounds	ST-6	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$422
295981	Veterans Building & Grounds	ST-6	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	\$918
295982	Veterans Building & Grounds	ST-7	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$246
295983	Veterans Building & Grounds	ST-7	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$2,282
295984	Veterans Building & Grounds	ST-8	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$1,467
295986	Veterans Building & Grounds	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,072
295987	Veterans Building & Grounds	Sidewalk	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$239
295988	Veterans Building & Grounds	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,378
295989	Veterans Building & Grounds	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$3,072
295990	Veterans Building & Grounds	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$8,205
295991	Veterans Building & Grounds	Sidewalk	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$2,775
295992	Veterans Building & Grounds	Sidewalk	Exterior Accessible Route	1	Sidewalk has areas of vertical level changes in excess of 1/4" that are not ramped.	\$59
295993	Veterans Building & Grounds	P1-A	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
295994	Veterans Building & Grounds	P1-A	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295995	Veterans Building & Grounds	P1-A	Parking Space - Car	1	An access aisle is not provided.	\$420
295996	Veterans Building & Grounds	P1-B	Parking Space - Car	1	An access aisle is not provided.	\$420
295997	Veterans Building & Grounds	P1-B	Parking Space - Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
295998	Veterans Building & Grounds	P1-B	Parking Space - Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
295999	Veterans Building & Grounds	P1	Parking Space - Van	1	CALIFORNIA: A van space and adjacent van aisle are not provided.	\$840
295796	Veterans Building & Grounds	315 Exit	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
295799	Veterans Building & Grounds	315	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295800	Veterans Building & Grounds	310	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295801	Veterans Building & Grounds	320	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295802	Veterans Building & Grounds	325	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295803	Veterans Building & Grounds	330	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295815	Veterans Building & Grounds	340	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295816	Veterans Building & Grounds	355	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295817	Veterans Building & Grounds	350	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295818	Veterans Building & Grounds	360	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295819	Veterans Building & Grounds	380	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295820	Veterans Building & Grounds	390	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295821	Veterans Building & Grounds	380	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295822	Veterans Building & Grounds	380	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
295824	Veterans Building & Grounds	ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$1,304
295825	Veterans Building & Grounds	ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
295830	Veterans Building & Grounds	254	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295831	Veterans Building & Grounds	255	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295842	Veterans Building & Grounds	260	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295843	Veterans Building & Grounds	260	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295844	Veterans Building & Grounds	252	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295845	Veterans Building & Grounds	250	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295846	Veterans Building & Grounds	258	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295860	Veterans Building & Grounds	250	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295861	Veterans Building & Grounds	250	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295863	Veterans Building & Grounds	220	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295865	Veterans Building & Grounds	210	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295873	Veterans Building & Grounds	200	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295875	Veterans Building & Grounds	140	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295877	Veterans Building & Grounds	140	Restroom/Bathroom - Door	2	The swinging door does not have a smooth surface within 10" of the ground measured vertically on the push side extending the full width of the door.	\$0
295887	Veterans Building & Grounds	124	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295888	Veterans Building & Grounds	120	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295896	Veterans Building & Grounds	130	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$93
295897	Veterans Building & Grounds	130	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
295900	Veterans Building & Grounds	134	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295902	Veterans Building & Grounds	136	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295903	Veterans Building & Grounds	136	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295908	Veterans Building & Grounds	120	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$93
295912	Veterans Building & Grounds	110	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295913	Veterans Building & Grounds	105	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295914	Veterans Building & Grounds	150	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295916	Veterans Building & Grounds	160	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295917	Veterans Building & Grounds	155	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295922	Veterans Building & Grounds	160	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295923	Veterans Building & Grounds	145	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295924	Veterans Building & Grounds	170	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295925	Veterans Building & Grounds	180	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295928	Veterans Building & Grounds	180	Door	2	The surface of the swinging door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$93
295930	Veterans Building & Grounds	184	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295934	Veterans Building & Grounds	ST-2	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$163
295945	Veterans Building & Grounds	Elevator	Elevator	2	CALIFORNIA: The hall call buttons are not compliant.	\$4,500
295947	Veterans Building & Grounds	Elevator	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
295952	Veterans Building & Grounds	Elevator	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
295953	Veterans Building & Grounds	Elevator	Elevator	2	CALIFORNIA: The hall call buttons are not compliant.	\$4,500
295954	Veterans Building & Grounds	Elevator	Elevator	2	CALIFORNIA: The hall call buttons are not compliant.	\$4,500

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295955	Veterans Building & Grounds	Elevator	Door	2	The bottom of the door vision light is higher than 43" and less than 66".	\$2,600
295958	Veterans Building & Grounds	360	Signage	2	The existing signage is not mounted at the latch side of the door or at a compliant height.	\$55
295962	Veterans Building & Grounds	Main	Building Entrance - Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$1,100
295978	Veterans Building & Grounds	ST-6	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$326
295985	Veterans Building & Grounds	ST-8	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$163
295797	Veterans Building & Grounds	315 Exit	Signage	3	Means of egress signage is not provided.	\$55
295798	Veterans Building & Grounds	315	Signage	3	Means of egress signage is not provided.	\$55
295804	Veterans Building & Grounds	320	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
295805	Veterans Building & Grounds	320	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
295806	Veterans Building & Grounds	320	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
295807	Veterans Building & Grounds	320	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295808	Veterans Building & Grounds	320	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
295809	Veterans Building & Grounds	330	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
295810	Veterans Building & Grounds	330	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295811	Veterans Building & Grounds	330	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295812	Veterans Building & Grounds	330	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
295813	Veterans Building & Grounds	330	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
295832	Veterans Building & Grounds	254	Restroom/Bathroom - Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
295833	Veterans Building & Grounds	254	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
295834	Veterans Building & Grounds	254	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The centerline of the lavatory is less than 18" from the side wall or partition wall.	\$3,000
295835	Veterans Building & Grounds	254	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
295836	Veterans Building & Grounds	254	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
295837	Veterans Building & Grounds	254	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$93
295838	Veterans Building & Grounds	254	Restroom/Bathroom	3	The height of controls are not compliant.	\$500
295839	Veterans Building & Grounds	254	Restroom/Bathroom	3	The entire restroom is not compliant due to limited room dimensions.	\$12,000
295840	Veterans Building & Grounds	254	Restroom/Bathroom - Door	3	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
295841	Veterans Building & Grounds	254	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
295847	Veterans Building & Grounds	Stage	Platform Lift	3	CALIFORNIA: A platform lift is required but not provided.	\$22,525
295850	Veterans Building & Grounds	250	Signage	3	Means of egress signage is not provided.	\$55
295851	Veterans Building & Grounds	250	Signage	3	Means of egress signage is not provided.	\$55

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295852	Veterans Building & Grounds	250	Signage	3	Means of egress signage is not provided.	\$55
295862	Veterans Building & Grounds	1st Floor	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
295866	Veterans Building & Grounds	210	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
295867	Veterans Building & Grounds	210	Restroom/Bathroom - Signage	3	CALIFORNIA: The International Symbol signage at the exterior entry door is not compliant.	\$110
295869	Veterans Building & Grounds	210	Restroom/Bathroom	3	The height of controls are not compliant.	\$500
295870	Veterans Building & Grounds	210	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
295871	Veterans Building & Grounds	210	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$186
295872	Veterans Building & Grounds	210	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$400
295876	Veterans Building & Grounds	140	Restroom/Bathroom - Door	3	The force required to open the interior, hinged, non-fire door is more than 5 pounds.	\$366
295878	Veterans Building & Grounds	140	Restroom/Bathroom - Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$220
295879	Veterans Building & Grounds	140	Restroom/Bathroom - Water Closet	3	A wheelchair stall is not provided in a multi-user restroom.	\$2,750
295880	Veterans Building & Grounds	140	Restroom/Bathroom - Lavatory	3	CALIFORNIA: The lavatory does not have the required knee and toe clearance.	\$720
295881	Veterans Building & Grounds	140	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
295882	Veterans Building & Grounds	140	Restroom/Bathroom - Lavatory	3	The lavatory faucet hardware is not compliant.	\$555
295883	Veterans Building & Grounds	140	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$93

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295884	Veterans Building & Grounds	140	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
295885	Veterans Building & Grounds	140	Restroom/Bathroom - Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
295886	Veterans Building & Grounds	140	Restroom/Bathroom - Toilet Stall	3	The ambulatory stall size is not compliant, or an ambulatory stall is not provided.	\$720
295890	Veterans Building & Grounds	121	Signage	3	Means of egress signage is not provided.	\$55
295891	Veterans Building & Grounds	121	Signage	3	Means of egress signage is not provided.	\$55
295911	Veterans Building & Grounds	120	Signage	3	Means of egress signage is not provided.	\$55
295915	Veterans Building & Grounds	150	Signage	3	Means of egress signage is not provided.	\$55
295949	Veterans Building & Grounds	Elevator	Elevator	3	CALIFORNIA: The elevator car dimensions are not compliant.	\$80,000
295959	Veterans Building & Grounds	350	Signage	3	Means of egress signage is not provided.	\$55
295814	Veterans Building & Grounds	3rd Floor	Drinking Fountain/Water Cooler	4	The minimum number of drinking fountains is not provided. If the minimum number is provided, two levels or a hi-lo are not provided. If more than 2 are provided, less than 50% are high or less than 50% are low.	\$5,440
295899	Veterans Building & Grounds	Kitchen	Kitchen - Counter - Public	4	A minimum 30" wide section of the counter is not a minimum height of 28" and maximum height of 34" with knee and toe clearance.	\$2,382
294305	Washington Park & Facilities	Picnic Area	Exterior Accessible Route	1	The accessible route has areas of vertical level changes in excess of 1/4" that are not beveled or ramped.	\$179
294328	Washington Park & Facilities	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750
294329	Washington Park & Facilities	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$2,688

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294332	Washington Park & Facilities	Accessible Parking Space P1-B at Dog Park	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$9
294333	Washington Park & Facilities	Access Aisle serving P1-C	Parking Space-Car	1	CALIFORNIA: The car parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294334	Washington Park & Facilities	Accessible Parking Space P1-C at Dog Park	Parking Space-Car	1	CALIFORNIA: A car accessible stall and adjacent aisle are not provided.	\$840
294335	Washington Park & Facilities	Accessible Parking Space P1-C	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has an unstable surface.	\$100
294337	Washington Park & Facilities	Accessible Parking Space P1-A	Parking Space-Van	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
294338	Washington Park & Facilities	Access Aisle serving P1-A	Parking Space-Van	1	CALIFORNIA: The van parking aisle slope is greater than 1:48 (2.08%).	\$5,000
294340	Washington Park & Facilities	Accessible Parking Space P1-C at Dog Park	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
294341	Washington Park & Facilities	Accessible Parking Space P1-B at Dog Park	Parking Space-Car	1	CALIFORNIA: The car parking stall markings are not compliant.	\$420
294343	Washington Park & Facilities	Accessible Parking Space P1-B at Dog Park	Parking Space-Car	1	An access aisle is not provided.	\$420
294344	Washington Park & Facilities	Accessible Parking Space P1-B at Dog Park	Parking Space-Car	1	CALIFORNIA: The car stall slope is greater than 1:48 (2.08%).	\$6,300
294407	Washington Park & Facilities	Playground	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
294408	Washington Park & Facilities	Playground	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$99

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294409	Washington Park & Facilities	Playground	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$99
294410	Washington Park & Facilities	Playground	Exterior Accessible Route	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$387
294418	Washington Park & Facilities	Playground	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$119
294419	Washington Park & Facilities	Recreation Center Lawn on Central Avenue and Eighth Street	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$896
294421	Washington Park & Facilities	Playground	Exterior Accessible Route	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$563
294423	Washington Park & Facilities	Playground	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$400
294424	Washington Park & Facilities	Baseball/Softball Field near Tennis Courts	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
294319	Washington Park & Facilities	Route in the Swing-set Play Area	Exterior Accessible Route	1	CALIFORNIA: The exterior accessible route has slopes in excess of maximum 1:20 (5%) running slope and/or maximum 1:48 (2.08)% cross slope.	\$496
294324	Washington Park & Facilities	Baseball/Softball Field at Central Avenue	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$99
294368	Washington Park & Facilities	Tennis Courts	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$1,250
294369	Washington Park & Facilities	Tennis Courts	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$250
294372	Washington Park & Facilities	Boardwalk at Duck Pond	Building Entrance-Door	1	Gaps in the door threshold or entry are over .5" wide OR elongated gaps are not perpendicular to path of travel	\$1,500
294373	Washington Park & Facilities	Boardwalk at Duck Pond	Building Entrance-Door	1	Gaps in the door threshold or entry are over .5" wide OR elongated gaps are not perpendicular to path of travel	\$1,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294374	Washington Park & Facilities	Boardwalk at Duck Pond	Fishing Piers And Platforms	1	The fishing pier or platform does not have edge protection where railings, guards or handrails are provided.	\$1,630
294375	Washington Park & Facilities	Baseball/Softball Field near Tennis Courts	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$500
294379	Washington Park & Facilities	Stairs ST-1	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$8,150
294380	Washington Park & Facilities	Stairs ST-1	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$739
294381	Washington Park & Facilities	Stairs ST-1	Stairs	1	Steps do not have uniform and compliant riser heights and/or tread depths.	\$9,180
294382	Washington Park & Facilities	Stairs ST-1	Ground Surface	1	Ground surfaces are not firm, stable and slip resistant.	\$100
294383	Washington Park & Facilities	Stairs ST-2	Ground Surface	1	Ground surfaces are not firm, stable and slip resistant.	\$100
294384	Washington Park & Facilities	Stairs ST-2	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$739
294385	Washington Park & Facilities	Stairs ST-2	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$6,520
294387	Washington Park & Facilities	Stairs ST-3	Ground Surface	1	Ground surfaces are not firm, stable and slip resistant.	\$100
294388	Washington Park & Facilities	Stairs ST-3	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$4,890
294392	Washington Park & Facilities	Baseball/ Softball Field at Central Avenue	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
297020	Washington Park & Facilities	Accessible Parking Space P1-B at Dog Park	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
297216	Washington Park & Facilities	Baseball/Softball Field at Central Avenue	Stairs	1	CALIFORNIA: Handrails are not compliant or are not provided.	\$3,260
297217	Washington Park & Facilities	Stairs ST-3	Stairs	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$880
304191	Washington Park & Facilities	Baseball/Softball Field at Central Avenue	Stairs	1	Stairs have open risers.	\$16,800
304271	Washington Park & Facilities	Ramp R-1	Ramp	1	CALIFORNIA: The ramp has running slopes and/or rises in excess of 1:12.	\$250
294326	Washington Park & Facilities	Recreation Center Entry 740 on Street Side	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
297015	Washington Park & Facilities	Recreation Center Entry on Park Side of 740	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297016	Washington Park & Facilities	Recreation Center Entry on Park Side of 740	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$0
297017	Washington Park & Facilities	Recreation Center Entry 740 on Street Side	Building Entrance-Door	1	The accessible door with door closer has a sweep period of less than 5 seconds from 90 degrees to a position 12 degrees from latch.	\$366
297019	Washington Park & Facilities	Recreation Center Entry 740 on Street Side	Floor Surface	1	The edges of the carpet are not securely attached.	\$216

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294357	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom - Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
294314	Washington Park & Facilities	Recreation Center Entry 740 on Street Side	Building Entrance-Door	1	CALIFORNIA: The non-fire, hinged accessible exterior door takes more than 5#s of pressure to operate.	\$366
294336	Washington Park & Facilities	Dog Park	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$320
294411	Washington Park & Facilities	Playground	Transfer System	2	The transfer platform for connecting to elevated play elements has non-compliant dimensions.	\$23,909
294414	Washington Park & Facilities	Playground	Ground Surface - Fibar	2	The ground surface has not been inspected and maintained regularly.	\$500
294416	Washington Park & Facilities	Playground	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$1,250
294420	Washington Park & Facilities	Playground	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	\$5,000
294422	Washington Park & Facilities	Playground	Elevated Route - Accessed by Transfer System	2	The elevated route connecting elevated play components accessed by a transfer system is less than 24" wide.	\$25,000
294317	Washington Park & Facilities	Picnic Area	Dining And Work Surface	2	A minimum of 5% ADA compliant dining seating and standing spaces are not provided.	\$3,000
294320	Washington Park & Facilities	Baseball/Softball Field at Central Avenue	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	\$20,000
294321	Washington Park & Facilities	Baseball/Softball Field at Central Avenue	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$652
294325	Washington Park & Facilities	Baseball/Softball Field at Central Avenue	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294365	Washington Park & Facilities	Tennis Courts	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
294366	Washington Park & Facilities	Tennis Courts	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$160
294367	Washington Park & Facilities	Tennis Courts	Gate	2	The gate does not have a smooth surface within 10" of the ground.	\$320
294370	Washington Park & Facilities	Tennis Courts	Tennis Court	2	The gate does not have a smooth surface within 10" of the ground.	\$320
294371	Washington Park & Facilities	Tennis Courts	Tennis Court	2	The gate does not have a smooth surface within 10" of the ground.	\$320
294376	Washington Park & Facilities	Baseball/Softball Field near Tennis Courts	Player Seating	2	A wheelchair space is not provided at each team bench area at the ball field.	\$476
294378	Washington Park & Facilities	Baseball/Softball Field near Tennis Courts	Bleacher Seating	2	The required number of wheelchair spaces is not provided at the bleacher seating for the ball field.	\$1,748
297014	Washington Park & Facilities	Recreation Center Entry on Park Side of 740	Door	2	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
297018	Washington Park & Facilities	Recreation Center Entry 740 on Street Side	Door	2	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
294315	Washington Park & Facilities	Recreation Center Entry on Park Side of 740	Signage	2	Means of egress signage does not have tactile lettering.	\$55
294316	Washington Park & Facilities	Recreation Center Entry 740 on Street Side	Signage	2	Means of egress signage does not have tactile lettering.	\$55
294318	Washington Park & Facilities	Picnic Area	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$2,600

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294323	Washington Park & Facilities	Baseball/Softball Field at Central Avenue	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
294377	Washington Park & Facilities	Baseball/Softball Field near Tennis Courts	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
294393	Washington Park & Facilities	Playground	Drinking Fountain/Water Cooler	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000
297218	Washington Park & Facilities	Recreation Center Lawn with Redwoods on Central Avenue and Eighth Street	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$200
294394	Washington Park & Facilities	Women's Historic Restroom at Playground	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$100
294395	Washington Park & Facilities	Women's Historic Restroom at Playground	Controls And Dispensers	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294396	Washington Park & Facilities	Women's Historic Restroom at Playground	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$293
294397	Washington Park & Facilities	Women's Historic Restroom at Playground	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
294398	Washington Park & Facilities	Women's Historic Restroom at Playground	Protruding Object	3	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$200

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294399	Washington Park & Facilities	Women's Historic Restroom at Playground	Restroom/Bathroom - Door	3	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
294400	Washington Park & Facilities	Men's Historic Restroom at Playground	Restroom/Bathroom-Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$110
294401	Washington Park & Facilities	Men's Historic Restroom at Playground	Protruding Object	3	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$200
294402	Washington Park & Facilities	Men's Historic Restroom at Playground	Protruding Object	3	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
294403	Washington Park & Facilities	Men's Historic Restroom at Playground	Restroom/Bathroom-Door	3	The wheelchair stall door is not self closing.	\$293
294404	Washington Park & Facilities	Men's Historic Restroom at Playground	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
294405	Washington Park & Facilities	Men's Historic Restroom at Playground	Controls And Dispensers	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294406	Washington Park & Facilities	Women's Historic Restroom at Playground	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$794
294346	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom-Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$110
294347	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
294348	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	\$65

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294349	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$100
294350	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom	3	CALIFORNIA: The baby changing table is not compliant.	\$100
294351	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	\$65
294352	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom - Door	3	CALIFORNIA: The hardware at the accessible door is not compliant.	\$293
294353	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294354	Washington Park & Facilities	Men's Restroom at Tennis Courts	Controls And Dispensers	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294355	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The wheelchair stall with out-swinging door does not have the required dimensions.	\$1,100
294356	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom - Door	3	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
294358	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
294359	Washington Park & Facilities	Women's Restroom at Tennis Courts	Controls And Dispensers	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294360	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom - Door	3	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
294361	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom-Unisex	3	The slope of the floor surface is greater than 2% cross or 5% running	\$496
294362	Washington Park & Facilities	Men's Restroom at Tennis Courts	Restroom/Bathroom-Unisex	3	The slope of the floor surface is greater than 2% cross or 5% running	\$496
294363	Washington Park & Facilities	Men's Restroom at Tennis Courts	Protruding Object	3	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$200
294306	Washington Park & Facilities	Unisex Restroom at Recreation Center	Restroom/Bathroom-Lavatory	3	Pipes are not insulated.	\$65

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
294307	Washington Park & Facilities	Unisex Restroom at Recreation Center	Restroom/Bathroom - Toilet Stall	3	The hardware at the accessible door requires tight grasping, pinching or twisting of the wrist to operate	\$293
294308	Washington Park & Facilities	Unisex Restroom at Recreation Center	Restroom/Bathroom-Door	3	The hardware at the wheelchair stall door is not compliant.	\$293
294309	Washington Park & Facilities	Unisex Restroom at Recreation Center	Restroom/Bathroom-Water Closet	3	CALIFORNIA: The disposal unit at the water closet is not compliant.	\$280
294310	Washington Park & Facilities	Unisex Restroom at Recreation Center	Restroom/Bathroom-Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
294311	Washington Park & Facilities	Unisex Restroom at Recreation Center	Restroom/Bathroom-Toilet Stall	3	The rear grab bar in the wheelchair stall is not compliant.	\$355
294312	Washington Park & Facilities	Unisex Restroom at Recreation Center	Controls And Dispensers	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
294313	Washington Park & Facilities	Unisex Restroom at Recreation Center	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$100
304078	Washington Park & Facilities	Women's Restroom at Tennis Courts	Restroom/Bathroom-Signage	3	The restroom does not have compliant signage at the door with the International Symbol of Accessibility, raised characters, and Braille.	\$55
304192	Washington Park & Facilities	Men's Historic Restroom at Playground	Door	3	The pull side of the accessible door does not have the required maneuvering clearances.	\$1,250
294339	Washington Park & Facilities	Parking Lot	Parking Spaces-General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
294345	Washington Park & Facilities	Tennis Courts	Drinking Fountain/Water Cooler	4	The spout and/or water flow of the lower level drinking fountain is not compliant.	\$2,505
294389	Washington Park & Facilities	Stairs ST-3	Signage	4	Directional signage indicating the accessible path of travel is not provided, where existing path of travels are both accessible and non-accessible.	\$560
294390	Washington Park & Facilities	Stairs ST-2	Signage	4	Directional signage indicating the accessible path of travel is not provided, where existing path of travels are both accessible and non-accessible.	\$560
294391	Washington Park & Facilities	Stairs ST-1	Signage	4	Directional signage indicating the accessible path of travel is not provided, where existing path of travels are both accessible and non-accessible.	\$560

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300674	West End Library & Grounds	Accessible Parking Space P1-A	Parking Space-Car	1	CALIFORNIA: Signage is not provided at the standard accessible space, or the existing signage is not compliant.	\$280
300675	West End Library & Grounds	Ramp R-1	Ramp	1	CALIFORNIA: The ramp landings are not compliant.	\$3,310
317158	West End Library & Grounds	Main Entrance Door	Door	1	CALIFORNIA: The power operated door is not compliant.	\$5,200
300672	West End Library & Grounds	Sidewalk	Building Entrance-Door	2	CALIFORNIA: The non-accessible entrance does not have signage indicating the location of the nearest accessible entrance, in the existing building where not all entrances are accessible.	\$55
300663	West End Library & Grounds	Reading Room	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$1,000
300664	West End Library & Grounds	Reading Room	Interior Access Route	2	CALIFORNIA: The width of the aisle is not compliant.	\$500
300665	West End Library & Grounds	Reading Room	Interior Access Route	2	CALIFORNIA: The width of the aisle is not compliant.	\$500
300666	West End Library & Grounds	Reading Room	Dining And Work Surface	2	CALIFORNIA: The dining or work surface is not compliant.	\$1,000
300668	West End Library & Grounds	Reading Room	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
300651	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom - Door	3	The accessible restroom entry door does not have compliant maneuvering clearances.	\$100
300652	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
300653	West End Library & Grounds	Reading Room	Dining And Work Surface	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$5,439
300654	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
300655	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom	3	The space between the grab bar and projecting objects above the grab bar is less than 12" minimum.	\$100

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
300656	West End Library & Grounds	Unisex Restroom 1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
300657	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
300658	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
300659	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom - Water Closet	3	CALIFORNIA: The centerline of the toilet in the wheelchair stall or single-user restroom is not 17" minimum to 18" maximum from the sidewall.	\$1,368
300660	West End Library & Grounds	Unisex Restroom 1	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$93
300661	West End Library & Grounds	Unisex Restroom 1	Restroom/Bathroom - Door	3	The push side of the accessible door does not have the required maneuvering clearances.	\$400
300676	West End Library & Grounds	Unisex Restroom 2	Restroom/Bathroom - Signage	3	CALIFORNIA: The unisex restroom does not have compliant signage at the door.	\$110
300677	West End Library & Grounds	Unisex Restroom 2	Restroom/Bathroom-Water Closet	3	The rear grab bar at the water closet is not compliant.	\$355
300678	West End Library & Grounds	Unisex Restroom 2	Restroom/Bathroom - Lavatory	3	Pipes are not insulated.	\$65
300679	West End Library & Grounds	Unisex Restroom 2	Restroom/Bathroom - Coat Hook	3	The coat hook is not within an allowable reach range.	\$115
300680	West End Library & Grounds	Unisex Restroom 2	Restroom/Bathroom-Water Closet	3	The toilet paper dispenser is not at a compliant location.	\$280
300681	West End Library & Grounds	Unisex Restroom 2	Restroom/Bathroom - Water Closet	3	The flush control is located on the closed side and/or is not within reach range.	\$313
300669	West End Library & Grounds	Reading Room Exit to 788 Santa Clara Avenue	Exterior Accessible Route-Signage	4	Signage with tactile lettering does not have 18" minimum by 18" minimum clear space centered on the tactile characters and/or beyond the arc swing of a door between the closed position and 45 degrees open.	\$280
295404	Woodstock Park & Facilities	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: The van parking stall slope is greater than 1:48 (2.08%).	\$6,300

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
293872	Woodstock Park & Facilities	Curb Ramp CR-1	Exterior Accessible Route	1	ADVISORY: A marked crosswalk is not provided where the accessible route crosses a vehicular way between the accessible parking aisle and the building entrance.	\$0
293873	Woodstock Park & Facilities	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: The van parking aisle for perpendicular and angled parking is not on the passenger side.	\$420
293874	Woodstock Park & Facilities	Accessible Parking Space P-1A	Parking Space-Van	1	CALIFORNIA: The van parking aisle is less than 96" wide, where the van stall is less than 144" wide.	\$420
293875	Woodstock Park & Facilities	Playground PG-1	Elevated Route	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$387
293877	Woodstock Park & Facilities	Accessible Parking Space P-1A	Parking Space - General	1	CALIFORNIA: Signage is not provided at the van accessible space, or the existing signage is not compliant.	\$280
293879	Woodstock Park & Facilities	Walkway from P-1A	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$79
293908	Woodstock Park & Facilities	Walkway from Restrooms to Picnic Area at PG-1	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$79
293909	Woodstock Park & Facilities	Walkway from PG-1 to Picnic Tables	Exterior Accessible Route	1	In areas along the route there are level changes of 1/2" or greater that are not ramped.	\$79
293911	Woodstock Park & Facilities	Stairs ST-1	Elevated Route	1	CALIFORNIA: The top of the stair flight and all stair treads do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$70
293913	Woodstock Park & Facilities	Walking Path	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
293914	Woodstock Park & Facilities	Walking Path	Exterior Accessible Route	1	The accessible route has gaps in the surface greater than 1/2" wide.	\$496
293915	Woodstock Park & Facilities	Playground PG-2	Elevated Route	1	CALIFORNIA: The transfer steps do not have a stripe which provides visual contrast of dark-on-light or light-on-dark distinguished from the remainder of the surface.	\$317
293917	Woodstock Park & Facilities	Playground PG-2	Curb Ramp	1	CALIFORNIA: The curb ramp has non-compliant slopes.	\$1,750

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
303817	Woodstock Park & Facilities	Walkway from to Picnic Area at PG-1 and PG-2	Exterior Accessible Route	1	A compliant accessible route is not provided from the public access to the amenity.	\$1,344
303818	Woodstock Park & Facilities	Curb Ramp CR-1	Curb Ramp	1	CALIFORNIA: The curb ramp run does not have a compliant detectable warning.	\$672
295401	Woodstock Park & Facilities	Classroom	Floor Surface	1	The carpet in the common area has an unstable pad or backing.	\$1,200
293904	Woodstock Park & Facilities	Door to Restroom Facility	Building Entrance-Door	1	CALIFORNIA: The hardware at the accessible door is not compliant.	\$676
293906	Woodstock Park & Facilities	Playground PG-1	Play Component - Swing	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	\$250
293910	Woodstock Park & Facilities	Playground PG-1	Transfer System	2	The transfer platform connecting to elevated play elements has a non-compliant height lower than 11" or higher than 18".	\$10,000
303819	Woodstock Park & Facilities	Stairs ST-1	Stairs	2	CALIFORNIA: The stair handrail extensions are not compliant.	\$978
303929	Woodstock Park & Facilities	Playground PG-2	Ground Surface-Fibar	2	The ground surface has not been inspected and maintained regularly.	\$450
295402	Woodstock Park & Facilities	Classroom	Building Entrance-Door	2	The surface of the door within 10 inches of the finish floor or ground for the full width of the door on the push side is not smooth.	\$400
293890	Woodstock Park & Facilities	Men's Restroom	Controls And Dispensers	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$100
293891	Woodstock Park & Facilities	Women's Restroom	Controls And Dispensers	2	The restroom circulation path is not free of objects protruding more than 4" from wall in the space between 27" and 80" height above finish floor.	\$100
293919	Woodstock Park & Facilities	Classroom	Signage	2	Tactile means of egress signage is not provided at the latch side of the door. (Applies to designated egress stairways, exit doors, areas of refuge)	\$55
293907	Woodstock Park & Facilities	Picnic Area at Playground PG-1 and PG-2	Picnic Table	3	CALIFORNIA: A compliant picnic table is not provided.	\$2,600
293912	Woodstock Park & Facilities	Drinking Fountain DF-1	Controls And Dispensers	3	CALIFORNIA: The minimum number of drinking fountains is not provided.	\$8,000

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
295403	Woodstock Park & Facilities	Door at Restroom Facility	Door	3	CALIFORNIA: The surface of the swinging door within 10" of the finish floor or ground for the full width of the door on the push side is not smooth.	\$200
293876	Woodstock Park & Facilities	Men's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
293881	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
293882	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom-Urinal	3	The urinal dimensions are not compliant.	\$935
293883	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
293884	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom - Toilet Stall	3	The hardware at the wheelchair stall door is not compliant.	\$586
293885	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom - Toilet Stall	3	The hardware at the wheelchair stall door is not compliant.	\$293
293886	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom	3	The side grab bar at the water closet is not compliant.	\$355
293887	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom	3	The rear grab bar at the water closet is not compliant.	\$355
293888	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom	3	The flush control is located on the closed side and/or is not within reach range.	\$313
293889	Woodstock Park & Facilities	Men's Restroom	Restroom/Bathroom	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
293892	Woodstock Park & Facilities	Women's Restroom	Restroom/Bathroom - Mirror	3	The mirror is mounted higher than 40" above finish floor to the bottom of the reflective surface, where it is installed above a lavatory or counter.	\$200
293893	Woodstock Park & Facilities	Men's Restroom	Controls And Dispensers	3	CALIFORNIA: The location of electrical controls are not compliant.	\$500
293894	Woodstock Park & Facilities	Women's Restroom	Controls And Dispensers	3	CALIFORNIA: The location of electrical controls are not compliant.	\$500
293895	Woodstock Park & Facilities	Men's Restroom	Signage	3	CALIFORNIA: The men's restroom does not have compliant signage at the door.	\$220

## Appendix H

### Summary Facility Barriers

Id	Facility	Location Description	Category	Barrier Priority	Detail	Estimate
293896	Woodstock Park & Facilities	Women's Restroom	Signage	3	CALIFORNIA: The women's restroom does not have compliant signage at the door.	\$220
293897	Woodstock Park & Facilities	Women's Restroom	Controls And Dispensers	3	CALIFORNIA: Dispensers in restrooms are not located maximum 40" AFF.	\$200
293898	Woodstock Park & Facilities	Women's Restroom	Restroom/Bathroom - Door	3	The wheelchair stall door is not self closing.	\$293
293899	Woodstock Park & Facilities	Women's Restroom	Restroom/Bathroom - Toilet Stall	3	The hardware at the wheelchair stall door is not compliant.	\$293
293900	Woodstock Park & Facilities	Women's Restroom	Restroom/Bathroom	3	The side grab bar at the water closet is not compliant.	\$355
293901	Woodstock Park & Facilities	Women's Restroom	Restroom/Bathroom	3	The rear grab bar at the water closet is not compliant.	\$355
293902	Woodstock Park & Facilities	Women's Restroom	Restroom/Bathroom	3	The flush control is located on the closed side and/or is not within reach range.	\$313
293903	Woodstock Park & Facilities	Women's Restroom	Restroom/Bathroom	3	CALIFORNIA: The toilet paper dispenser is not compliant.	\$280
293878	Woodstock Park & Facilities	Parking Lot P1	Parking Space - General	4	CALIFORNIA: The parking facility does not have facility entrance/ accessible parking signage indicating that accessible parking violators will be towed, or the existing signage is not compliant.	\$280
295400	Woodstock Park & Facilities	Classroom	Exterior Accessible Route-Signage	4	Signage identifying the name of a permanent indoor or outdoor space does not have raised lettering and/or visual characters.	\$280